



Status Report

HAWKER 800XP

S/N 258545 N312FU

OWNER: N312FU LLC  
ADDRESS: 6111 BROKEN SOUNDS PKWY  
SUITE 330 BOCA RATON,  
BOCA RATON FL 33487  
OFFICE:  
FAX:

OPERATOR: SKYWAYS CHARTER LLC  
ADDRESS: 3700 AIRPORT RD  
BOCA RATON FL 33431  
OFFICE: 561-237-5607  
FAX: 561-208-5514

ANALYST: CHRISTOPHER CUTLER  
EMAIL: CCUTLER@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)  
316-462-2442 (FAX)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO  
RECORD CHANGES TO ADDRESS, LAST ACTUALS  
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;PN/SN-UNKNOWN Components:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE

AIRCRAFT	SERIAL/REGNO: 258545/N312FU	MODEL: HAWKER 800XP	MANUFACTURER: TEXTRON AVIATION INC.
	CERTIFICATION DATE: 19-JUL-2001	LAST ACTUALS: 12087.2 A/C HRS as of 12-SEP-2022 7613 AFL as of 12-SEP-2022 10558 APH as of 04-SEP-2022	
APU	SERIAL/PART: P-545/3800304-1	MODEL: GTCP36-150(W)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 30-JAN-2005 3395 APU HRS 2836.4 A/C HRS 0 APUS	LAST ACTUALS: 10558 APU HRS as of 04-SEP-2022 7463 APUS as of 04-SEP-2022	
ENGINE NO. 1	SERIAL/PART: P-107407/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
	INSTALLED ON: 23-MAR-2008 5476.8 ENG. HRS 5399.6 A/C HRS 3861 ENC	LAST ACTUALS: 11827.1 ENG. HRS as of 12-SEP-2022 7675 ENC as of 12-SEP-2022	
ENGINE NO. 2	SERIAL/PART: P-107404/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
	INSTALLED ON: 23-MAR-2008 6279 ENG. HRS 5399.6 A/C HRS 4450 ENC	LAST ACTUALS: 12511.6 ENG. HRS as of 12-SEP-2022 8191 ENC as of 12-SEP-2022	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 00 - INFORMATION</b>									
000000 <sup>U</sup>		GENERAL DOCUMENTS						Component	ATA:00
PN:PN	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0	TSN 0						
	AFL	0	TSN 0						
000005 <sup>U</sup>		BRIGHTWORK POLISH						Service	ATA:00
	MOS/MSC	10-Mar-17	A/R						
	HRS	10537							
	AFL	6713							
000010 <sup>U</sup>		AIRCRAFT PAINT						Service	ATA:00
	MOS/MSC	14-May-15	-						
	HRS	9204.9							
	AFL	5944							
000015 <sup>U</sup>		AIRCRAFT INTERIOR						Service	ATA:00
	MOS/MSC	19-Jul-01	-						
	HRS	0							
	AFL	0							
00200 <sup>U</sup>		REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MONITORING REQUIREMENTS						Service	ATA:00
	MOS/MSC	29-Mar-16	A/R						
	HRS	10084.4							
	AFL	6445							
00500 <sup>U</sup>		CHECK AFM FOR CURRENT REVISION STATUS						Service	ATA:00
	MOS/MSC	28-Oct-16	A/R						
	HRS	10335.8							
	AFL	6609							
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050000 <sup>U</sup>		SERVICE CHECK						Service	ATA:05
	MOS/MSC	08-Sep-22	A/R						
	HRS	12086.5							
	AFL	7611							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050001	<b>INSPECTION PRE-FLIGHT</b>							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.T01	AFL	0							
					REF: AFMS 05-00-00				
050005	<b>INSPECTION POST FLIGHT</b>							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.T02	AFL	0							
					REF: AFMS 05-00-00				
050110	<b>INSPECTION B1-B12 COMPLETE</b>							Package	ATA:05
	MOS	03-May-21							
	HRS	11562.2	800 (+40/-10)		12362.2	12402.2	275 (+40)		
	AFL	7300							
								PKG:91	
050141 <sup>S</sup>	<b>INSPECT AREA F1-800 HOURS</b>							Service	ATA:05
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 05.203	AFL	7300							
					REF: AFMS INTRODUCTION, AFMS INSPECTION B3			PKG:9,91	
050171 <sup>S</sup>	<b>INSPECT AREA F3 ABOVE FLOOR-800 HOURS</b>							Service	ATA:05
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 05.206	AFL	7300							
					REF: AFMS INTRODUCTION, AFMS INSPECTION B6			PKG:12,91	
050181 <sup>S</sup>	<b>INSPECT AREA F4-800 HOURS</b>							Service	ATA:05
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 05.207	AFL	7300							
					REF: AFMS INTRODUCTION, AFMS INSPECTION B7			PKG:13,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>								
050191 <sup>S</sup>	INSPECT AREA T1-800 HOURS							Service ATA:05
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 05.208	AFL	7300						
				REF: AFMS INTRODUCTION, AFMS INSPECTION B8				PKG:14,91
050201 <sup>S</sup>	INSPECT AREA W1-800 HOURS							Service ATA:05
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 05.209	AFL	7300						
				REF: AFMS INTRODUCTION, AFMS INSPECTION B9				PKG:15,91
050211 <sup>S</sup>	INSPECT AREA W2-800 HOURS							Service ATA:05
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 05.210	AFL	7300						
				REF: AFMS INTRODUCTION, AFMS INSPECTION B10				PKG:16,91
050221 <sup>S</sup>	INSPECT AREA M1/M2-800 HOURS							Service ATA:05
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 05.211	AFL	7300						
				REF: AFMS INTRODUCTION, AFMS INSPECTION B11				PKG:17,91
050231 <sup>S</sup>	INSPECT AREA G-800 HOURS							Service ATA:05
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 05.212	AFL	7300						
				REF: AFMS INTRODUCTION, AFMS INSPECTION B12				PKG:18,91
050240	INSPECTION C1-C12 COMPLETE							Package ATA:05
	MOS	19-Feb-18						
	HRS	10726	1600 (+50/-50)		12326	12376	238.8 (+50)	
	AFL	6832						
								PKG:92



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050271 <sup>S</sup>	INSPECT AREA F1-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.303	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C3			PKG:21,92	
050281 <sup>S</sup>	INSPECT AREA F2-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.304	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C4			PKG:22,92	
050291 <sup>S</sup>	INSPECT AREA F3 UNDERFLOOR-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.305	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C5			PKG:23,92	
050301 <sup>S</sup>	INSPECT AREA F3- ABOVE FLOOR-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.306	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C6			PKG:24,92	
050311 <sup>S</sup>	INSPECT AREA F4-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.307	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C7			PKG:25,92	
050321 <sup>S</sup>	INSPECT AREA T1-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.308	AFL	6832							
					REF: AFMS INSPECTION C8			PKG:26,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050331 <sup>S</sup>	INSPECT AREA W1-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.309	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C9			PKG:27,92	
050341 <sup>S</sup>	INSPECT AREA W2-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.310	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C10			PKG:28,92	
050351 <sup>S</sup>	INSPECT AREA M1/M2-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.311	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C11			PKG:29,92	
050361 <sup>S</sup>	INSPECT AREA G-1600 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 05.312	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION C12			PKG:30,92	
050370	INSPECTION D1-D12 COMPLETE							Package	ATA:05
	MOS	19-Feb-18							
	HRS	10726	3200 (+150/-50)		13926	14076	1838.8 (+150)		
	AFL	6832							
								PKG:93	
050411 <sup>S</sup>	INSPECT AREA F2-3200 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 05.404	AFL	6832							
					REF: AFMS INTRODUCTION, AFMS INSPECTION D4			PKG:34,93	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050431 <sup>S</sup>	INSPECT AREA F3 ABOVE FLOOR-3200 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 05.406	AFL	6832							
				REF: AFMS INTRODUCTION, AFMS INSPECTION D6				PKG:36,93	
050441 <sup>S</sup>	INSPECT AREA F4-3200 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 05.407	AFL	6832							
				REF: AFMS INTRODUCTION, AFMS INSPECTION D7				PKG:37,93	
050491 <sup>S</sup>	INSPECT AREA G-3200 HOURS							Service	ATA:05
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 05.412	AFL	6832							
				REF: AFMS INTRODUCTION, AFMS INSPECTION D12				PKG:42,93	
050500	INSPECTION E1-E12 COMPLETE							Package	ATA:05
	MOS	13-Mar-22	12 (+1m/-1m)		13-Mar-23	13-Apr-23	181 d (+31)		
	HRS	11930.2							
	AFL	7513							
								PKG:94	
050571 <sup>S</sup>	INSPECT AREA F4-12 MONTHS							Service	ATA:05
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 05.506	AFL	7513							
				REF: AFMS INTRODUCTION, AFMS INSPECTION E7				PKG:49,94	
050630	INSPECTION F1-F12 COMPLETE							Package	ATA:05
	MOS	17-Jun-22	24 (+2m/-2m)		17-Jun-24	17-Aug-24	643 d (+61)		
	HRS	12023.9							
	AFL	7567							
								PKG:95	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
050661 <sup>S</sup>	INSPECT AREA F1-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.603	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F3			PKG:57,95	
050671 <sup>S</sup>	INSPECT AREA F2-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.604	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F4			PKG:58,95	
050691 <sup>S</sup>	INSPECT AREA F3-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.606	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F6			PKG:60,95	
050701 <sup>S</sup>	INSPECT AREA F4-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.607	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F7			PKG:61,95	
050721 <sup>S</sup>	INSPECT AREA W1-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.609	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F9			PKG:63,95	
050731 <sup>S</sup>	INSPECT AREA W2-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.610	AFL	7567							
					REF: AFMS INTRODUCTION, AFMS INSPECTION F10			PKG:64,95	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
050751 <sup>S</sup>	INSPECT AREA G-24 MONTHS							Service	ATA:05
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.612	AFL	7567							
				REF: AFMS INTRODUCTION, AFMS INSPECTION F12				PKG:66,95	
050760	INSPECTION G COMPLETE							Package	ATA:05
	MOS	17-Jun-22	48 (+2m/-2m)		17-Jun-26	17-Aug-26	1373 d (+61)		
	HRS	12023.9							
	AFL	7567						PKG:96	
050761 <sup>S</sup>	INSPECT AREA F1-48 MONTHS							Service	ATA:05
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.703	AFL	7567							
				REF: AFMS INTRODUCTION, AFMS INSPECTION G				PKG:96	
050762 <sup>S</sup>	INSPECT AREA F2-48 MONTHS							Service	ATA:05
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.704	AFL	7567							
				REF: AFMS INTRODUCTION, AFMS INSPECTION G				PKG:96	
050763 <sup>S</sup>	INSPECT AREA F3-48 MONTHS							Service	ATA:05
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.705	AFL	7567							
				REF: AFMS INTRODUCTION, AFMS INSPECTION G				PKG:96	
050764 <sup>S</sup>	INSPECT AREA F4-48 MONTHS							Service	ATA:05
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 05.707	AFL	7567							
				REF: AFMS INTRODUCTION, AFMS INSPECTION G				PKG:96	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>								
<b>050765<sup>S</sup> INSPECT AREA T1-48 MONTHS Service ATA:05</b>								
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)					
	HRS	12023.9						
WC#: 05.708	AFL	7567						
REF: AFMS INTRODUCTION, AFMS INSPECTION G								PKG:96
<b>050766<sup>S</sup> INSPECT AREA W1/W2-48 MONTHS Service ATA:05</b>								
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)					
	HRS	12023.9						
WC#: 05.709	AFL	7567						
REF: AFMS INTRODUCTION, AFMS INSPECTION G								PKG:96
<b>050771 INSPECTION 400 HOUR DETAILED WALK-AROUND Service ATA:05</b>								
	MOS	02-Apr-22						
	HRS	11960.2	400 (+40/-10)	Adj 2	12362.2	12402.2	275 (+40)	
WC#: 05.100	AFL	7530						
REF: AFMS 400 HR DETAILED WALK-AROUND								
<b>055005 ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING Service ATA:05</b>								
	MOS/MSC	19-Jul-01	A/R					
	HRS	0						
WC#: 05.710	AFL	0						
REF: AFMS HEAVY LANDING INSPECTION								
<b>055010 ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE Service ATA:05</b>								
	MOS/MSC	19-Jul-01	A/R					
	HRS	0						
WC#: 05.711	AFL	0						
REF: AFMS TURBULENCE								
<b>055015 ACCOMPLISH INSPECTIONS AFTER A LIGHTNING STRIKE Service ATA:05</b>								
	MOS/MSC	15-Mar-22	A/R					
	HRS	11930.5						
WC#: 05.712	AFL	7514						
REF: AFMS LIGHTNING STRIKE INSPECTION								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
055035	ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.713	AFL	0							
055040	ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.714	AFL	0							
								REF: AFMS REVERSE THRUST INSPECTION	
055045	ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION							Service	ATA:05
	MOS/MSC	05-Feb-05	A/R						
	HRS	2858.4							
WC#: 05.715	AFL	1981							
								REF: AFMS VIBRATION INSP.	
055050	ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.716	AFL	0							
								REF: AFMS SLUSHY RUNWAY INSPECTION	
055060	ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP							Service	ATA:05
	MOS/MSC	22-Dec-08	A/R						
	HRS	5746.2							
WC#: 05.717	AFL	3873							
								REF: AFMS EMERGENCY STOP INSPECTION	
055065	ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.718	AFL	0							
								REF: AFMS ABNORMAL APU INSPECTION	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
055070	<b>ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED</b>							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.719	AFL	0							
			REF: AFMS FLAP OVERSPEED						
055075	<b>ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH</b>							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
WC#: 05.720	AFL	0							
			REF: AFMS VOLCANIC ASH						
055080	<b>ACCOMPLISH INSPECTIONS FOR HYDRAULIC CONTAMINATION OF THE CABIN VENTILATION SYSTEM</b>							Service	ATA:05
	MOS/MSC	19-Jul-01	A/R						
	HRS	0							
	AFL	0							
057110	<b>NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION</b>							Package	ATA:05
	MOS	27-Jun-22							
	HRS	11763.8	150 (+100)		(11913.8) 12173.9	12013.8	86.7 (+100)		
	ENC	7629							
			REF: LMM 72-00-00						PKG:1
057110	<b>NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION</b>							Package	ATA:05
	MOS	22-Jul-22							
	HRS	12461.4	150 (+100)		(12611.4) 12187	12711.4	99.8 (+100)		
	ENC	8155							
			REF: LMM 72-00-00						PKG:1
057120	<b>NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION</b>							Package	ATA:05
	MOS	27-May-22							
	HRS	11763.8	300 (+100)		(12063.8) 12323.9	12163.8	236.7 (+100)		
	ENC	7629							
			REF: LMM 72-00-00						PKG:2



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>								
057120	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION							Package ATA:05
	MOS	30-Jun-22						
	HRS	12448.3	300 (+100)		(12748.3) 12323.9	12848.3	236.7 (+100)	
	ENC	8155						
				REF: LMM 72-00-00				PKG:2
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	27-Jun-22						
	HRS	11763.8	600 (+250)		(12363.8) 12623.9	12613.8	536.7 (+250)	
	ENC	7629						
				REF: LMM 72-00-00, LMM 72-00-00				PKG:3
057140	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION							Package ATA:05
	MOS	24-May-22						
	HRS	12448.3	600 (+250)		(13048.3) 12623.9	13298.3	536.7 (+250)	
	ENC	8145						
				REF: LMM 72-00-00, LMM 72-00-00				PKG:3
057160	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	21-Jun-22						
	HRS	11763.8	1000 (+400)		(12763.8) 13023.9	13163.8	936.7 (+400)	
	ENC	7629						
				REF: LMM 72-00-00, LMM 72-00-00				PKG:4
057160	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION							Package ATA:05
	MOS	27-Jun-22						
	HRS	12448.3	1000 (+400)		(13448.3) 13023.9	13848.3	936.7 (+400)	
	ENC	8145						
				REF: LMM 72-00-00, LMM 72-00-00				PKG:4



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package	ATA:05
	MOS	17-Jun-20							
	HRS	10842.9	1200 (+450)		(12042.9) 12303	12492.9	215.8 (+450)		
	ENC	7132							
				REF: LMM 72-00-00, LMM 72-00-00				PKG:5	
057170	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package	ATA:05
	MOS	03-Dec-20							
	HRS	12041.2	1200 (+450)		(13241.2) 12816.8	13691.2	729.6 (+450)		
	ENC	7917							
				REF: LMM 72-00-00, LMM 72-00-00				PKG:5	
<b>ATA 08 - LEVELING AND WEIGHING</b>									
080005 <sup>U</sup>	WEIGH AIRCRAFT AND UPDATE FLIGHT MANUAL WEIGHT AND BALANCE INFORMATION							Service	ATA:08
	MOS	25-Feb-21	36		29-Feb-24		534 d		
	HRS	11418.4							
	AFL	7225							
<b>ATA 12 - SERVICING</b>									
120001	LUBRICATE AREA G-200 HOURS							Service	ATA:12
	MOS	21-Jun-22							
	HRS	12023.9	200 (+40/-10)		12223.9	12263.9	136.7 (+40)		
WC#: 12.001	AFL	7567							
				REF: AFMS LUBRICATION, AFMS LUBRICATION					
120003	LUBRICATE AREA F1-400 HOURS							Service	ATA:12
	MOS	03-Apr-22							
	HRS	11960.2	400 (+40/-10)	Adj 2	12362.2	12402.2	275 (+40)		
WC#: 12.003	AFL	7530							
				REF: AFMS LUBRICATION					
120004	LUBRICATE AREA T1-400 HOURS							Service	ATA:12
	MOS	02-Apr-22							
	HRS	11960.2	400 (+40/-10)	Adj 2	12362.2	12402.2	275 (+40)		
WC#: 12.004	AFL	7530							
				REF: AFMS LUBRICATION, AFMS LUBRICATION					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 12 - SERVICING									
120007	LUBRICATE AREA W1/W2-400 HOURS							Service	ATA:12
	MOS	03-Apr-22							
	HRS	11960.2	400 (+40/-10)	Adj 2	12362.2	12402.2	275 (+40)		
WC#: 12.007	AFL	7530							
REF: AFMS LUBRICATION, AFMS LUBRICATION									
120012 <sup>S</sup>	LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS							Service	ATA:12
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 12.012	AFL	7300							
REF: AFMS LUBRICATION									
120013 <sup>S</sup>	LUBRICATE AREA F4-800 HOURS							Service	ATA:12
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 12.009	AFL	7300							
REF: AFMS LUBRICATION									
120015 <sup>S</sup>	LUBRICATE AREA W1-800 HOURS							Service	ATA:12
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 12.015	AFL	7300							
REF: AFMS LUBRICATION, AFMS LUBRICATION									
120016 <sup>S</sup>	LUBRICATE AREA W2-800 HOURS							Service	ATA:12
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 12.016	AFL	7300							
REF: AFMS LUBRICATION, AFMS LUBRICATION									
120018 <sup>S</sup>	LUBRICATE AREA G-800 HOURS							Service	ATA:12
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 12.018	AFL	7300							
REF: AFMS LUBRICATION, AFMS LUBRICATION									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 12 - SERVICING</b>									
120019 <sup>S</sup>	LUBRICATE AREA F1-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.013	AFL	6914							
				REF: AFMS LUBRICATION				PKG:21,92	
120020 <sup>S</sup>	LUBRICATE AREA F2-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.020	AFL	6914							
				REF: AFMS LUBRICATION				PKG:22,92	
120021 <sup>S</sup>	LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.021	AFL	6914							
				REF: AFMS LUBRICATION				PKG:23,92	
120022 <sup>S</sup>	LUBRICATE AREA F3-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.022	AFL	6914							
				REF: AFMS LUBRICATION				PKG:24,92	
120023 <sup>S</sup>	LUBRICATE AREA F4-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.023	AFL	6914							
				REF: AFMS LUBRICATION				PKG:25,92	
120024 <sup>S</sup>	LUBRICATE AREA T1-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.024	AFL	6914							
				REF: AFMS LUBRICATION				PKG:26,92	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 12 - SERVICING									
120025 <sup>S</sup>	LUBRICATE AREA W1-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.025	AFL	6914							
				REF: AFMS LUBRICATION				PKG:27,92	
120026 <sup>S</sup>	LUBRICATE AREA W2-1600 HOURS							Service	ATA:12
	MOS	02-Apr-20							
	HRS	10840	1600 <sup>S</sup> (+50/-50)						
WC#: 12.026	AFL	6914							
				REF: AFMS LUBRICATION				PKG:28,92	
120030 <sup>S</sup>	LUBRICATE AREA F2-3200 HOURS							Service	ATA:12
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 12.030	AFL	6832							
				REF: AFMS LUBRICATION				PKG:34,93	
120049 <sup>S</sup>	LUBRICATE AREA F1-24 MONTHS							Service	ATA:12
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 12.049	AFL	7567							
				REF: AFMS LUBRICATION				PKG:57,95	
120050 <sup>S</sup>	LUBRICATE AREA F2-24 MONTHS							Service	ATA:12
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 12.050	AFL	7567							
				REF: AFMS LUBRICATION				PKG:58,95	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 20 - STANDARD PRACTICES - AIRFRAME</b>									
200001 <sup>S</sup>	<b>BONDING CHECK CONTROL SURFACES</b>							Service	ATA:20
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 20.010	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
200002 <sup>S</sup>	<b>FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF)</b>							Service	ATA:20
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 20.020	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
200003 <sup>S</sup>	<b>CHECK RADIO RACKING, ELECTRICAL-BONDING</b>							Service	ATA:20
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 20.030	AFL	7567							
				REF: AFMS INSPECTION G				PKG:96	
<b>ATA 21 - AIR CONDITIONING</b>									
210002	<b>CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE</b>							Service	ATA:21
	MOS	03-May-21							
	HRS	11562.2	800 (+40/-10)		12362.2	12402.2	275 (+40)		
WC#: 21.075	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
210003 <sup>S</sup>	<b>BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM</b>							Service	ATA:21
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 21.110	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
210004 <sup>S</sup>	<b>CHECK MANUAL CABIN ALTITUDE CONTROL VALVE</b>							Service	ATA:21
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 21.270	AFL	7300							
				REF: AFMS INSPECTION B4				PKG:10,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
210005 <sup>S</sup>	CHECK COOLING TURBINE EXHAUST DUCT DRAIN							Service	ATA:21
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 21.260	AFL	7300							
				REF: AFMS INSPECTION B7				PKG:13,91	
210006	INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION							Service	ATA:21
	MOS	03-Apr-22							
	HRS	11960.2	400 (+10%)		12360.2	12400.2	273 (+40)		
WC#: 21.221	AFL	7530							
				REF: AFMS OUT OF PHASE INSPECTIONS					
210007	INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS							Service	ATA:21
	MOS	02-Apr-22							
	HRS	11960.2	400 (+10%)		12360.2	12400.2	273 (+40)		
WC#: 21.280	AFL	7530							
				REF: AFMS OUT OF PHASE INSPECTIONS					
210008 <sup>S</sup>	VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.118	AFL	6832							
				REF: AFMS INSPECTION C4				PKG:22,92	
210009 <sup>S</sup>	CHECK PRESSURIZATION CONTROL VENTURI SCREEN							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.275	AFL	6832							
				REF: AFMS INSPECTION C6				PKG:24,92	
210010 <sup>S</sup>	CLEAN PRESSURE REGULATOR FILTER SCREENS							Service	ATA:21
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 21.155	AFL	7567							
				REF: AFMS INSPECTION G				PKG:96	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
210011 <sup>S</sup>	CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES							Service	ATA:21
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 21.120	AFL	7567							
				REF: AFMS INSPECTION G				PKG:96	
210012 <sup>S</sup>	INSPECT AIR CONDITIONING DUCTS							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.250	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
210013 <sup>S</sup>	INSPECT RAM AIR DUCT							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.255	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
210014 <sup>S</sup>	INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM)							Service	ATA:21
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 21.310	AFL	7567							
				REF: AFMS INSPECTION G				PKG:96	
210015 <sup>S</sup>	INSPECT SILENCER DUCT/SOUNDPROOFING							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 21.015	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	
210016 <sup>S</sup>	BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 21.195	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
210018 <sup>S</sup>	FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING							Service	ATA:21
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 21.135	AFL	7567							
				REF: AFMS INSPECTION G				PKG:96	
210019 <sup>S</sup>	INSPECT CABIN SUPPLY NON-RETURN VALVE							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 21.065	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	
210020 <sup>S</sup>	FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.180	AFL	6832							
				REF: AFMS INSPECTION C1				PKG:19,92	
210021 <sup>S</sup>	INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 21.030	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	
210022	CHECK TORQUE AIR CONDITIONING DUCTS							Service	ATA:21
	MOS/MSC	03-May-21	O/C						
	HRS	11562.2							
WC#: 21.010	AFL	7300							
				REF: AFMS OUT OF PHASE INSPECTIONS					
210024 <sup>S</sup>	CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER							Service	ATA:21
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 21.290	AFL	7300							
				REF: AFMS INSPECTION B7				PKG:13,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
210025 <sup>S</sup>	INSPECT PATS APU GTCP36-150W BLEED AIR SYSTEM							Service	ATA:21
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 21.035	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
211013	LEFT SWITCHES BLEED AIR OVER TEMPERATURE TEST							Service	ATA:21
	MOS	03-Dec-21	60		03-Dec-26		1542 d		
	HRS	11882.7							
WC#: 21.265	AFL	7485							
211014	RIGHT SWITCHES BLEED AIR OVER TEMPERATURE TEST							Service	ATA:21
	MOS	03-Dec-21	60		03-Dec-26		1542 d		
	HRS	11882.7							
WC#: 21.265	AFL	7485							
211019	APU SHUTOFF VALVE							Component	ATA:21
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.020	AFL	0		TSN 0					
211088	NO. 1 AIR DISTRIBUTION ACTUATOR							Component	ATA:21
PN:800-9405-22	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:2452	HRS	0		TSN 0					
WC#: 21.108	AFL	0		TSN 0					
211089	NO. 2 AIR DISTRIBUTION ACTUATOR							Component	ATA:21
PN:800-9405-22	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:2455	HRS	0		TSN 0					
WC#: 21.108	AFL	0		TSN 0					
211090	NO. 3 AIR DISTRIBUTION ACTUATOR							Component	ATA:21
PN:1092TH100-47	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:2943D	HRS	0		TSN 0					
WC#: 21.108	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>211091 NO. 4 AIR DISTRIBUTION ACTUATOR</b> Component ATA:21								
PN:1092TH100-47	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:2810D	HRS	0		TSN 0				
WC#: 21.108	AFL	0		TSN 0				
<b>211092 NO. 5 AIR DISTRIBUTION ACTUATOR</b> Component ATA:21								
PN:1092TH100-47	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:2936D	HRS	0		TSN 0				
WC#: 21.108	AFL	0		TSN 0				
<b>212001 LEFT MAIN AIR VALVE</b> Component ATA:21								
PN:321292-1	MOS/MSC	06-Dec-04	O/C	TSO 0				
SN:P-1109	HRS	2712		TSO 0				
WC#: 21.040	AFL	1889		TSO 0				
<b>212002 RIGHT MAIN AIR VALVE</b> Component ATA:21								
PN:250072	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:11010027	HRS	0		TSN 0				
WC#: 21.045	AFL	0		TSN 0				
<b>212008 PRESSURE REGULATOR VALVE</b> Component ATA:21								
PN:3215086-3	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:517	HRS	0		TSN 0				
WC#: 21.295	AFL	0		TSN 0				
<b>212026 NO. 1 ENGINE BLEED AIR NON-RETURN VALVE</b> Component ATA:21								
PN:HTE250072-1	MOS/MSC	20-May-20	O/C	TSO 0				
SN:29060897	HRS	10855.5		TSO 0				
WC#: 21.050	AFL	6932		TSO 0				
<b>212027 NO. 2 ENGINE BLEED AIR NON-RETURN VALVE</b> Component ATA:21								
PN:HTE41686	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:M0504VNR0900	HRS	0		TSN 0				
WC#: 21.050	AFL	0		TSN 0				
<b>212050 AUXILIARY HEATING BLEED AIR NON-RETURN VALVE</b> Component ATA:21								
PN:109812-9	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:3332	HRS	0		TSN 0				
WC#: 21.055	AFL	0		TSN 0				



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
<b>2120501<sup>U</sup></b>		<b>NOSE FAN</b>						<b>Component</b>	<b>ATA:21</b>
PN:0901-2	MOS/MSC	19-Jul-01	O/C						
SN:0379	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>212062</b>		<b>LEFT (HP/LP) MIXING VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:3213788-1-1	MOS/MSC	13-Mar-22	O/C	TSO 0					
SN:P-116	HRS	11930.2		TSO 0					
WC#: 21.060	AFL	7513		TSO 0					
<b>212063</b>		<b>RIGHT (HP/LP) MIXING VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:3213788-1-1	MOS/MSC	13-Mar-22	O/C	TSO 0					
SN:1482	HRS	11930.2		TSO 0					
WC#: 21.060	AFL	7513		TSO 0					
<b>212074</b>		<b>MAIN SUPPLY NON-RETURN VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:AWE124-51-2	MOS	25-Oct-11		TSN 0				<b>OVERHAUL</b>	
SN:7811023	HRS	6590.4	12000	TSN 0	18590.4		6503.2		
WC#: 21.245	AFL			TSN 0					
<b>212082</b>		<b>BLEED AIR CHECK VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:HHTE4405	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:M0290VNR0201	HRS	0		TSN 0					
WC#: 21.070	AFL	0		TSN 0					
<b>212086</b>		<b>RAM AIR NON-RETURN VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:321262-1	MOS/MSC	03-May-21	O/C	TSO 0					
SN:1171	HRS	11562.2		TSO 0					
WC#: 21.075	AFL	7300		TSO 0					
<b>212098</b>		<b>RAM AIR SUPPLY NON-RETURN VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:123190-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:6531	HRS	0		TSN 0					
WC#: 21.080	AFL	0		TSN 0					
<b>212122</b>		<b>UPPER CHECK VALVE</b>						<b>Component</b>	<b>ATA:21</b>
PN:130156-1	MOS/MSC	15-Dec-04	O/C						
SN:74-A0361	HRS	2713.5		TSN 0					
WC#: 21.095	AFL	1890		TSN 0					





## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>212123 LOWER CHECK VALVE</b> Component ATA:21								
PN:130156-2	MOS/MSC	31-Jul-08	O/C	TSN 0				
SN:47-A0889	HRS	5564		TSN 0				
WC#: 21.095	AFL	3728		TSN 0				
<b>212146 CABIN RECIRCULATING FAN</b> Component ATA:21								
PN:0901-2	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:379	HRS	0		TSN 0				
WC#: 21.100	AFL	0		TSN 0				
<b>213001 NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE</b> Component ATA:21								
PN:B01A2-14128A	MOS/MSC	19-Nov-08	O/C	TSR 0				
SN:HAY0226	HRS	5711		TSR 0				
WC#: 21.105	AFL	3848		TSR 0				
<b>213002 NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE</b> Component ATA:21								
PN:B01A2-14128A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:VR417	HRS	0		TSN 0				
WC#: 21.105	AFL	0		TSN 0				
<b>213019 OUTFLOW/SAFETY VALVE CONTROLLER</b> Component ATA:21								
PN:130530-5	MOS/MSC	13-Mar-22	O/C	TSN 0				
SN:88-C0474	HRS	11930.2		TSN 0				
WC#: 21.115	AFL	7513		TSN 0				
<b>213031 LEFT OUTFLOW VALVE</b> Component ATA:21								
PN:103278-18	MOS/MSC	15-Dec-04	O/C	TSN 0				
SN:41-A0452	HRS	2714		TSN 0				
WC#: 21.120	AFL	1890		TSN 0				
<b>213032 RIGHT OUTFLOW VALVE</b> Component ATA:21								
PN:103278-13	MOS	15-Dec-04		TSN 0				LIFE LIMIT
SN:40-A0422	HRS	2714	30000	TSN 0	32714		20626.8	
WC#: 21.120	AFL	1890		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>213035 2" BUTTERFLY VALVE Component ATA:21</b>								
PN:AWE113-13A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:VP471	HRS	0		TSN 0				
WC#: 21.320	AFL	0		TSN 0				
REF: GENERIC NO REF								
<b>213050<sup>U</sup> LEFT OUTFLOW VALVE Component ATA:21</b>								
PN:103278-18	MOS/MSC	15-Dec-04	O/C					
SN:41-A0453	HRS	2713.5		TSO 0				
	AFL	1890		TSO 0				
<b>213050<sup>U</sup> RIGHT OUTFLOW VALVE Component ATA:21</b>								
PN:103278-13	MOS/MSC	15-Jun-09	O/C					
SN:40-A0400	HRS	5983.2		TSO 0				
	AFL	4032		TSO 0				
<b>213067 CABIN ALTITUDE CONTROL VALVE Component ATA:21</b>								
PN:131004-2	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:120-5668	HRS	0		TSN 0				
WC#: 21.125	AFL	0		TSN 0				
<b>213073 MECHANICAL DUMP VALVE Component ATA:21</b>								
PN:HTE940008	MOS/MSC	19-Jul-01	O/C					
SN:FR035BE	HRS	0		TSN 0				
WC#: 21.130	AFL	0		TSN 0				
<b>213097 ALTIMETER PRESSURE SWITCH Component ATA:21</b>								
PN:140-380024-7	MOS/MSC	27-Jul-09	O/C	TSN 0				
SN:K008107	HRS	6022		TSN 0				
WC#: 21.135	AFL	4065		TSN 0				
<b>213109 VENTURI Component ATA:21</b>								
PN:131052-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:119-4022	HRS	0		TSN 0				
WC#: 21.140	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>213115 FAN OPERATED VENTURI</b> Component ATA:21								
PN:132322-3-1	MOS/MSC	24-Jan-22	O/C	TSO 0				
SN:129-1684	HRS	11886		TSO 0				
WC#: 21.145	AFL	7487		TSO 0				
<b>213121 LEFT PNEUMATIC VALVE</b> Component ATA:21								
PN:107312-4-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:50-12332	HRS	0		TSN 0				
WC#: 21.150	AFL	0		TSN 0				
<b>213122 RIGHT PNEUMATIC VALVE</b> Component ATA:21								
PN:107312-4-1	MOS/MSC	17-Feb-22	O/C					
SN:53-6661	HRS	11909.5						
WC#: 21.150	AFL	7500						
<b>213133 LEFT ABSOLUTE PRESSURE CONTROL</b> Component ATA:21								
PN:102466-13	MOS/MSC	15-Dec-04	O/C	TSR 0				
SN:122-A0111	HRS	2714		TSR 0				
WC#: 21.155	AFL	1890		TSR 0				
<b>213134 RIGHT ABSOLUTE PRESSURE CONTROL</b> Component ATA:21								
PN:102466-13	MOS/MSC	15-Dec-04	O/C	TSR 0				
SN:82-A0004	HRS	2714		TSR 0				
WC#: 21.155	AFL	1890		TSR 0				
<b>213157 JET PUMP</b> Component ATA:21								
PN:131150-1-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:20-3067	HRS	0		TSN 0				
WC#: 21.160	AFL	0		TSN 0				
<b>213181 GROUND PRESSURE CONNECTOR</b> Component ATA:21								
PN:WGE133-2A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:VP487	HRS	0		TSN 0				
WC#: 21.170	AFL	0		TSN 0				
<b>216001 CABIN TEMPERATURE CONTROL VALVE</b> Component ATA:21								
PN:104968	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:1410	HRS	0		TSN 0				
WC#: 21.175	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>216025 AUXILIARY HEATING VALVE</b> Component ATA:21								
PN:104568	MOS/MSC	07-Dec-05	O/C	TSO 0				
SN:P-10326	HRS	3537		TSO 0				
WC#: 21.180	AFL	2391		TSO 0				
<b>216055 CABIN TEMPERATURE (CONTROLLER) SENSOR</b> Component ATA:21								
PN:617452-4	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:041C-1387	HRS	0		TSN 0				
WC#: 21.185	AFL	0		TSN 0				
<b>216073 CABIN TEMPERATURE CONTROLLER</b> Component ATA:21								
PN:617452-4	MOS/MSC	20-Aug-05	O/C					
SN:119C211	HRS	3347.9		TSR 0				
WC#: 21.190	AFL	2263		TSR 0				
<b>216115 COLD AIR UNIT PACK</b> Component ATA:21								
PN:2340594-4	MOS/MSC	25-Jun-13	O/C					
SN:2127	HRS	7869						
WC#: 21.200	AFL	5246						
<b>216121 MODULATING VALVE</b> Component ATA:21								
PN:978836-5-1	MOS/MSC	18-Jun-02	O/C	TSR 0				
SN:331	HRS	662		TSR 0				
WC#: 21.210	AFL	464		TSR 0				
<b>216127 CONTROL SENSOR</b> Component ATA:21								
PN:1150642-3	MOS/MSC	18-Jun-02	O/C	TSR 0				
SN:069C-10314	HRS	662		TSR 0				
WC#: 21.215	AFL	464		TSR 0				
<b>216135 TOTAL TEMPERATURE SENSOR</b> Component ATA:21								
PN:102-ER-1EC	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:A37609	HRS	0		TSN 0				
WC#: 21.305	AFL	0		TSN 0				
<b>217001 WATER SEPARATOR</b> Component ATA:21								
PN:21BC113	MOS/MSC	03-May-21	O/C					
SN:NSN	HRS	11562						
WC#: 21.220	AFL	7300						



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 21 - AIR CONDITIONING</b>								
<b>217014 CABIN TRIPLE INDICATOR</b>								Component ATA:21
PN:51010-1113	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:505528	HRS	0		TSN 0				
WC#: 21.225	AFL	0		TSN 0				
<b>217023 PRESSURE SWITCH</b>								Component ATA:21
PN:HTE690090	MOS/MSC	01-Mar-05	O/C					
SN:FRTR016AX	HRS	2905.4						
WC#: 21.235	AFL	2007						
<b>ATA 22 - AUTO FLIGHT</b>								
<b>221001 AFCS CONTROL PANEL</b>								Component ATA:22
PN:7011702-915	MOS/MSC	25-Jul-22	O/C	TSR 0				
SN:01041156	HRS	12037		TSR 0				
WC#: 22.010	AFL	7577		TSR 0				
<b>221007 NO. 1 FLIGHT GUIDANCE COMPUTER</b>								Component ATA:22
PN:7003974-732	MOS/MSC	23-Aug-22	O/C	TSR 0				
SN:98065031	HRS	12078.9		TSR 0				
WC#: 22.015	AFL	7605		TSR 0				
REF: GENERIC NO REF								
<b>221008 NO. 2 FLIGHT GUIDANCE COMPUTER</b>								Component ATA:22
PN:7003974-732	MOS/MSC	06-Feb-17	O/C	TSR 0				
SN:94063901	HRS	10500.4		TSR 0				
WC#: 22.015	AFL	6693		TSR 0				
REF: GENERIC NO REF								
<b>221037 AUTOPILOT ELEVATOR SERVO</b>								Component ATA:22
PN:4006719-910	MOS/MSC	03-Feb-07	O/C	TSR 0				
SN:95077946	HRS	4455		TSR 0				
WC#: 22.020	AFL	2982		TSR 0				
<b>221039 ELEVATOR SERVO MOUNT</b>								Component ATA:22
PN:4005842	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:113162	HRS	0		TSN 0				
WC#: 22.050	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 22 - AUTO FLIGHT</b>									
<b>221043</b>		<b>AUTOPILOT RUDDER SERVO</b>					<b>Component</b>		<b>ATA:22</b>
PN:4006719-913	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1025099	HRS	0		TSN 0					
WC#: 22.020	AFL	0		TSN 0					
<b>221045</b>		<b>RUDDER SERVO MOUNT</b>					<b>Component</b>		<b>ATA:22</b>
PN:4005842	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:627773	HRS	0		TSN 0					
WC#: 22.050	AFL	0		TSN 0					
<b>221049</b>		<b>AUTOPILOT AILERON SERVO</b>					<b>Component</b>		<b>ATA:22</b>
PN:4006719-906	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1015023	HRS	0		TSN 0					
WC#: 22.020	AFL	0		TSN 0					
<b>221052</b>		<b>AILERON SERVO MOUNT</b>					<b>Component</b>		<b>ATA:22</b>
PN:4005842	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:72996	HRS	0		TSN 0					
WC#: 22.050	AFL	0		TSN 0					
<b>ATA 23 - COMMUNICATIONS</b>									
<b>2300001<sup>U</sup></b>		<b>CAPT HEADSET</b>					<b>Component</b>		<b>ATA:23</b>
PN:324843-0020	MOS/MSC	24-Aug-16	O/C	TSR 0					
SN:053851C32870002AE	HRS	10500.4		TSR 0					
	AFL	6693		TSR 0					
<b>2300002<sup>U</sup></b>		<b>FO'S HEADSET</b>					<b>Component</b>		<b>ATA:23</b>
PN:324843-0020	MOS/MSC	09-Mar-16	O/C						
SN:048023E82110258AE	HRS	9810.6							
	AFL	6293							
<b>231001</b>		<b>NO. 1 HF COMMUNICATIONS CONTROLLER</b>					<b>Component</b>		<b>ATA:23</b>
PN:071-1274-02	MOS/MSC	30-Mar-20	O/C						
SN:X5452	HRS	10840							
WC#: 23.015	AFL	6914							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 23 - COMMUNICATIONS</b>									
231002	NO. 2 HF COMMUNICATIONS CONTROLLER							Component	ATA:23
PN:071-1274-02	MOS/MSC	30-Mar-20	O/C						
SN:5748	HRS	10840							
WC#: 23.015	AFL	6914							
231004	NO. 1 HF CONTROLLER ADAPTER							Component	ATA:23
PN:071-1268-01	MOS/MSC	29-Dec-16	O/C						
SN:4435	HRS	10423							
WC#: 23.020	AFL	6657							
231006	NO. 2 HF CONTROLLER ADAPTER							Component	ATA:23
PN:071-1268-01	MOS/MSC	29-Dec-16	O/C						
SN:4308	HRS	10423							
WC#: 23.020	AFL	6657							
231011	NO. 1 HF COMMUNICATIONS POWER AMPLIFIER							Component	ATA:23
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 23.025	AFL	0		TSN 0					
231012	NO. 2 HF COMMUNICATIONS POWER AMPLIFIER							Component	ATA:23
PN:064-1017-02	MOS/MSC	19-Jul-01	O/C		TSN 0				
SN:17019	HRS	0			TSN 0				
WC#: 23.025	AFL	0			TSN 0				
231025	NO. 1 HF RECEIVER EXCITER							Component	ATA:23
PN:064-1015-01	MOS/MSC	29-May-17	O/C		TSR 1				
SN:31681	HRS	10697			TSR 0				
WC#: 23.030	AFL	6813			TSR 0				
231026	NO. 2 HF RECEIVER EXCITER							Component	ATA:23
PN:064-1015-01	MOS/MSC	14-Aug-10	O/C						
SN:31128	HRS	6553.4							
WC#: 23.030	AFL	4401							
231027	NO. 1 HF BRIDGING AMPLIFIER							Component	ATA:23
PN:071-0019-00	MOS/MSC	19-Jul-01	O/C		TSN 0				
SN:3736	HRS	0			TSN 0				
WC#: 23.035	AFL	0			TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 23 - COMMUNICATIONS</b>								
<b>231028 NO. 2 HF BRIDGING AMPLIFIER Component ATA:23</b>								
PN:071-0019-00	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:3743	HRS	0		TSN 0				
WC#: 23.035	AFL	0		TSN 0				
<b>231029 DUAL HF CAPACITOR Component ATA:23</b>								
PN:071-1270-01	MOS/MSC	01-Feb-03	O/C					
SN:2404	HRS	1256						
WC#: 23.040	AFL	915						
<b>231043 NO. 1 VHF COMMUNICATIONS TRANSCEIVER Component ATA:23</b>								
PN:7510700-764	MOS/MSC	03-Jun-03	O/C					
SN:24860	HRS	1644						
WC#: 23.045	AFL	1152						
<b>231049 NO. 2 VHF COMMUNICATIONS TRANSCEIVER Component ATA:23</b>								
PN:7510700-764	MOS/MSC	19-Aug-14	O/C					
SN:1056410	HRS	8835						
WC#: 23.045	AFL	5736						
<b>2310506<sup>U</sup> NO.1 COMM/TRANSPONDER UNIT Component ATA:23</b>								
PN:7510700-764	MOS/MSC	03-Jun-03	O/C					
SN:00024860	HRS	1644.3		TSR 0				
	AFL	1152		TSR 0				
<b>2310507<sup>U</sup> NO.2 COMM/TRANSPONDER UNIT Component ATA:23</b>								
PN:7510700-764	MOS/MSC	19-Aug-14	O/C					
SN:01056410	HRS	8835						
	AFL	5736						
<b>231055 NO. 1 VHF AERIAL Component ATA:23</b>								
PN:16-21-1TMD02	MOS/MSC	06-May-10	O/C	TSN 0				
SN:7905	HRS	6506.1		TSN 0				
WC#: 23.055	AFL	4358		TSN 0				
<b>231055<sup>U</sup> NO. 1 VHF AERIAL Component ATA:23</b>								
PN:16-21-1T	MOS/MSC	19-Jul-01	O/C					
SN:7295	HRS	0		TSN 0				
	AFL	0		TSN 0				





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 23 - COMMUNICATIONS</b>								
231056	NO. 2 VHF AERIAL							Component ATA:23
PN:S65-5366-8L	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:5276	HRS	0		TSN 0				
WC#: 23.055	AFL	0		TSN 0				
231058	AUDIO TONE GENERATOR							Component ATA:23
PN:M1285AC	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:1030002679	HRS	0		TSN 0				
WC#: 23.060	AFL	0		TSN 0				
231061	NO. 1 RADIO MANAGEMENT UNIT							Component ATA:23
PN:7013270-983	MOS/MSC	25-Jan-21	O/C	TSR 0				
SN:15029151	HRS	11368.5		TSR 0				
WC#: 23.065	AFL	7198		TSR 0				
231062	NO. 2 RADIO MANAGEMENT UNIT							Component ATA:23
PN:7012100-825	MOS/MSC	07-Mar-18	O/C					
SN:98112260	HRS	10727						
WC#: 23.065	AFL	6833						
231064	CLEARANCE DELIVERY CONTROL							Component ATA:23
PN:7513000-835	MOS/MSC	26-Feb-15	O/C	TSN 0				
SN:13014032	HRS	9184.1		TSN 0				
WC#: 23.070	AFL	5930		TSN 0				
235001	NO. 1 AUDIO CONTROLLER							Component ATA:23
PN:7511001-909	MOS/MSC	31-Jul-08	O/C	TSR 0				
SN:99124753	HRS	5564		TSR 0				
WC#: 23.095	AFL	3728		TSR 0				
235002	NO. 2 AUDIO CONTROLLER							Component ATA:23
PN:7511001-909	MOS/MSC	21-Nov-03	O/C	TSR 0				
SN:92010599	HRS	1956.4		TSR 0				
WC#: 23.095	AFL	1384		TSR 0				
235017	NO. 1 HANDHELD AUDIO MICROPHONE							Component ATA:23
PN:602FTR	MOS/MSC	05-Mar-02	O/C					
SN:21332	HRS	321						
WC#: 23.100	AFL	223						



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 23 - COMMUNICATIONS</b>									
235019	NO. 2 HANDHELD AUDIO MICROPHONE							Component	ATA:23
PN:602FTR	MOS/MSC	05-Mar-02	O/C						
SN:18974	HRS	321							
WC#: 23.100	AFL	223							
237001	COCKPIT VOICE RECORDER							Component	ATA:23
PN:1603-02-12	MOS/MSC	24-Apr-20	O/C	TSO 0					
SN:1384	HRS	10841		TSO 0					
WC#: 23.105	AFL	6917		TSO 0					
237004	COCKPIT VOICE RECORDER NO.1 MICROPHONE							Component	ATA:23
PN:16301-01	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:735	HRS	0		TSN 0					
WC#: 23.110	AFL	0		TSN 0					
237005	COCKPIT VOICE RECORDER NO.2 MICROPHONE							Component	ATA:23
PN:16301-01	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:767	HRS	0		TSN 0					
WC#: 23.110	AFL	0		TSN 0					
237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component	ATA:23
PN:DK120	MOS	21-Jun-22	72	TSN 0	21-Jun-28		2108 d	OVERHAUL	
SN:AT177045	HRS	12023.9		TSN 0					
WC#: 23.105	AFL	7567		TSN 0					
237015	TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Service	ATA:23
	MOS	03-May-21	24		31-May-23		260 d		
	HRS	11562							
WC#: 23.105	AFL	7300							
237017	REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service	ATA:23
	MOS/MSC	21-Jun-22	DUE		31-Mar-29 <sup>M</sup>		2391 d		
	HRS	12023.9							
WC#: 23.105	AFL	7567							
237019	LEFT COCKPIT VOICE RECORDER CONTROL							Component	ATA:23
PN:1634-01	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:443	HRS	0		TSN 0					
WC#: 23.125	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 23 - COMMUNICATIONS</b>									
<b>237021</b>		<b>VOICE RECORDER INERTIA SWITCH</b>					<b>Component</b>		<b>ATA:23</b>
PN:3LO-453/2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9797	HRS	0		TSN 0					
WC#: 23.115	AFL	0		TSN 0					
<b>2370500<sup>U</sup></b>		<b>COCKPIT VOICE RECORDER</b>					<b>Component</b>		<b>ATA:23</b>
PN:1603-02-12	MOS/MSC	27-Mar-08	O/C						
SN:1384	HRS	5399.6		TSO 0					
	AFL	3609		TSO 0					
<b>238015</b>		<b>SELCAL DECODER UNIT</b>					<b>Component</b>		<b>ATA:23</b>
PN:1200008-002	MOS/MSC	04-May-16	O/C	TSR 4					
SN:7469	HRS	9954.3		TSR 0					
WC#: 23.120	AFL	6365		TSR 0					
<b>ATA 24 - ELECTRICAL POWER</b>									
<b>240001</b>		<b>INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR</b>					<b>Service</b>		<b>ATA:24</b>
PN:23080-064	MOS	21-Jun-22							
SN:P1609	HRS	12023.9	300 (+100)		12323.9	12423.9	236.7 (+100)		
WC#: 24.045	AFL	7567							
REF: AFMS OUT OF PHASE INSPECTIONS									
<b>240001</b>		<b>INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR</b>					<b>Service</b>		<b>ATA:24</b>
PN:23080-064	MOS	13-Mar-22							
SN:P1992	HRS	11930.2	300 (+100)		12230.2	12330.2	143 (+100)		
WC#: 24.045	AFL	7513							
REF: AFMS OUT OF PHASE INSPECTIONS									
<b>240002<sup>S</sup></b>		<b>OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS</b>					<b>Service</b>		<b>ATA:24</b>
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 24.010	AFL	7300							
REF: AFMS INSPECTION B1									
								PKG:7,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 24 - ELECTRICAL POWER</b>								
<b>240003<sup>S</sup> FUNCTION TEST FREQUENCY WILD A.C. SYSTEM Service ATA:24</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 24.030	AFL	6832						
				REF: AFMS INSPECTION D1				PKG:31,93
<b>240004<sup>S</sup> CHECK BUSBAR CONTACTOR CONTROL Service ATA:24</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 24.145	AFL	6832						
				REF: AFMS INSPECTION C1				PKG:19,92
<b>240005<sup>U</sup> DC CONVERTER INSTALL Component ATA:24</b>								
PN:LS03-05105	MOS/MSC	02-Oct-13	O/C					
SN:007-002246	HRS	8133.1						
	AFL	5385						
<b>240005<sup>S</sup> FUNCTIONAL TEST APU GENERATOR OVERHEAT INDICATION CIRCUIT Service ATA:24</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 24.180	AFL	6832						
				REF: AFMS INSPECTION D1				PKG:31,93
<b>240006<sup>S</sup> CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT Service ATA:24</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 24.070	AFL	6832						
				REF: AFMS INSPECTION D6				PKG:36,93
<b>240007<sup>S</sup> BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED). Service ATA:24</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 24.110	AFL	6832						
				REF: AFMS INSPECTION D7				PKG:37,93



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
240009 <sup>S</sup>	FUNCTIONAL TEST D.C. GENERATING SYSTEM							Service	ATA:24
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 24.065	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
240010 <sup>S</sup>	INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 24.160	AFL	6832							
				REF: AFMS INSPECTION C6				PKG:24,92	
240011 <sup>S</sup>	REPLACE BUSBAR PE, PS1 AND PS2 FEEDER FUSES							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 24.150	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
240012 <sup>S</sup>	INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 24.165	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
240013 <sup>S</sup>	FUNCTION TEST ALL CIRCUIT BREAKERS							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.005	AFL	6832							
				REF: AFMS INSPECTION D1				PKG:31,93	
240014 <sup>S</sup>	FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.040	AFL	6832							
				REF: AFMS INSPECTION D1				PKG:31,93	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
240015 <sup>S</sup>	FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.040	AFL	6832							
				REF: AFMS INSPECTION D1				PKG:31,93	
240016 <sup>S</sup>	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.235	AFL	6832							
				REF: AFMS INSPECTION D3				PKG:33,93	
240018 <sup>S</sup>	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.235	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	
240024	INSPECT/CHECK APU STARTER/GENERATOR							Service	ATA:24
PN:23080-064	MOS	08-Sep-21							
SN:Y30328	HRS	11817							
WC#: 24.085	AFL	7449							
	APH	10218	500		10718		160		
				REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS					
240025 <sup>S</sup>	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.245	AFL	6832							
				REF: AFMS INSPECTION D5				PKG:35,93	
240026 <sup>S</sup>	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.240	AFL	6832							
				REF: AFMS INSPECTION D4				PKG:34,93	



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
240027 <sup>S</sup>	CHECK MAIN BATTERIES							Service	ATA:24
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 24.250	AFL	6832							
REF: AFMS INSPECTION D7						PKG:37,93			
240028	VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M							Service	ATA:24
	MOS	02-Apr-22							
	HRS	11960.2	400 (+10%)		12360.2	12400.2	273 (+40)		
WC#: 24.095	AFL	7530							
REF: AFMS OUT OF PHASE INSPECTIONS									
240029 <sup>S</sup>	VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF HEAT DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS							Service	ATA:24
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 24.260	AFL	7513							
REF: AFMS INSPECTION E6						PKG:48,94			
242001	NO. 1 (MAIN) INVERTER							Component	ATA:24
PN:100-1600-04	MOS/MSC	09-Sep-22	O/C	TSR 0					
SN:1185ME	HRS	12086.8		TSR 0					
WC#: 24.015	AFL	7611		TSR 0					
242002	NO. 2 (MAIN) INVERTER							Component	ATA:24
PN:140-380010-7	MOS/MSC	26-Jan-22	O/C	TSN 0					
SN:1159955E	HRS	11886		TSN 0					
WC#: 24.015	AFL	7487		TSN 0					
242013	NO. 3 (STANDBY) INVERTER							Component	ATA:24
PN:PC-250	MOS/MSC	17-Nov-13	O/C	TSO 0					
SN:6398	HRS	8133.4		TSO 0					
WC#: 24.015	AFL	5386		TSO 0					
242031	NO. 1 INVERTER CONTACTOR							Component	ATA:24
PN:LDA200B18C	MOS	14-Jan-16						OVERHAUL	
SN:P4955	HRS	9849.5	5000		14849.5 <sup>M</sup>		2762.3		
WC#: 24.020	AFL	6309							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 24 - ELECTRICAL POWER</b>								
<b>242032 NO. 2 INVERTER CONTACTOR</b>								
PN:LDA200B18C	MOS	26-Jan-22		TSO 0				Component ATA:24 OVERHAUL
SN:Q32025	HRS	11886	5000	TSO 0	16886		4798.8	
WC#: 24.020	AFL	7487		TSO 0				
<b>242073 NO. 1 ENGINE AC GENERATOR</b>								
PN:BA02801-1	MOS	14-Jul-16	96		14-Jul-24 <sup>M</sup>		670 d	Component ATA:24 OVERHAUL
SN:3230	HRS	10258.7	3000	TSO 0	13258.7		1171.5	
WC#: 24.025	AFL	6557		TSO 0				
<b>242074 NO. 2 ENGINE AC GENERATOR</b>								
PN:BA02801-1	MOS	11-Sep-20	96	TSO 0	11-Sep-28		2190 d	Component ATA:24 OVERHAUL
SN:3230	HRS	11121.9	3000	TSO 0	14121.9		2034.7	
WC#: 24.025	AFL	7063		TSO 0				
<b>242097 LEFT AC GENERATOR CONTROL UNIT</b>								
PN:CB02701	MOS/MSC	27-Oct-05	O/C					Component ATA:24
SN:2500	HRS	3470.1						
WC#: 24.035	AFL	2345						
<b>242098 RIGHT AC GENERATOR CONTROL UNIT</b>								
PN:CB02701	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:24
SN:2448	HRS	0		TSN 0				
WC#: 24.035	AFL	0		TSN 0				
<b>243001 NO. 1 ENGINE STARTER/GENERATOR</b>								
PN:23080-064	MOS	03-Dec-20		TSO 0				Component ATA:24 OVERHAUL
SN:P1609	HRS	11285.1	1000	TSO 0	12285.1		197.9	
WC#: 24.045	AFL	7152		TSO 0				
<b>243002 NO. 2 ENGINE STARTER/GENERATOR</b>								
PN:23080-064	MOS	13-Mar-22		TSO 0				Component ATA:24 OVERHAUL
SN:P1992	HRS	11930.2	1000	TSO 0	12930.2		843	
WC#: 24.045	AFL	7513		TSO 0				
<b>243037 NO. 1 DC GENERATOR CONTROL UNIT</b>								
PN:51539-006H	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:24
SN:Y0584	HRS	0		TSN 0				
WC#: 24.050	AFL	0		TSN 0				





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 24 - ELECTRICAL POWER</b>								
<b>243038 NO. 2 DC GENERATOR CONTROL UNIT</b> Component ATA:24								
PN:51539-006H	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:Y0586	HRS	0		TSN 0				
WC#: 24.050	AFL	0		TSN 0				
<b>243079 DC VOLTAGE SENSING UNIT</b> Component ATA:24								
PN:U3626-2	MOS/MSC	23-Apr-05	O/C					
SN:2453	HRS	3042.1						
WC#: 24.070	AFL	2090						
<b>243091 GROUND SUPPLY START (E) CONTACTOR</b> Component ATA:24								
PN:LDG150Y4	MOS	04-Oct-12		TSN 0				OVERHAUL
SN:C2944	HRS	7445.1	6000	TSN 0	13445.1		1357.9	
WC#: 24.075	AFL	4979		TSN 0				
<b>243103 APU STARTER/GENERATOR CONTROL UNIT</b> Component ATA:24								
PN:51539-006H	MOS/MSC	09-Dec-20	O/C	TSR 0				
SN:P1378	HRS	11294.3		TSR 0				
WC#: 24.080	AFL	7157		TSR 0				
<b>243115 APU STARTER/GENERATOR</b> Component ATA:24								
PN:23080-064	MOS	03-Dec-20		TSO 0				OVERHAUL
SN:Y30328	HRS	11285.1		TSO 0				
WC#: 24.085	AFL	7152		TSO 0				
	APH	10001	1000	TSO 0	11001		443	
<b>243137 NO. 1 BATTERY</b> Component ATA:24								
PN:9750W0640	MOS/MSC	21-Oct-20	O/C	TSN 0				
SN:200170019	HRS	11200.5		TSN 0				
WC#: 24.090	AFL	7103		TSN 0				
<b>243138 NO. 2 BATTERY</b> Component ATA:24								
PN:9750W0640	MOS/MSC	21-Oct-20	O/C	TSN 0				
SN:200170021	HRS	11200.5		TSN 0				
WC#: 24.090	AFL	7103		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 24 - ELECTRICAL POWER</b>								
243139	NO. 3 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:40716888	HRS	0		TSN 0				
WC#: 24.210	AFL	0		TSN 0				
243140	NO. 4 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	14-Aug-20	O/C	TSN 0				
SN:7001080	HRS	11060.4		TSN 0				
WC#: 24.220	AFL	7036		TSN 0				
243141	NO. 5 BATTERY							Component ATA:24
PN:RG-126	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:40716873	HRS	0		TSN 0				
WC#: 24.230	AFL	0		TSN 0				
REF: AFMS 24-30-155								
243142	NO. 6 BATTERY							Component ATA:24
PN:PN	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.230	AFL	0		TSN 0				
REF: AFMS 24-30-155								
243143	NO. 7 BATTERY							Component ATA:24
PN:PN	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 24.230	AFL	0		TSN 0				
REF: AFMS 24-30-155								
243154	CAPACITY CHECK NO. 1 BATTERY							Service ATA:24
PN:9750W0640	MOS	09-Sep-21	12 (+30d/-30d)		30-Sep-22	09-Oct-22	17 d (+9)	
SN:200170019	HRS	11200.5						
WC#: 24.090	AFL	7103						
243155	CAPACITY CHECK NO. 2 BATTERY							Service ATA:24
PN:9750W0640	MOS	09-Sep-21	12 (+30d/-30d)		30-Sep-22	09-Oct-22	17 d (+9)	
SN:200170021	HRS	11200.5						
WC#: 24.090	AFL	7103						



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
243156	CAPACITY CHECK NO. 3 BATTERY							Service	ATA:24
PN:RG-126	DAYS/MSC	09-Sep-21	O/C						
SN:40716888	HRS	11817							
WC#: 24.210	AFL	7449							
243157	CAPACITY CHECK NO. 4 BATTERY							Service	ATA:24
PN:RG-126	DAYS/MSC	09-Sep-21	O/C						
SN:7001080	HRS	11817							
WC#: 24.220	AFL	7449							
243158	CAPACITY CHECK NO. 5 BATTERY							Service	ATA:24
PN:RG-126	DAYS/MSC	09-Sep-21	O/C						
SN:40716873	HRS	11817							
WC#: 24.230	AFL	7449							
243159	ENERGY LEVEL TEST NO. 6 BATTERY							Service	ATA:24
PN:PN	DAYS/MSC	20-Nov-01	O/C	TAC 0					
SN:UNKNOWN	HRS	0							
WC#: 24.230	AFL	0							
243160	ENERGY LEVEL TEST NO. 7 BATTERY							Service	ATA:24
PN:PN	DAYS/MSC	20-Nov-01	O/C	TAC 0					
SN:UNKNOWN	HRS	0							
WC#: 24.230	AFL	0							
243238	OVERVOLTAGE SENSOR							Component	ATA:24
PN:E311TS	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:CM75942	HRS	0		TSN 0					
WC#: 24.110	AFL	0		TSN 0					
243246	THERMAL SWITCH							Component	ATA:24
PN:21346-6	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:4907	HRS	0		TSN 0					
WC#: 24.115	AFL	0		TSN 0					
243247	S CONTACTOR							Component	ATA:24
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.120	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
<b>245001</b>		<b>BUS TIE (T) CONTACTOR</b>						<b>Component</b>	<b>ATA:24</b>
PN:LDA150-A8C	MOS	02-Oct-13						OVERHAUL	
SN:P36439	HRS	8133.1	5000		13133.1 <sup>M</sup>		1045.9		
WC#: 24.140	AFL	5385							
<b>245043</b>		<b>TEMPERATURE SENSOR</b>						<b>Component</b>	<b>ATA:24</b>
PN:548408-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:021C-2000	HRS	0		TSN 0					
WC#: 24.170	AFL	0		TSN 0					
<b>246004.4<sup>U</sup></b>		<b>CONTACTOR</b>						<b>Component</b>	<b>ATA:24</b>
PN:PN	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>246005.2<sup>U</sup></b>		<b>NO1 STARTER CONTACTOR</b>						<b>Component</b>	<b>ATA:24</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>246005.3<sup>U</sup></b>		<b>NO.2 STARTER CONTACTOR</b>						<b>Component</b>	<b>ATA:24</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
<b>250000<sup>U</sup></b>		<b>ATG SOFTWARE UPGRADE TO VERSION 2.7</b>						<b>Service</b>	<b>ATA:25</b>
	MOS	19-Jul-01							
	HRS	0							
	AFL	0							
<b>250003<sup>S</sup></b>		<b>CHECK 3RD CREW MEMBERS SEAT</b>						<b>Service</b>	<b>ATA:25</b>
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 25.115	AFL	7300							

REF: AFMS INSPECTION B6

PKG:12,91



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
250005	INSPECT EMERGENCY PACKS (IF FITTED)							Service	ATA:25
	MOS/MSC	13-Mar-22	N/R						
	HRS	11930.2							
WC#: 25.125	AFL	7513							
				REF: AFMS INSPECTION E6				PKG:48	
250006 <sup>S</sup>	CHECK FIRST AID KITS							Service	ATA:25
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 25.130	AFL	7513							
				REF: AFMS INSPECTION E6				PKG:48,94	
250007 <sup>S</sup>	OPERATIONAL CHECK CREW SEATS							Service	ATA:25
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 25.145	AFL	7300							
				REF: AFMS INSPECTION B4				PKG:10,91	
250008 <sup>S</sup>	DETAILED CHECK CREW SEATS							Service	ATA:25
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 25.150	AFL	6832							
				REF: AFMS INSPECTION D4				PKG:34,93	
251001	NO. 1 CREW SEAT							Component	ATA:25
PN:3A026-0013-00-2	MOS/MSC	09-Dec-09	O/C						
SN:35123	HRS	6201.1							
WC#: 25.010	AFL	4190							
251002	NO. 2 CREW SEAT							Component	ATA:25
PN:3A026-0014-00-2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:37058	HRS	0		TSN 0					
WC#: 25.010	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>								
<b>251020 THROTTLE BOX Component ATA:25</b>								
PN:25-8CX179-577A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:789	HRS	0		TSN 0				
WC#: 25.020	AFL	0		TSN 0				
<b>2510501.1<sup>U</sup> COCKPIT OBSERVERS SEAT Component ATA:25</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
<b>255006<sup>U</sup> FIRST AID KIT Component ATA:25</b>								
PN:FL220-FAKFAA	MOS/MSC	13-Mar-22	A/R	TSN 0				
SN:0222-2469	HRS	11930.2		TSN 0				
	AFL	7514		TSN 0				
<b>256001 EMERGENCY LOCATOR TRANSMITTER Component ATA:25</b>								
PN:453-5000-999	MOS/MSC	02-Oct-13	O/C					
SN:210-03973	HRS	8133.1						
WC#: 25.025	AFL	5385						
<b>256005 INSPECT EMERGENCY LOCATOR TRANSMITTER Service ATA:25</b>								
PN:453-5000-999	MOS	24-Jan-22	12		31-Jan-23		140 d	
SN:210-03973	HRS	11886						
WC#: 25.025	AFL	7487						
<b>256006 ELT REMOTE (CONTROL UNIT) SWITCH Component ATA:25</b>								
PN:345-6196-04	MOS/MSC	23-Apr-05	O/C					
SN:NSN	HRS	3042.1		TSN 0				
WC#: 25.030	AFL	2090		TSN 0				
<b>256007 REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY Service ATA:25</b>								
PN:452-0133	MOS/MSC	21-Jun-22	DUE		30-Jun-27 <sup>M</sup>		1751 d	
SN:374567-041	HRS	12023.9						
WC#: 25.025	AFL	7567						
<b>256009 EMERGENCY LOCATOR TRANSMITTER ANTENNA Component ATA:25</b>								
PN:110-337	MOS/MSC	23-Apr-05	O/C	TSN 0				
SN:4033826	HRS	3042.1		TSN 0				
WC#: 25.015	AFL	2090		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
256010	FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER							Service	ATA:25
PN:453-5000-999	MOS	24-Jan-22	12		31-Jan-23		140 d		
SN:210-03973	HRS	11886							
WC#: 25.025	AFL	7487							
256013	INSPECT LIFE VESTS							Service	ATA:25
	MOS	24-Jan-22	12		31-Jan-23		140 d		
	HRS	11886							
WC#: 25.040	AFL	7487							
256097	DIGITAL INTERFACE UNIT							Component	ATA:25
PN:920050	MOS/MSC	26-Nov-14	O/C	TSN 0, TSR 0					
SN:1540	HRS	8939.9		TSN 0, TSR 0					
WC#: 25.140	AFL	5812		TSN 0, TSR 0					
256222 <sup>U</sup>	RECERTIFICATION-PASSENGER NO.1 EASTERN AERO MARINE LIFE VEST							Service	ATA:25
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256223 <sup>U</sup>	RECERTIFICATION-PASSENGER NO.2 EASTERN AERO MARINE LIFE VEST							Service	ATA:25
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256224 <sup>U</sup>	RECERTIFICATION-PASSENGER NO.3 EASTERN AERO MARINE LIFE VEST							Service	ATA:25
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256225 <sup>U</sup>	RECERTIFICATION-PASSENGER NO.4 EASTERN AERO MARINE LIFE VEST							Service	ATA:25
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256226 <sup>U</sup>	RECERTIFICATION-PASSENGER NO.5 EASTERN AERO MARINE LIFE VEST							Service	ATA:25
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 25 - EQUIPMENT/FURNISHINGS									
256227 <sup>U</sup>								Service ATA:25	
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256228 <sup>U</sup>								Service ATA:25	
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256229 <sup>U</sup>								Service ATA:25	
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256230 <sup>U</sup>								Service ATA:25	
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256231 <sup>U</sup>								Service ATA:25	
	MOS	16-Feb-18	60		28-Feb-23		168 d		
	HRS								
	AFL								
256301	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component	ATA:25
PN:452-0133	MOS/MSC	30-Jan-18	O/C	TSN 0					
SN:374567-041	HRS	10726		TSN 0					
	AFL	6832		TSN 0					
256310 <sup>U</sup>								Service ATA:25	
	MOS	26-Jan-22	24		31-Jan-24		505 d		
	HRS	11886							
	AFL	7487							
257000 <sup>U</sup>								Service ATA:25	
	MOS	29-Jan-21	36		31-Jan-24		505 d		
	HRS	12023.9							
	AFL	7567							





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
258000 <sup>U</sup> <sup>S</sup>		DOCUMENT RAFT AND RAFT ELT S/N							Service ATA:25
	MOS/MSC	28-Jan-17	- <sup>S</sup>	TAC 1					
	HRS	10500.4		TAC 0					
	AFL	6693		TAC 0					
<b>ATA 26 - FIRE PROTECTION</b>									
260001 <sup>S</sup>		CHECK AFT ENGINE FIRE EXTINGUISHER							Service ATA:26
	MOS	26-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11960.2							
WC#: 26.020	AFL	7530							
				REF: AFMS INSPECTION E1				PKG:43,94	
260001 <sup>S</sup>		CHECK FORWARD ENGINE FIRE EXTINGUISHER							Service ATA:26
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 26.010	AFL	7513							
				REF: AFMS INSPECTION E1				PKG:43,94	
260002 <sup>S</sup>		FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM							Service ATA:26
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 26.035	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
260003		WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C352	MOS	03-Mar-22	12 (+1m/-1m)		03-Mar-23	03-Apr-23	171 d (+31)		
SN:Y23522	HRS								
WC#: 26.080	AFL								
				REF: AFMS INSPECTION E4				PKG:46,94	
260004		WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:C352	MOS	03-Mar-22	12 (+1m/-1m)		31-Mar-23	03-Apr-23	199 d (+3)		
SN:E-72483747	HRS								
WC#: 26.075	AFL								
				REF: AFMS INSPECTION E6				PKG:48,94	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
260005	<b>WEIGHT CHECK AFT ENGINE FIRE EXTINGUISHER</b>							Service	ATA:26
	MOS/MSC	26-Mar-22	N/R						
	HRS	11960.2							
WC#: 26.020	AFL	7530							
				REF: AFMS INSPECTION E7				PKG:49	
260005	<b>WEIGHT CHECK FORWARD ENGINE FIRE EXTINGUISHER</b>							Service	ATA:26
	MOS/MSC	25-Jan-21	N/R						
	HRS								
WC#: 26.010	AFL								
				REF: AFMS INSPECTION E7				PKG:49	
260008	<b>FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)</b>							Service	ATA:26
	MOS	08-Sep-22	6 (+10%)		08-Mar-23	26-Mar-23	176 d (+18)		
	HRS	12086.8							
WC#: 26.115	AFL	7611							
				REF: AFMS OUT OF PHASE INSPECTIONS					
260010 <sup>S</sup>	<b>CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER</b>							Service	ATA:26
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 26.085	AFL	7513							
				REF: AFMS INSPECTION E7, CMM 26-20-02				PKG:49,94	
261030	<b>APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH</b>							Component	ATA:26
PN:17343*/160275-1	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
WC#: 26.120	AFL	0							
261031	<b>APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH</b>							Component	ATA:26
PN:17343*/160275-1	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
WC#: 26.125	AFL	0							
261032	<b>APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH</b>							Component	ATA:26
PN:17343*/160275-1	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
WC#: 26.130	AFL	0							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
<b>261033</b>	<b>APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH</b>							<b>Component</b>	<b>ATA:26</b>
PN:17343*/160275-1	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
WC#: 26.135	AFL	0							
<b>261034</b>	<b>TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH</b>							<b>Service</b>	<b>ATA:26</b>
PN:17343*/160275-1	MOS	03-Dec-21	60		03-Dec-26		1542 d		
SN:UNKNOWN	HRS	11882.7							
WC#: 26.120	AFL	7485							
<b>261035</b>	<b>TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH</b>							<b>Service</b>	<b>ATA:26</b>
PN:17343*/160275-1	MOS	03-Dec-21	60		03-Dec-26		1542 d		
SN:UNKNOWN	HRS	11882.7							
WC#: 26.125	AFL	7485							
<b>261036</b>	<b>TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH</b>							<b>Service</b>	<b>ATA:26</b>
PN:17343*/160275-1	MOS	03-Dec-21	60		03-Dec-26		1542 d		
SN:UNKNOWN	HRS	11882.7							
WC#: 26.130	AFL	7485							
<b>261037</b>	<b>TEST APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH</b>							<b>Service</b>	<b>ATA:26</b>
PN:17343*/160275-1	MOS	03-Dec-21	60		03-Dec-26		1542 d		
SN:UNKNOWN	HRS	11882.7							
WC#: 26.135	AFL	7485							
<b>261074</b>	<b>OVERHEAT DETECTION SWITCHES TEST</b>							<b>Service</b>	<b>ATA:26</b>
	MOS	03-Dec-21	60		03-Dec-26		1542 d		
	HRS	11882.7							
WC#: 26.030	AFL	7485							
<b>261171</b>	<b>NO. 1 ENGINE ZONE 1 FIRE DETECTOR</b>							<b>Component</b>	<b>ATA:26</b>
PN:3001-112-900-400-10	MOS/MSC	28-Jul-06	O/C						
SN:82565	HRS	4029							
WC#: 26.050	AFL	2698							
<b>261172</b>	<b>NO. 2 ENGINE ZONE 1 FIRE DETECTOR</b>							<b>Component</b>	<b>ATA:26</b>
PN:3001-112-900-400-10	MOS/MSC	28-Jul-06	O/C						
SN:82575	HRS	4029							
WC#: 26.055	AFL	2698							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
261183	NO. 1 ENGINE ZONE 2 FIRE DETECTOR							Component	ATA:26
PN:3001-133-900-500-6	MOS/MSC	03-May-13	O/C						
SN:96710	HRS	7758							
WC#: 26.050	AFL	5172							
261184	NO. 2 ENGINE ZONE 2 FIRE DETECTOR							Component	ATA:26
PN:3001-133-900-500-6	MOS/MSC	14-May-15	O/C	TSN 0					
SN:99128	HRS	9230.7		TSN 0					
WC#: 26.055	AFL	5958		TSN 0					
262001	ENGINE FORWARD FIRE EXTINGUISHER							Component	ATA:26
PN:33200009-3	MOS/MSC	02-Oct-13	O/C						
SN:19627C1	HRS	8133.1							
WC#: 26.010	AFL	5385							
262002	ENGINE AFT FIRE EXTINGUISHER							Component	ATA:26
PN:33200009	MOS/MSC	02-Apr-22	O/C	TSO 0					
SN:29311C1	HRS	11960.2		TSO 0					
WC#: 26.020	AFL	7530		TSO 0					
262025	HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER							Service	ATA:26
PN:33200009-3	MOS	26-Sep-13	120		26-Sep-23		378 d		
SN:19627C1	HRS								
WC#: 26.010	AFL								
		HydroCheck Date: : 26-Sep-13							
262026	HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER							Service	ATA:26
PN:33200009	MOS	28-Sep-20	60		28-Sep-25		1111 d		
SN:29311C1	HRS								
WC#: 26.020	AFL								
262027	FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE							Component	ATA:26
PN:30900000M	MOS/MSC	09-Nov-21	O/C	TSN 0					
SN:10159	HRS	11867.6		TSN 0					
WC#: 26.015	AFL	7479		TSN 0					
		REF: GENERIC NO REF							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 26 - FIRE PROTECTION</b>								
<b>262028 AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE</b>								Component ATA:26
PN:30900000M	MOS/MSC	09-Nov-21	O/C	TSN 0				
SN:10180	HRS	11867.6		TSN 0				
WC#: 26.025	AFL	7479		TSN 0				
REF: GENERIC NO REF								
<b>262029 FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE</b>								Component ATA:26
PN:30900000M	MOS/MSC	09-Nov-21	O/C	TSN 0				
SN:10163	HRS	11867.6		TSN 0				
WC#: 26.015	AFL	7479		TSN 0				
REF: GENERIC NO REF								
<b>262030 AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE</b>								Component ATA:26
PN:30900000M	MOS/MSC	09-Nov-21	O/C	TSN 0				
SN:10184	HRS	11867.6		TSN 0				
WC#: 26.025	AFL	7479		TSN 0				
REF: GENERIC NO REF								
<b>262037 REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)</b>								Service ATA:26
PN:30900000M	MOS	09-Nov-21	120		09-Nov-31		3344 d	LIFE LIMIT
SN:10159	HRS							
WC#: 26.015	AFL							
<b>262038 REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)</b>								Service ATA:26
PN:30900000M	MOS	09-Nov-21	120		09-Nov-31		3344 d	LIFE LIMIT
SN:10180	HRS							
WC#: 26.025	AFL							
<b>262049 REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)</b>								Service ATA:26
PN:30900000M	MOS	09-Nov-21	120		09-Nov-31		3344 d	LIFE LIMIT
SN:10163	HRS							
WC#: 26.015	AFL							
<b>262050 REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)</b>								Service ATA:26
PN:30900000M	MOS	09-Nov-21	120		09-Nov-31		3344 d	LIFE LIMIT
SN:10184	HRS							
WC#: 26.025	AFL							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 26 - FIRE PROTECTION</b>								
<b>262061 REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)</b>								
PN:30900000M	MOS	30-Sep-21	180		01-Sep-36 <sup>M</sup>		5102 d	Service ATA:26 LIFE LIMIT
SN:10159	HRS							
WC#: 26.015	AFL							
<b>262062 REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)</b>								
PN:30900000M	MOS	30-Sep-21	180		30-Sep-36		5131 d	Service ATA:26 LIFE LIMIT
SN:10180	HRS							
WC#: 26.025	AFL							
<b>262073 REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)</b>								
PN:30900000M	MOS	30-Sep-21	180		01-Sep-36 <sup>M</sup>		5102 d	Service ATA:26 LIFE LIMIT
SN:10163	HRS							
WC#: 26.015	AFL							
<b>262074 REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)</b>								
PN:30900000M	MOS	30-Sep-21	180		01-Sep-36 <sup>M</sup>		5102 d	Service ATA:26 LIFE LIMIT
SN:10184	HRS							
WC#: 26.025	AFL							
<b>262091 CABIN PORTABLE FIRE EXTINGUISHER</b>								
PN:C352	MOS/MSC	30-Jan-18	O/C	TSN 0				Component ATA:26
SN:E-72483747	HRS	10726		TSN 0				
WC#: 26.075	AFL	6832		TSN 0				
<b>262103 HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER</b>								
PN:C352	MOS	19-Feb-18	144		31-Dec-29 <sup>M</sup>		2666 d	Service ATA:26
SN:E-72483747	HRS							
WC#: 26.075	AFL							
<b>262109 COCKPIT PORTABLE FIRE EXTINGUISHER</b>								
PN:C352	MOS/MSC	30-Jan-18	O/C	TSN 0				Component ATA:26
SN:Y23522	HRS	10726		TSN 0				
WC#: 26.080	AFL	6832		TSN 0				
<b>262121 HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER</b>								
PN:C352	MOS	19-Feb-18	144		31-Jan-30 <sup>M</sup>		2697 d	Service ATA:26
SN:Y23522	HRS							
WC#: 26.080	AFL							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
262125 <sup>U</sup>	MID-HYDROSTATIC MAINTENANCE-COCKPIT FIRE EXTINGUISHER							Service	ATA:26
	MOS/MSC	12-Dec-11	A/R						
	HRS	6951.3							
	AFL	4687							
262127	APU FIRE EXTINGUISHER							Component	ATA:26
PN:4190-1	MOS/MSC	19-Feb-18	O/C						
SN:1839	HRS	10726							
WC#: 26.085	AFL	6832							
262130 <sup>U</sup>	MID-HYDROSTATIC MAINTENANCE-CABIN FIRE EXTINGUISHER							Service	ATA:26
	MOS/MSC	12-Dec-11	A/R						
	HRS	6951.3							
	AFL	4687							
262139	HYDROSTATIC TEST APU FIRE EXTINGUISHER							Service	ATA:26
PN:4190-1	MOS	19-Feb-18	60		28-Feb-23		168 d		
SN:1839	HRS								
WC#: 26.085	AFL								
262143	APU FORWARD CARTRIDGE							Component	ATA:26
PN:30900000M/60-60019	MOS/MSC	11-Jan-16	O/C						
SN:1097	HRS	9692.3							
WC#: 26.060	AFL	6232							
								REF: GENERIC NO REF	
262145	REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:30900000M/60-60019	MOS	31-Dec-15	120		31-Dec-25		1205 d	LIFE LIMIT	
SN:1097	HRS								
WC#: 26.060	AFL								
								Installation Date: : 31-Dec-15 REF: CMM 26-20-02	
262150 <sup>U</sup>	INSPECTION/WEIGHT CHECK-COCKPIT PORTABLE FIRE EXTINGUISHER							Service	ATA:26
	MOS/MSC	09-Sep-21	A/R						
	HRS	11817							
	AFL	7449							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
262151 <sup>U</sup>	INSPECTION/WEIGHT CHECK-CABIN PORTABLE FIRE EXTINGUISHER							Service	ATA:26
	MOS/MSC	09-Sep-21	A/R						
	HRS	11817							
	AFL	7449							
262157	REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:30900000M/60-60019	MOS	31-Dec-15	180		31-Dec-30		3031 d	LIFE LIMIT	
SN:1097	HRS			TAC 0					
WC#: 26.060	AFL			TAC 0					
		Manufacture Date:: 31-Dec-15		REF: CMM 26-20-02					
262190	FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE							Component	ATA:26
PN:A1003(1)	MOS/MSC	14-Aug-20	O/C	TSN 0					
SN:NSN	HRS	11060.4		TSN 0					
WC#: 26.100	AFL	7036		TSN 0					
				REF: GENERIC NO REF					
262195	AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE							Component	ATA:26
PN:A1003(1)	MOS/MSC	14-Aug-20	O/C	TSN 0					
SN:NSN	HRS	11060.4		TSN 0					
WC#: 26.105	AFL	7036		TSN 0					
				REF: GENERIC NO REF					
262199	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:A1003(1)	MOS		48		14-Aug-23 <sup>M</sup>		335 d	LIFE LIMIT	
SN:NSN	HRS								
WC#: 26.100	AFL								
262200	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)							Service	ATA:26
PN:A1003(1)	MOS		48		14-Aug-23 <sup>M</sup>		335 d	LIFE LIMIT	
SN:NSN	HRS								
WC#: 26.105	AFL								
262201	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:A1003(1)	MOS	14-Aug-20	36		14-Aug-23		335 d	LIFE LIMIT	
SN:NSN	HRS								
WC#: 26.100	AFL								





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
262202	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)							Service	ATA:26
PN:A1003(1)	MOS	14-Aug-20	36		14-Aug-23		335 d	LIFE LIMIT	
SN:NSN	HRS								
WC#: 26.105	AFL								
262301	SMOKE DETECTOR AMPLIFIER							Component	ATA:26
PN:30-326-7	MOS/MSC	19-Jul-01	O/C						
SN:3144	HRS	0		TSN 0					
WC#: 26.070	AFL	0		TSN 0					
<b>ATA 27 - FLIGHT CONTROLS</b>									
270002 <sup>S</sup>	INSPECT LEFT WING FLAP VANE INNER							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.490	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270003 <sup>S</sup>	INSPECT LEFT WING FLAP SCREWJACKS SCREW THREADS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.495	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270004 <sup>S</sup>	FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.120	AFL	7300							
				REF: AFMS INSPECTION B2				PKG:8,91	
270008 <sup>S</sup>	FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.060	AFL	7300							
				REF: AFMS INSPECTION B2				PKG:8,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270009 <sup>S</sup>	FUNCTIONAL TEST STALL DETECTOR UNIT (THIRD CHANNEL)							Service	ATA:27
	MOS	03-May-21							
	HRS	11562	800 <sup>S</sup> (+40/-10)						
WC#: 27.110	AFL	7300							
				REF: AFMS INSPECTION B2				PKG:8,91	
270011 <sup>S</sup>	INSPECT GUST LOCKS/AILERONS AND ELEVATORS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.415	AFL	7300							
				REF: AFMS INSPECTION B4				PKG:10,91	
270012 <sup>S</sup>	CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.450	AFL	7300							
				REF: AFMS INSPECTION B8				PKG:14,91	
270013 <sup>S</sup>	CHECK AND INSPECT ELEVATORS AND TRIM TABS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.485	AFL	7300							
				REF: AFMS INSPECTION B8				PKG:14,91	
270014 <sup>S</sup>	INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.420	AFL	7300							
				REF: AFMS INSPECTION B8				PKG:14,91	
270015 <sup>S</sup>	OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.425	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270016 <sup>S</sup>			CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.435	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270017 <sup>S</sup>			CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.500	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270018 <sup>S</sup>			INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.550	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270019 <sup>S</sup>			CHECK FLAP CONTROL UNIT					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.525	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270020 <sup>S</sup>			OPERATE FLAP CONTROL UNIT					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.520	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	
270021 <sup>S</sup>			INSPECT LEFT FLAP DRIVE SHAFTS					Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.510	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270022 <sup>S</sup>	OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.425	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270023 <sup>S</sup>	CHECK AND INSPECT RIGHT AILERON SERVO TABS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.435	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270024 <sup>S</sup>	CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.500	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270025 <sup>S</sup>	INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.550	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270026 <sup>S</sup>	INSPECT RIGHT FLAP DRIVE SHAFTS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.510	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270027 <sup>S</sup>	FUNCTIONAL TEST FLAP CONTROL SYSTEM							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.200	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270028 <sup>S</sup>	FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.260	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
270030 <sup>S</sup>	CHECK ELEVATOR TRIM SERVO							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.095	AFL	6832							
				REF: AFMS INSPECTION C2				PKG:20,92	
270032 <sup>S</sup>	CHECK AILERON AUTOPILOT SERVO CONTROL CABLES							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.440	AFL	6832							
				REF: AFMS INSPECTION C4				PKG:22,92	
270033 <sup>S</sup>	INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.100	AFL	6832							
				REF: AFMS INSPECTION C4				PKG:22,92	
270034 <sup>S</sup>	CHECK ELEVATOR PRIMARY CONTROL CABLES							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.460	AFL	6832							
				REF: AFMS INSPECTION C5				PKG:23,92	
270035 <sup>S</sup>	CHECK FLAP CONTROL CABLES							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.540	AFL	6832							
				REF: AFMS INSPECTION C5				PKG:23,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270036 <sup>S</sup>			CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.465	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	
270037 <sup>S</sup>			CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.455	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	
270038 <sup>S</sup>			CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.475	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	
270039 <sup>S</sup>			CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.445	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	
270040 <sup>S</sup>			CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.480	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	
270041 <sup>S</sup>			INSPECT ELEVATOR TRIM CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.470	AFL	6832							
					REF: AFMS INSPECTION C8			PKG:26,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270042 <sup>S</sup>			CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.430	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270043 <sup>S</sup>			INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.565	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270044 <sup>S</sup>			CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.535	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270045 <sup>S</sup>			CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.515	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270046 <sup>S</sup>			CHECK FLAP/AIRBRAKE BAULK BOBBIN					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.575	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
270047 <sup>S</sup>			CHECK FLAP SPRING DRUM PULLEY-LEVER					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.555	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270048 <sup>S</sup>			CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.505	AFL	6832							
					REF: AFMS INSPECTION C9			PKG:27,92	
270049 <sup>S</sup>			CHECK LEFT FLAP SYNCHRONIZING SYSTEM					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.530	AFL	6832							
					REF: AFMS INSPECTION C9			PKG:27,92	
270050 <sup>S</sup>			CHECK LEFT AIRBRAKE CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.570	AFL	6832							
					REF: AFMS INSPECTION C9			PKG:27,92	
270051 <sup>S</sup>			CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.430	AFL	6832							
					REF: AFMS INSPECTION C10			PKG:28,92	
270052 <sup>S</sup>			INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.565	AFL	6832							
					REF: AFMS INSPECTION C10			PKG:28,92	
270053 <sup>S</sup>			CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY					Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.535	AFL	6832							
					REF: AFMS INSPECTION C10			PKG:28,92	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
270054 <sup>S</sup>			CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX					Service ATA:27
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 27.505	AFL	6832						
					REF: AFMS INSPECTION C10			PKG:28,92
270055 <sup>S</sup>			CHECK RIGHT FLAP SYNCHRONIZING SYSTEM					Service ATA:27
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 27.530	AFL	6832						
					REF: AFMS INSPECTION C10			PKG:28,92
270056 <sup>S</sup>			CHECK RIGHT AIRBRAKE CONTROL CABLES					Service ATA:27
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 27.570	AFL	6832						
					REF: AFMS INSPECTION C10			PKG:28,92
270057 <sup>S</sup>			CHECK FLAP CONTROL FORWARD SPRING STRUT					Service ATA:27
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 27.560	AFL	6832						
					REF: AFMS INSPECTION D4			PKG:34,93
270058 <sup>S</sup>			CHECK FLAP CONTROL INPUT-CIRCUIT					Service ATA:27
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 27.210	AFL	6832						
					REF: AFMS INSPECTION D4			PKG:34,93
270059 <sup>S</sup>			INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD					Service ATA:27
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)					
	HRS	11930.2						
WC#: 27.545	AFL	7513						
					REF: AFMS INSPECTION E7			PKG:49,94



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270060 <sup>S</sup>	REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 27.215	AFL	6832							
				REF: AFMS INSPECTION D10				PKG:40,93	
270061	CHECK FLIGHT CONTROL CABLES TENSION							Service	ATA:27
	MOS/MSC	25-Oct-11	O/C						
	HRS								
WC#: 27.010	AFL								
				REF: AFMS OUT OF PHASE INSPECTIONS					
270063	LUBRICATE/CLEAN SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)							Service	ATA:27
	MOS/MSC	19-Jul-01	C/C						
	HRS	0							
WC#: 27.030	AFL	0							
				REF: AFMS OUT OF PHASE INSPECTIONS					
270064 <sup>S</sup>	INSPECT RIGHT WING FLAP VANE INNER							Service	ATA:27
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 27.490	AFL	6832							
				REF: AFMS INSPECTION C10				PKG:28,92	
270065 <sup>S</sup>	INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.495	AFL	7300							
				REF: AFMS INSPECTION B10				PKG:16,91	
270066 <sup>S</sup>	INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS							Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.600	AFL	7300							
				REF: AFMS INSPECTION B9				PKG:15,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270067 <sup>S</sup>		INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS						Service	ATA:27
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 27.605	AFL	7300							
					REF: AFMS INSPECTION B10			PKG:16,91	
270068 <sup>S</sup>		LUBRICATE/CLEAN AILERON SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 27.610	AFL	7567							
					REF: AFMS INSPECTION G			PKG:96	
270069 <sup>S</sup>		LUBRICATE/CLEAN ELEVATOR SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 27.615	AFL	7567							
					REF: AFMS INSPECTION G			PKG:96	
270070 <sup>S</sup>		LUBRICATE/CLEAN RUDDER SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)						Service	ATA:27
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 27.620	AFL	7567							
					REF: AFMS INSPECTION G			PKG:96	
270071 <sup>S</sup>		INSPECT RUDDER TRIM JACK						Service	ATA:27
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 27.700	AFL	7567							
					REF: AFMS INSPECTION G			PKG:96	
270072 <sup>S</sup>		INSPECT ELEVATOR TRIM JACK						Service	ATA:27
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 27.700	AFL	7567							
					REF: AFMS INSPECTION G			PKG:96	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>270100 LEFT CONTROL COLUMN</b> Component ATA:27								
PN:25-8CF53-217	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:PPLS/DH/1541	HRS	0		TSN 0				
WC#: 27.015	AFL	0		TSN 0				
<b>270102 RIGHT CONTROL COLUMN</b> Component ATA:27								
PN:25-8CF55-215	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:PPLS/DH/1558	HRS	0		TSN 0				
WC#: 27.015	AFL	0		TSN 0				
<b>271001 LEFTAILERON</b> Component ATA:27								
PN:25-9WG1-111A	MOS/MSC	30-Jan-18	O/C					
SN:DHB1265	HRS	10726						
WC#: 27.020	AFL	6832						
<b>271025 AILERON TRIM SCREWJACK</b> Component ATA:27								
PN:25-8CW49-39A	MOS/MSC	30-Jan-18	O/C					
SN:DHB573	HRS	10726						
WC#: 27.025	AFL	6832						
<b>272001 RUDDER</b> Component ATA:27								
PN:25-8TR105-11A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FL/DHB/8537	HRS	0		TSN 0				
WC#: 27.045	AFL	0		TSN 0				
<b>272019 RUDDER TRIM JACK</b> Component ATA:27								
PN:25CW573AG	MOS/MSC	02-Oct-13	O/C	TSO 0				
SN:MEC/DHB/2036	HRS	8133.1		TSO 0				
WC#: 27.050	AFL	5385		TSO 0				
<b>272020 RUDDER GEARED TAB</b> Component ATA:27								
PN:25TR209AF	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FL/DHB/8565A	HRS	0		TSN 0				
WC#: 27.125	AFL	0		TSN 0				
<b>272021 RUDDER TRIM TAB</b> Component ATA:27								
PN:25TR221AF	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FL/DHB/8580A	HRS	0		TSN 0				
WC#: 27.285	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
<b>272022</b>		<b>LEFT RUDDER PEDAL ASSEMBLY</b>					<b>Component ATA:27</b>		
PN:25-8CF549-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:CML/DHB/365	HRS	0	TSN 0						
WC#: 27.065	AFL	0	TSN 0						
<b>272023</b>		<b>RIGHT RUDDER PEDAL ASSEMBLY</b>					<b>Component ATA:27</b>		
PN:25-CW573A/G	MOS/MSC	19-Feb-18	O/C	TSN 0					
SN:MEC/DHB/1130	HRS	10726	TSN 0						
WC#: 27.065	AFL	6832	TSN 0						
<b>272049</b>		<b>LEFT RUDDER BIAS STRUT</b>					<b>Component ATA:27</b>		
PN:ACA1218	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:EGH037	HRS	0	TSN 0						
WC#: 27.055	AFL	0	TSN 0						
<b>272050</b>		<b>RIGHT RUDDER BIAS STRUT</b>					<b>Component ATA:27</b>		
PN:ACA1218	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:EGH039	HRS	0	TSN 0						
WC#: 27.055	AFL	0	TSN 0						
<b>2720503<sup>U</sup></b>		<b>LEFT RUDDER BIAS STRUT</b>					<b>Component ATA:27</b>		
PN:ACA1218	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:EGH037	HRS	0	TSN 0						
	AFL	0	TSN 0						
<b>2720504<sup>U</sup></b>		<b>RIGHT RUDDER BIAS STRUT</b>					<b>Component ATA:27</b>		
PN:ACA1218	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:EGH039	HRS	0	TSN 0						
	AFL	0	TSN 0						
<b>272066</b>		<b>LEFT RUDDER BIAS STRUT HEATER MUFF</b>					<b>Component ATA:27</b>		
PN:259W03486-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1159	HRS	0	TSN 0						
WC#: 27.060	AFL	0	TSN 0						
<b>272067</b>		<b>RIGHT RUDDER BIAS STRUT HEATER MUFF</b>					<b>Component ATA:27</b>		
PN:259W03486-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1146	HRS	0	TSN 0						
WC#: 27.061	AFL	0	TSN 0						



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>272103 LEFT RUDDER BIAS PRESSURE SWITCH Component ATA:27</b>								
PN:THE690011	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:20303	HRS	0		TSN 0				
WC#: 27.290	AFL	0		TSN 0				
<b>272105 RIGHT RUDDER BIAS PRESSURE SWITCH Component ATA:27</b>								
PN:THE690011	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:20299	HRS	0		TSN 0				
WC#: 27.290	AFL	0		TSN 0				
<b>273021 ELEVATOR TRIM SERVOMOTOR Component ATA:27</b>								
PN:622-3260-001	MOS	02-Apr-22		TSO 0				OVERHAUL
SN:545	HRS	11960.2	3500	TSO 0	15460.2		3373	
WC#: 27.085	AFL	7530		TSO 0				
<b>273025 LEFT ELEVATOR TRIM JACK Component ATA:27</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.080	AFL	0		TSN 0				
<b>273026 RIGHT ELEVATOR TRIM JACK Component ATA:27</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.080	AFL	0		TSN 0				
<b>273104 LEFT STICK SHAKER Component ATA:27</b>								
PN:B1443-2	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8806	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
<b>273105 RIGHT STICK SHAKER Component ATA:27</b>								
PN:B1443-2	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8802	HRS	0		TSN 0				
WC#: 27.140	AFL	0		TSN 0				
<b>273110 FORWARD STALL WARNING DETECTOR Component ATA:27</b>								
PN:C87706-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:019	HRS	0		TSN 0				
WC#: 27.145	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>273111 AFT STALL WARNING DETECTOR</b> Component ATA:27								
PN:C87706-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:650	HRS	0		TSN 0				
WC#: 27.145	AFL	0		TSN 0				
<b>273115 NO. 1 STALL WARNING VANE</b> Component ATA:27								
PN:1703-12	MOS/MSC	04-Nov-05	O/C					
SN:1424	HRS	3471						
WC#: 27.150	AFL	2346						
<b>273116 NO. 2 STALL WARNING VANE</b> Component ATA:27								
PN:1703-12	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:2006	HRS	0		TSN 0				
WC#: 27.150	AFL	0		TSN 0				
<b>273121 THIRD CHANNEL STALL DETECTOR</b> Component ATA:27								
PN:10201-1	MOS/MSC	29-Jan-16	O/C	TSO 1				
SN:F089	HRS	9692.3		TSO 0				
WC#: 27.305	AFL	6232		TSO 0				
<b>275001 LEFT FLAP</b> Component ATA:27								
PN:25-8WF251-1A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:SD/DH/767	HRS	0		TSN 0				
WC#: 27.155	AFL	0		TSN 0				
<b>275002 RIGHT FLAP</b> Component ATA:27								
PN:25-8WF25-2	MOS/MSC	14-Jan-08	O/C					
SN:UNKNOWN	HRS	5224						
WC#: 27.155	AFL	3495						
<b>275025 LEFT FLAP SCREWJACK AND REDUCTION GEARBOX</b> Component ATA:27								
PN:25-8CW159AC	MOS	27-Sep-20		TSO 0				OVERHAUL
SN:MEH/DHB/426	HRS	11155.3		TSO 0				
WC#: 27.160	AFL	7076	4000	TSO 0	11076		3463	
<b>275026 RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX</b> Component ATA:27								
PN:25-8CW161	MOS	25-Oct-11		TSN 0				OVERHAUL
SN:BPED/R/DHB035	HRS							
WC#: 27.160	AFL	3971	4000	TSN 0	7971		358	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>275049 LEFT OUTBOARD FLAP VANE</b> Component ATA:27								
PN:25-8WF13-65A	MOS/MSC	26-Apr-11	O/C					
SN:SD-DH-877	HRS	6861						
WC#: 27.165	AFL	4622						
<b>275050 RIGHT OUTBOARD FLAP VANE</b> Component ATA:27								
PN:25-8WF13-66A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:SD/DH/930	HRS	0		TSN 0				
WC#: 27.170	AFL	0		TSN 0				
<b>275051 LEFT INBOARD FLAP VANE</b> Component ATA:27								
PN:25-7WF101A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:SD/DH/813	HRS	0		TSN 0				
WC#: 27.165	AFL	0		TSN 0				
<b>275052 RIGHT INBOARD FLAP VANE</b> Component ATA:27								
PN:25-7WF102A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:SD/DH/944	HRS	0		TSN 0				
WC#: 27.170	AFL	0		TSN 0				
<b>275057 LEFT FLAP BEVEL SHAFT ASSEMBLY</b> Component ATA:27								
PN:25CF2667AD	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:MEC/DHB/1074	HRS	0		TSN 0				
WC#: 27.175	AFL	0		TSN 0				
<b>275058 RIGHT FLAP BEVEL SHAFT ASSEMBLY</b> Component ATA:27								
PN:25CF2668AD	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:MEC/DHB/1078	HRS	0		TSN 0				
WC#: 27.175	AFL	0		TSN 0				
<b>275073 FLAP CONTROL UNIT</b> Component ATA:27 OVERHAUL								
PN:614MK2	MOS	05-Jul-22		TSO 0				
SN:1581	HRS	12024.9		TSO 0				
WC#: 27.180	AFL	7568	6000	TSO 0	13568		5955	
<b>275074 FLAP DESIGN UNIT</b> Component ATA:27								
PN:25-8NW111-1A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:83111	HRS	0		TSN 0				
WC#: 27.590	AFL	0		TSN 0				





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>275085 FLAP SYNCHRONIZING SYSTEM RECEIVER</b> Component ATA:27								
PN:CHA617-104	MOS	25-Oct-11		TSN 0				OVERHAUL
SN:1168	HRS							
WC#: 27.185	AFL	4330	4500	TSN 0	8830		1217	
<b>275091 FLAP POSITION INDICATOR</b> Component ATA:27								
PN:2132-01-0011	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:852301	HRS	0		TSN 0				
WC#: 27.190	AFL	0		TSN 0				
<b>275097 FLAP POSITION TRANSMITTER</b> Component ATA:27								
PN:S132-3-22	MOS/MSC	31-Dec-10	O/C					
SN:83055	HRS	6756.4						
WC#: 27.195	AFL	4547						
<b>275145 LEFT FLAP INBOARD FORWARD SYNCHRO CABLE</b> Component ATA:27								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.220	AFL	4999	5000	TSN 0	9999		2386	
<b>275146 RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE</b> Component ATA:27								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.225	AFL	4999	5000	TSN 0	9999		2386	
<b>275147 LEFT FLAP INBOARD AFT SYNCHRO CABLE</b> Component ATA:27								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.220	AFL	4999	5000	TSN 0	9999		2386	
<b>275148 RIGHT FLAP INBOARD AFT SYNCHRO CABLE</b> Component ATA:27								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.225	AFL	4999	5000	TSN 0	9999		2386	
<b>275149 LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE</b> Component ATA:27								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.230	AFL	4999	5000	TSN 0	9999		2386	



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 27 - FLIGHT CONTROLS</b>								
<b>275150 RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE</b>								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				Component ATA:27 LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.235	AFL	4999	5000	TSN 0	9999		2386	
<b>275151 LEFT FLAP OUTBOARD AFT SYNCHRO CABLE</b>								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				Component ATA:27 LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.230	AFL	4999	5000	TSN 0	9999		2386	
<b>275152 RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE</b>								
PN:PN-UNKNOWN	MOS	03-Nov-12		TSN 0				Component ATA:27 LIFE LIMIT
SN:UNKNOWN	HRS	7475		TSN 0				
WC#: 27.235	AFL	4999	5000	TSN 0	9999		2386	
<b>276001 LEFT UPPER AIRBRAKE</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					Component ATA:27
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.240	AFL	0		TSN 0				
<b>276002 RIGHT UPPER AIRBRAKE</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					Component ATA:27
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
<b>276003 LEFT LOWER AIRBRAKE</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					Component ATA:27
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.240	AFL	0		TSN 0				
<b>276004 RIGHT LOWER AIRBRAKE</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					Component ATA:27
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 27.245	AFL	0		TSN 0				
<b>276039 LEFT AIRBRAKE JACK ASSEMBLY</b>								
PN:AIR46520/2	MOS	22-Aug-14						Component ATA:27 OVERHAUL
SN:APB972253	HRS	8939.9	3000	TSO 0, Adj 300	12239.9		152.7	
WC#: 27.250	AFL	5812		TSO 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
276040	RIGHT AIRBRAKE JACK ASSEMBLY							Component	ATA:27
PN: AIR46521-2	MOS	25-Sep-21						OVERHAUL	
SN: LK0359	HRS	11828	3000	TSO 0	14828		2740.8		
WC#: 27.255	AFL	7454		TSO 0					
276051	LEFT AIRBRAKE JACK BODY							Component	ATA:27
PN: AIR111462	MOS	24-Nov-14		TSN 3				LIFE LIMIT	
SN: N2992	HRS	8939.9							
WC#: 27.250	AFL	5812	25000	TSN 3538	27274		19661		
276052	RIGHT AIRBRAKE JACK BODY							Component	ATA:27
PN: AIR46521/2	MOS	06-Sep-14		TSO 0				LIFE LIMIT	
SN: LK0359	HRS	8860.6		TSO 0					
WC#: 27.255	AFL	5752	25000	TSN 4078, TSO 0	26674		19061		
276110	STICK PUSHER							Component	ATA:27
PN: 104829001	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: CWDD/DH/12/01	HRS	0		TSN 0					
WC#: 27.585	AFL	0		TSN 0					
<b>ATA 28 - FUEL</b>									
280001 <sup>S</sup>	FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS							Service	ATA:28
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 28.075	AFL	7300							
				REF: AFMS INSPECTION B1				PKG:7,91	
280002 <sup>S</sup>	CHECK FUEL VALVE CONTROL CABLES							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 28.010	AFL	6832							
				REF: AFMS INSPECTION C5				PKG:23,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
280003 <sup>S</sup>	FUNCTIONAL TEST LP VALVES							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 28.050	AFL	6832							
				REF: AFMS INSPECTION D1				PKG:31,93	
280004 <sup>S</sup>	INSPECT/CLEAN OR REPLACE APU FUEL INLET FILTER ELEMENT (IF FITTED)							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 28.085	AFL	6832							
				REF: AFMS INSPECTION D7				PKG:37,93	
280005 <sup>S</sup>	VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 28.165	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
280006 <sup>S</sup>	VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 28.170	AFL	6832							
				REF: AFMS INSPECTION C9				PKG:27,92	
280007 <sup>S</sup>	VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 28.165	AFL	6832							
				REF: AFMS INSPECTION C10				PKG:28,92	
280008 <sup>S</sup>	VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS							Service	ATA:28
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 28.170	AFL	6832							
				REF: AFMS INSPECTION C10				PKG:28,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
280010	CHECK CABLE TENSION OF FUEL CONTROL VALVES							Service	ATA:28
	MOS/MSC	25-Oct-11	O/C						
	HRS								
WC#: 28.020	AFL								
REF: AFMS OUT OF PHASE INSPECTIONS									
280016 <sup>S</sup>	VISUAL INSPECTION LOW PRESSURE FUEL VALVE SUPPORT STRUT. PART NO. 25 PF361, 25 PF361-5A (MOD. 25G310A) AND 25 PF363							Service	ATA:28
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 28.195	AFL	7567							
REF: AFMS INSPECTION G									
281067	VENTRAL FUEL TANK							Component	ATA:28
PN:25-8PT463-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:SD/DH/341	HRS	0		TSN 0					
WC#: 28.015	AFL	0		TSN 0					
282001	LEFT WING HIGH LEVEL FLOAT SWITCH							Component	ATA:28
PN:3515000-107	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FRTR1022BE	HRS	0		TSN 0					
WC#: 28.025	AFL	0		TSN 0					
282002	RIGHT WING HIGH LEVEL FLOAT SWITCH							Component	ATA:28
PN:3515000-107	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FRTR1027BE	HRS	0		TSN 0					
WC#: 28.025	AFL	0		TSN 0					
282005	LEFT FUEL COCK							Component	ATA:28
PN:7913003K	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR299BE	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
REF: GENERIC NO REF									
282006	RIGHT FUEL COCK							Component	ATA:28
PN:7913003K	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR301BE	HRS	0		TSN 0					
WC#: 28.180	AFL	0		TSN 0					
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
<b>282008</b>	<b>RIGHT FUEL ACTUATOR</b>							<b>Component</b>	<b>ATA:28</b>
PN:HTE9044-001	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:M503GB0600	HRS	0		TSN 0					
WC#: 28.185	AFL	0		TSN 0					
REF: GENERIC NO REF									
<b>282009</b>	<b>LEFT FUEL NON-RETURN VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:9807870	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR007BE	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
<b>282010</b>	<b>RIGHT FUEL NON-RETURN VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:9807870	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR012BE	HRS	0		TSN 0					
WC#: 28.190	AFL	0		TSN 0					
<b>2820507<sup>U</sup></b>	<b>LEFT FUEL BOOSTER PUMP</b>							<b>Component</b>	<b>ATA:28</b>
PN:2C40-2	MOS/MSC	19-Jul-01	O/C						
SN:3AU28	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>2820508<sup>U</sup></b>	<b>RIGHT FUEL BOOSTER PUMP</b>							<b>Component</b>	<b>ATA:28</b>
PN:2C40-2	MOS/MSC	21-Nov-05	O/C						
SN:8BA148	HRS	3496.2		TSO 0					
	AFL	2363		TSO 0					
<b>2820518<sup>U</sup></b>	<b>LEFT LP FUEL VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:HTE1984	MOS/MSC	19-Jul-01	O/C						
SN:FR136BE	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>2820519<sup>U</sup></b>	<b>RIGHT LP FUEL VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:HTE1984	MOS/MSC	19-Jul-01	O/C						
SN:FR126BE	HRS	0		TSN 0					
	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
282253	LEFT HAND LP FUEL VALVE							Component	ATA:28
PN:HTE1984	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR136BE	HRS	0	TSN 0						
WC#: 28.045	AFL	0	TSN 0						
282254	RIGHT HAND LP FUEL VALVE							Component	ATA:28
PN:HTE1984	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR126BE	HRS	0	TSN 0						
WC#: 28.045	AFL	0	TSN 0						
282289	FUEL 3C VALVE							Component	ATA:28
PN:HTE1984	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR133BE	HRS	0	TSN 0						
WC#: 28.055	AFL	0	TSN 0						
282295	FUEL 4S VALVE							Component	ATA:28
PN:HTE1984	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR131BE	HRS	0	TSN 0						
WC#: 28.060	AFL	0	TSN 0						
282343	LEFT BOOST PUMP							Component	ATA:28
PN:2C40-2	MOS/MSC	19-Feb-18	O/C						
SN:3AU28	HRS	10726	TSN 11867.6						
WC#: 28.080	AFL	6832	TSN 7479						
282344	RIGHT BOOST PUMP							Component	ATA:28
PN:2C40-2	MOS/MSC	19-Feb-18	O/C						
SN:8BA148	HRS	10726	TSN 3496						
WC#: 28.080	AFL	6832	TSN 2363						
282384	SINGLE-POINT PRESSURE CONTROL VALVE							Component	ATA:28
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0	TSN 0						
WC#: 28.175	AFL	0	TSN 0						
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
284013	LEFT NO. 1 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU04	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:8275	HRS	0		TSN 0					
WC#: 28.100	AFL	0		TSN 0					
284014	RIGHT NO.1 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU04	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:8279	HRS	0		TSN 0					
WC#: 28.100	AFL	0		TSN 0					
284015	LEFT NO.2 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9839	HRS	0		TSN 0					
WC#: 28.105	AFL	0		TSN 0					
284016	RIGHT NO.2 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9838	HRS	0		TSN 0					
WC#: 28.105	AFL	0		TSN 0					
284017	LEFT NO.3 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU3	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9639	HRS	0		TSN 0					
WC#: 28.110	AFL	0		TSN 0					
284018	RIGHT NO.3 FUEL TANK UNIT							Component	ATA:28
PN:0207KTU3	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9638	HRS	0		TSN 0					
WC#: 28.110	AFL	0		TSN 0					
284019	LEFT NO.4 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU4	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1985	HRS	0		TSN 0					
WC#: 28.115	AFL	0		TSN 0					
284020	RIGHT NO.4 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU4	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1983	HRS	0		TSN 0					
WC#: 28.115	AFL	0		TSN 0					





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
284021	LEFT NO.5 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU5	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:10220	HRS	0		TSN 0					
WC#: 28.120	AFL	0		TSN 0					
284022	RIGHT NO.5 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU5	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:10214	HRS	0		TSN 0					
WC#: 28.120	AFL	0		TSN 0					
284023	LEFT NO.6 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU6	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9984	HRS	0		TSN 0					
WC#: 28.125	AFL	0		TSN 0					
284024	RIGHT NO.6 FUEL TANK UNIT							Component	ATA:28
PN:0204KTU6	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9992	HRS	0		TSN 0					
WC#: 28.125	AFL	0		TSN 0					
284025	LEFT NO.7 FUEL TANK CONTENTS UNIT							Component	ATA:28
PN:0204KTU7	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9809	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
284026	RIGHT NO.7 FUEL TANK CONTENTS UNIT							Component	ATA:28
PN:0204KTU7	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9805	HRS	0		TSN 0					
WC#: 28.130	AFL	0		TSN 0					
284115	LEFT FUEL QUANTITY INDICATOR							Component	ATA:28
PN:WL1901KID1	MOS/MSC	01-Feb-06	O/C						
SN:011171	HRS	3671							
WC#: 28.140	AFL	2479							
284116	RIGHT FUEL QUANTITY INDICATOR							Component	ATA:28
PN:WL1901KID1	MOS/MSC	01-Feb-06	O/C						
SN:011218	HRS	3671							
WC#: 28.140	AFL	2479							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
284139	VENTRAL TANK LOW LEVEL FLOAT SWITCH							Component	ATA:28
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.145	AFL	0		TSN 0					
284151	LEFT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR967BE	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
2841510 <sup>U</sup>	LEFT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	19-Jul-01	O/C						
SN:FR967BE	HRS	0		TSN 0					
	AFL	0		TSN 0					
2841510.1 <sup>U</sup>	RIGHT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	19-Jul-01	O/C						
SN:FR966BE	HRS	0		TSN 0					
	AFL	0		TSN 0					
284152	RIGHT SURGE TANK FLOAT SWITCH							Component	ATA:28
PN:3515000-106	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FR966BE	HRS	0		TSN 0					
WC#: 28.155	AFL	0		TSN 0					
<b>ATA 29 - HYDRAULIC POWER</b>									
290003 <sup>S</sup>	REPLACE HYDRAULIC SUCTION FILTER ELEMENT							Service	ATA:29
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 29.070	AFL	7300							
				REF: AFMS INSPECTION B7				PKG:13,91	
290004 <sup>S</sup>	FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM							Service	ATA:29
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 29.075	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 29 - HYDRAULIC POWER</b>									
290005 <sup>S</sup>	OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM							Service	ATA:29
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 29.115	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
290006 <sup>S</sup>	DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM							Service	ATA:29
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 29.160	AFL	6832							
				REF: AFMS INSPECTION C7				PKG:25,92	
290007 <sup>S</sup>	TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING							Service	ATA:29
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 29.165	AFL	6832							
				REF: AFMS INSPECTION C12				PKG:30,92	
290008 <sup>S</sup>	CHECK EMERGENCY BRAKE SYSTEM LEAK RATE							Service	ATA:29
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 29.175	AFL	6832							
				REF: AFMS INSPECTION C12				PKG:30,92	
290009 <sup>S</sup>	FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM							Service	ATA:29
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 29.180	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
290010 <sup>S</sup>	FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM							Service	ATA:29
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 29.170	AFL	6832							
				REF: AFMS INSPECTION C12				PKG:30,92	



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 29 - HYDRAULIC POWER</b>								
<b>290011<sup>S</sup> CLEAN FULL-FLOW RELIEF VALVE Service ATA:29</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 29.005	AFL	6832						
				REF: AFMS INSPECTION D7				PKG:37,93
<b>290012<sup>S</sup> INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM Service ATA:29</b>								
	MOS	19-Feb-18						
	HRS	10726	3200 <sup>S</sup> (+150/-50)					
WC#: 29.145	AFL	6832						
				REF: AFMS INSPECTION D7				PKG:37,93
<b>291018 PRESSURE REGULATOR VALVE Component ATA:29</b>								
PN:NPAS129-163	MOS/MSC	04-Dec-01	O/C					
SN:UR154	HRS	64						
WC#: 29.010	AFL	48						
<b>291018-U1<sup>U</sup> PRESSURE REGULATOR VALVE Component ATA:29</b>								
PN:NPAS129-163	MOS/MSC	04-Dec-01	O/C					
SN:UR154	HRS	64.3		TSN 0				
	AFL	48		TSN 0				
<b>291025 NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE Component ATA:29</b>								
PN:AIR87240-0	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:APB002939	HRS	0		TSN 0				
WC#: 29.015	AFL	0		TSN 0				
<b>291037 LEFT HYDRAULIC SUCTION VALVE Component ATA:29</b>								
PN:7907015E	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FR072BE	HRS	0		TSN 0				
WC#: 29.020	AFL	0		TSN 0				
<b>291038 RIGHT HYDRAULIC SUCTION VALVE Component ATA:29</b>								
PN:7907015E	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FR076BE	HRS	0		TSN 0				
WC#: 29.020	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 29 - HYDRAULIC POWER</b>								
<b>291049 NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE</b>								
PN: AIR45394	MOS	25-Oct-11						Component ATA:29 OVERHAUL
SN: APB001600	HRS							
WC#: 29.025	AFL	4330	4500		8830 <sup>M</sup>		1217	
<b>291050 NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE</b>								
PN: AIR45394	MOS	25-Oct-11						Component ATA:29 OVERHAUL
SN: LK8908846	HRS							
WC#: 29.025	AFL	4330	4500		8830 <sup>M</sup>		1217	
<b>291051<sup>U</sup> CTR NON RETURN VALVE</b>								
PN: AIR48026-0	MOS/MSC	19-Jul-01	O/C					Component ATA:29
SN: APB010624	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>291051<sup>U</sup> NON-RETURN VALVE</b>								
PN: AIR87240-0	MOS/MSC	19-Jul-01	O/C					Component ATA:29
SN: APB002939	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>291061 NO. 1 DUNLOP VALVE</b>								
PN: AC69536	MOS/MSC	19-Jul-01	O/C					Component ATA:29
SN: Efy204	HRS	0		TSN 0				
WC#: 29.106	AFL	0		TSN 0				
<b>291073 PRESSURE MAINTAINING VALVE</b>								
PN: AIR45474-0-2	MOS	02-Nov-12						Component ATA:29 OVERHAUL
SN: LK9002938	HRS	7475						
WC#: 29.030	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>291096 HYDRAULIC PRESSURE GAUGE</b>								
PN: PN	MOS/MSC	19-Jul-01	O/C					Component ATA:29
SN: UNKNOWN	HRS	0		TSN 0				
WC#: 29.045	AFL	0		TSN 0				
<b>291103 MAIN HYDRAULIC ACCUMULATOR</b>								
PN: AIR45574-3	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:29
SN: APB010643	HRS	0		TSN 0				
WC#: 29.050	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 29 - HYDRAULIC POWER</b>									
<b>291109</b>	<b>EMERGENCY BRAKE ACCUMULATOR</b>							<b>Component</b>	<b>ATA:29</b>
PN: AIR45574-3	MOS/MSC	03-Jun-03	O/C						
SN: APB993568	HRS	1644.3							
WC#: 29.055	AFL	1152							
<b>291131</b>	<b>HYDRAULIC FILTER</b>							<b>Component</b>	<b>ATA:29</b>
PN: MFHA15104	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: BF00/0232	HRS	0		TSN 0					
WC#: 29.060	AFL	0		TSN 0					
REF: GENERIC NO REF									
<b>291132</b>	<b>PRESSURE FILTER ASSEMBLY</b>							<b>Component</b>	<b>ATA:29</b>
PN: B2125-H4	MOS/MSC	06-Feb-15	O/C	TSN 0					
SN: FYH208414	HRS	9148.6		TSN 0					
WC#: 29.065	AFL	5913		TSN 0					
<b>291163</b>	<b>NO. 1 ENGINE HYDRAULIC PUMP</b>							<b>Component</b>	<b>ATA:29</b>
PN: 42022-03	MOS/MSC	29-Nov-15	O/C						
SN: BT504	HRS	9625.2							
WC#: 29.080	AFL	6192							
<b>291164</b>	<b>NO. 2 ENGINE HYDRAULIC PUMP</b>							<b>Component</b>	<b>ATA:29</b>
PN: 42022-03	MOS/MSC	02-Oct-13	O/C	TSO 0					
SN: AT388	HRS	8133.1		TSO 0					
WC#: 29.080	AFL	5385		TSO 0					
<b>291170</b>	<b>HYDRAULIC RESERVOIR RELIEF VALVE</b>							<b>Component</b>	<b>ATA:29</b>
PN: AIR87236-0	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: APB000912	HRS	0		TSN 0					
WC#: 29.117	AFL	0		TSN 0					
<b>291178</b>	<b>BANJO ASSEMBLY</b>							<b>Component</b>	<b>ATA:29</b>
PN: FRH460001C	MOS/MSC	19-Jul-01	O/C						
SN: M0418SJ1000	HRS	0		TSN 0					
WC#: 29.118	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 29 - HYDRAULIC POWER</b>									
291182	GROUND SERVICING HANDPUMP							Component	ATA:29
PN: AIR45424-0	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: APB992502	HRS	0		TSN 0					
WC#: 29.085	AFL	0		TSN 0					
291186	NO. 1 NON-RETURN TANK PRESSURE VALVE							Component	ATA:29
PN: HTE4853	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: M0390VNR0100	HRS	0		TSN 0					
WC#: 29.090	AFL	0		TSN 0					
292001	EMERGENCY HYDRAULIC TANK							Component	ATA:29
PN: 25HC161AD	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: 31366/10	HRS	0		TSN 0					
WC#: 29.095	AFL	0		TSN 0					
292003	SUCTION FILTER ASSEMBLY							Component	ATA:29
PN: AIR87366-0	MOS/MSC	25-May-02	O/C	TSN 0					
SN: BF00/0272	HRS	607.4		TSN 0					
WC#: 29.100	AFL	422		TSN 0					
292007	EMERGENCY HYDRAULIC HAND PUMP							Component	ATA:29
PN: AIR45448-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: APB003381	HRS	0		TSN 0					
WC#: 29.105	AFL	0		TSN 0					
292013	AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH							Component	ATA:29
PN: PN	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: UNKNOWN	HRS	0		TSN 0					
WC#: 29.110	AFL	0		TSN 0					
292031	EMERGENCY TANK ON/OFF HAND PUMP VALVE							Component	ATA:29
PN: AIR45446-2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: APB003481	HRS	0		TSN 0					
WC#: 29.120	AFL	0		TSN 0					
292037	EMERGENCY SYSTEM CHECK VALVE							Component	ATA:29
PN: AIR48026-0	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN: APB010624	HRS	0		TSN 0					
WC#: 29.125	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 29 - HYDRAULIC POWER</b>								
<b>293001 NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH</b> Component ATA:29								
PN:211C223-647	MOS/MSC	07-Sep-16	O/C	TSN 0				
SN:T035482	HRS	10216.7		TSN 0				
WC#: 29.130	AFL	6529		TSN 0				
<b>293002 NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH</b> Component ATA:29								
PN:HE15185-4SN1	MOS/MSC	25-Sep-02	O/C					
SN:5419TW	HRS	893.3						
WC#: 29.130	AFL	656						
<b>293013 EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH</b> Component ATA:29								
PN:TP42001	MOS	13-Jul-16						OVERHAUL
SN:291	HRS	10499.4	5000	TSO 0	15499.4		3412.2	
WC#: 29.135	AFL	6692		TSO 0				
<b>293019 HYDRAULIC PRESSURE TRANSDUCER</b> Component ATA:29								
PN:695-4-20	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:6311-6-228	HRS	0		TSN 0				
WC#: 29.140	AFL	0		TSN 0				
<b>293024 HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH</b> Component ATA:29								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 29.145	AFL	0		TSN 0				
<b>294005 HYDRAULIC NON-RETURN VALVE</b> Component ATA:29								
PN:AIR45468-0	MOS/MSC	04-Oct-01	O/C					
SN:APB001852	HRS	0						
WC#: 29.188	AFL	0						
<b>ATA 30 - ICE AND RAIN PROTECTION</b>								
<b>300001<sup>S</sup> FUNCTIONAL TEST ROTARY ICE DETECTOR</b> Service ATA:30								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 30.085	AFL	7300						
REF: AFMS INSPECTION B1						PKG:7,91		





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 30 - ICE AND RAIN PROTECTION</b>								
<b>300002<sup>S</sup> OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM Service ATA:30</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 30.080	AFL	6832						
				REF: AFMS INSPECTION C1				PKG:19,92
<b>300003<sup>S</sup> REPLACE AIRFRAME DE-ICING FILTER ELEMENT Service ATA:30</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 30.020	AFL	7300						
				REF: AFMS INSPECTION B6				PKG:12,91
<b>300004<sup>S</sup> FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS Service ATA:30</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 30.065	AFL	6832						
				REF: AFMS INSPECTION C1				PKG:19,92
<b>300005<sup>S</sup> REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER Service ATA:30</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 30.045	AFL	6832						
				REF: AFMS INSPECTION C6				PKG:24,92
<b>301001 TKS DE-ICER TANK Component ATA:30</b>								
PN:08301-01	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AST01F205	HRS	0		TSN 0				
WC#: 30.010	AFL	0		TSN 0				
<b>301007 AIRFRAME DE-ICING PUMP ASSEMBLY Component ATA:30</b>								
PN:XA9511E009	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AST01A192	HRS	0		TSN 0				
WC#: 30.015	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 30 - ICE AND RAIN PROTECTION</b>								
<b>301013 AIRFRAME DE-ICING FILTER ASSEMBLY Component ATA:30</b>								
PN:F903	MOS/MSC	18-Jan-08	O/C					
SN:W09015/021	HRS	5224						
WC#: 30.020	AFL	3495						
<b>301025 DE-ICING VALVE ASSEMBLY Component ATA:30</b>								
PN:FV131-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AST00K517	HRS	0		TSN 0				
WC#: 30.025	AFL	0		TSN 0				
<b>301037 DE-ICING SYSTEM CONTENTS GAUGE Component ATA:30</b>								
PN:S458-3-191T	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:83078	HRS	0		TSN 0				
WC#: 30.030	AFL	0		TSN 0				
<b>301043 DE-ICING SYSTEM CONTENTS FLOAT Component ATA:30</b>								
PN:FRH070001	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FR283BD	HRS	0		TSN 0				
WC#: 30.035	AFL	0		TSN 0				
<b>3010510<sup>U</sup> ANTI ICE LOW-PRESSURE SWITCH Component ATA:30</b>								
PN:P067D-075	MOS/MSC	19-Jul-01	O/C					
SN:AST00G300	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>301063 EMPENNAGE TKS PROPORTION UNIT Component ATA:30</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 30.050	AFL	0		TSN 0				
<b>301067 TKS VENT VALVE Component ATA:30</b>								
PN:FV141	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AST00C228	HRS	0		TSN 0				
WC#: 30.055	AFL	0		TSN 0				
<b>301069 TKS PRESSURE SWITCH Component ATA:30</b>								
PN:P067D075	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AST00G300	HRS	0		TSN 0				
WC#: 30.060	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 30 - ICE AND RAIN PROTECTION</b>								
<b>304019 NO. 1 WINDSCREEN (A PANEL) CONTROLLER</b>								Component ATA:30
PN:ND0075-2011	MOS/MSC	20-Sep-16	O/C					
SN:L317000	HRS	10249						
WC#: 30.070	AFL	6551						
								WO#: N312FU-220911-1
<b>304020 NO. 2 WINDSCREEN (A PANEL) CONTROLLER</b>								Component ATA:30
PN:ND0075-2011	MOS/MSC	20-Sep-16	O/C					
SN:L392995	HRS	10249						
WC#: 30.070	AFL	6551						
<b>304022 NO. 1 WINDSCREEN (B PANEL) CONTROLLER</b>								Component ATA:30
PN:ND0075-2001	MOS/MSC	03-Apr-17	O/C					
SN:L404835	HRS	10573.3						
WC#: 30.075	AFL	6734						
<b>304023 NO. 2 WINDSCREEN (B PANEL) CONTROLLER</b>								Component ATA:30
PN:ND0075-2001	MOS/MSC	29-Oct-21	O/C		TSN 0			
SN:L533868	HRS	11847			TSN 0			
WC#: 30.075	AFL	7469			TSN 0			
<b>308001 ROTARY ICE DETECTOR</b>								Component ATA:30
PN:NFO075-0667	MOS/MSC	23-Jan-05	O/C					
SN:L216128	HRS	2829						
WC#: 30.085	AFL	1962						
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>								
<b>310002 LIGHTNING SENSOR ANTENNA</b>								Component ATA:31
PN:4057697-901	MOS/MSC	25-Jul-21	O/C		TSN 0			
SN:21013004	HRS	11768.3			TSN 0			
WC#: 31.015	AFL	7421			TSN 0			
<b>311001 TKS TIMER</b>								Component ATA:31
PN:100-1805-02	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:B269	HRS	0			TSN 0			
WC#: 31.020	AFL	0			TSN 0			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>									
3110542 <sup>U</sup>		NO.1 CONTROL DISPLAY						Component	ATA:31
PN:7005819-707	MOS/MSC	05-May-15	O/C						
SN:01034197	HRS	9226.2							
	AFL	5955							
3110543 <sup>U</sup>		NO.2 CONTROL DISPLAY						Component	ATA:31
PN:7005819-707	MOS/MSC	05-May-15	O/C						
SN:01044232	HRS	9226.2							
	AFL	5955							
3110556 <sup>U</sup>		NO.1 HSI DISPLAY						Component	ATA:31
PN:7003110-901	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
3110557 <sup>U</sup>		NO.2 HSI DISPLAY						Component	ATA:31
PN:7003110-901	MOS/MSC	03-Jun-16	O/C	TSO 1					
SN:89023301	HRS	10011		TSO 0					
	AFL	6400		TSO 0					
3110560 <sup>U</sup>		NO.1 ADI DISPLAY						Component	ATA:31
PN:7003110-901	MOS/MSC	07-Jun-16	O/C	TSR 1					
SN:95089178	HRS	10011		TSR 0					
	AFL	6400		TSR 0					
3110561 <sup>U</sup>		NO.2 ADI DISPLAY						Component	ATA:31
PN:7003110-901	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
3110587 <sup>U</sup>		NO.3 PRIMARY FLIGHT DISPLAY						Component	ATA:31
PN:7003110-901	MOS/MSC	15-Apr-22	O/C	TSR 0					
SN:98031079	HRS	12004.3		TSR 0					
	AFL	7551		TSR 0					
312001		PILOT CLOCK						Component	ATA:31
PN:M877A-5V	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:11777	HRS	0		TSN 0					
WC#: 31.025	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>								
<b>312002 COPILOT CLOCK</b> Component ATA:31								
PN:M877A-5V	MOS/MSC	20-Feb-10	O/C					
SN:12455	HRS	6387.2						
WC#: 31.025	AFL	4287						
<b>312008 O.A.T. INDICATOR</b> Component ATA:31								
PN:2141-1-14	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:82308	HRS	0		TSN 0				
WC#: 31.030	AFL	0		TSN 0				
<b>312009 PITOT AMMETER</b> Component ATA:31								
PN:2132-1-62	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:82265	HRS	0		TSN 0				
WC#: 31.035	AFL	0		TSN 0				
<b>313003 NO. 1 CURRENT MONITOR-</b> Component ATA:31								
PN:E37040S	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:3398	HRS	0		TSN 0				
WC#: 31.300	AFL	0		TSN 0				
<b>313004 NO. 2 CURRENT MONITOR-</b> Component ATA:31								
PN:E37040S	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:3402	HRS	0		TSN 0				
WC#: 31.300	AFL	0		TSN 0				
<b>313005 LEFT CURRENT LEVEL INDICATOR</b> Component ATA:31								
PN:770-537	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:1695	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
<b>313006 RIGHT CURRENT LEVEL INDICATOR</b> Component ATA:31								
PN:770-537	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:1737	HRS	0		TSN 0				
WC#: 31.040	AFL	0		TSN 0				
<b>313007 CABIN TEMPERATURE INDICATOR</b> Component ATA:31								
PN:2131-1-15	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:82282	HRS	0		TSN 0				
WC#: 31.045	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>								
<b>313008 DC VOLTMETER</b> Component ATA:31								
PN:2132-1-12	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:82313	HRS	0		TSN 0				
WC#: 31.050	AFL	0		TSN 0				
<b>313009 LEFT DC AMMETER</b> Component ATA:31								
PN:2132-1-13	MOS/MSC	18-Sep-05	O/C	TSR 0				
SN:BG74854	HRS	3423.1		TSR 0				
WC#: 31.055	AFL	2315		TSR 0				
<b>313010 AC VOLTMETER</b> Component ATA:31								
PN:2132-01-0014	MOS/MSC	14-Sep-01	O/C					
SN:82328	HRS	6.6						
WC#: 31.060	AFL	5						
<b>313011 RIGHT DC AMMETER</b> Component ATA:31								
PN:2131-1-13	MOS/MSC	20-Aug-02	O/C					
SN:BG75039	HRS	823.2						
WC#: 31.065	AFL	598						
<b>313014 DUCT AIR TEMPERATURE INDICATOR</b> Component ATA:31								
PN:2132-1-18	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:82322	HRS	0		TSN 0				
WC#: 31.070	AFL	0		TSN 0				
<b>313015 TEMPERATURE SELECTOR</b> Component ATA:31								
PN:25-6MC415	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:041C-1242	HRS	0		TSN 0				
WC#: 31.075	AFL	0		TSN 0				
<b>313020 FUEL PROCESSOR UNIT</b> Component ATA:31								
PN:0107KPU1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:1083	HRS	0		TSN 0				
WC#: 31.080	AFL	0		TSN 0				
<b>313030 FILTER UNIT</b> Component ATA:31								
PN:25-9NF4027-45A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:L316647	HRS	0		TSN 0				
WC#: 31.303	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>								
<b>313031</b>	<b>FILTER UNIT</b>							<b>Component ATA:31</b>
PN:25-9NF4027-47A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:L317245	HRS	0		TSN 0				
WC#: 31.303	AFL	0		TSN 0				
<b>313032</b>	<b>FILTER UNIT</b>							<b>Component ATA:31</b>
PN:25-9NF4027-49A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:L317120	HRS	0		TSN 0				
WC#: 31.303	AFL	0		TSN 0				
<b>313033</b>	<b>FILTER UNIT</b>							<b>Component ATA:31</b>
PN:25-9NF4027-51A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:L317484	HRS	0		TSN 0				
WC#: 31.303	AFL	0		TSN 0				
<b>313101</b>	<b>ANGLE OF ATTACK INDICATOR COMPUTER</b>							<b>Component ATA:31</b>
PN:C87705-4	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:498	HRS	0		TSN 0				
WC#: 31.095	AFL	0		TSN 0				
<b>313109</b>	<b>NO. 1 ANGLE OF ATTACK INDEXER</b>							<b>Component ATA:31</b>
PN:965-0113-003	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:2484	HRS	0		TSN 0				
WC#: 31.100	AFL	0		TSN 0				
<b>313110</b>	<b>NO. 2 ANGLE OF ATTACK INDEXER</b>							<b>Component ATA:31</b>
PN:965-0113-003	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:2467	HRS	0		TSN 0				
WC#: 31.100	AFL	0		TSN 0				
<b>313201</b>	<b>BRAKE PRESSURE INDICATOR</b>							<b>Component ATA:31</b>
PN:696-01-13	MOS/MSC	02-Oct-06	O/C	TSO 0				
SN:BG72992	HRS	4119		TSO 0				
WC#: 31.105	AFL	2755		TSO 0				
REF: GENERIC NO REF								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>									
314009	NO. 2 INCLINOMETER							Component	ATA:31
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.115	AFL	0		TSN 0					
314014	MAINTENANCE DIAGNOSTIC COMPUTER							Component	ATA:31
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 31.130	AFL	0		TSN 0					
REF: GENERIC NO REF									
<b>ATA 32 - LANDING GEAR</b>									
320001 <sup>S</sup>	TEST BRAKING SYSTEMS							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.305	AFL	7300							
REF: AFMS INSPECTION B12									
320002 <sup>S</sup>	FUNCTIONAL TEST MAXARET UNITS							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.370	AFL	7300							
REF: AFMS INSPECTION B12									
320003 <sup>S</sup>	CHECK NOSE GEAR LEG ASSEMBLY							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.430	AFL	7300							
REF: AFMS INSPECTION B12									
320004 <sup>S</sup>	CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.435	AFL	7300							
REF: AFMS INSPECTION B12									





## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
320005 <sup>S</sup>	INSPECT NOSEWHEEL STEERING JACK							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.470	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
320006 <sup>S</sup>	INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.450	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
320007 <sup>S</sup>	INSPECT NOSEWHEEL STEERING ON/OFF VALVE							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.350	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
320008 <sup>S</sup>	CHECK NOSE GEAR DRAG STAY ASSEMBLY							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.440	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
320009 <sup>S</sup>	DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.545	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	
320010 <sup>S</sup>	CHECK MAIN GEAR LEG ASSEMBLIES							Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.420	AFL	7300							
				REF: AFMS INSPECTION B12				PKG:18,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>320011<sup>S</sup> INSPECT MAIN LANDING GEAR SIDE-STAYS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.010	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320012<sup>S</sup> CHECK MAIN LANDING GEAR TORQUE LINKS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.015	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320013<sup>S</sup> INSPECT MAIN LANDING GEAR DOORS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.460	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320014<sup>S</sup> INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.425	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320015<sup>S</sup> INSPECT REVERSING VALVES AND OPERATING MECHANISMS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.445	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320016<sup>S</sup> CHECK STEERING SYSTEM CABLES AND CHAINS Service ATA:32</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 32.475	AFL	6832						
				REF: AFMS INSPECTION C4				PKG:22,92



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
320017 <sup>S</sup>			CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 32.180	AFL	6832							
					REF: AFMS INSPECTION C12			PKG:30,92	
320018 <sup>S</sup>			CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 32.350	AFL	6832							
					REF: AFMS INSPECTION C12			PKG:30,92	
320019 <sup>S</sup>			INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 32.385	AFL	6832							
					REF: AFMS INSPECTION D12			PKG:42,93	
320020 <sup>S</sup>			CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 32.185	AFL	6832							
					REF: AFMS INSPECTION D12			PKG:42,93	
320021 <sup>S</sup>			CLEAN RESTRICTOR VALVES					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 32.145	AFL	6832							
					REF: AFMS INSPECTION D12			PKG:42,93	
320022 <sup>S</sup>			CHECK BRAKE MASTER CYLINDERS					Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.465	AFL	7300							
					REF: AFMS INSPECTION B4			PKG:10,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
320023 <sup>S</sup>			CHECK BRAKE HOSES TO MASTER CYLINDERS					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 32.455	AFL	6832							
			REF: AFMS INSPECTION C4						PKG:22,92
320024 <sup>S</sup>			REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE					Service	ATA:32
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 32.375	AFL	6832							
			REF: AFMS INSPECTION C12						PKG:30,92
320027 <sup>S</sup>			VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE					Service	ATA:32
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 32.350	AFL	7567							
			REF: AFMS INSPECTION G						PKG:96
320028			INSPECT/NDT MAIN LANDING GEAR MAIN LANDING GEAR FAIRING STRUT					Service	ATA:32
	MOS	17-Jun-22	48 (+3m)	Adj -138d	30-Jan-26	30-Apr-26	1235 d (+90)		
	HRS	12023.9							
WC#: 32.035	AFL	7567							
			REF: AFMS STRUCTURAL INSPECTIONS, NTM 32-10-103						
320029 <sup>S</sup>			CHECK NOSE LANDING GEAR DRAG STAY					Service	ATA:32
	MOS/MSC	25-Oct-11	A/R <sup>S</sup>						
	HRS	0							
WC#: 32.070	AFL	1265							
			REF: AFMS OUT OF PHASE INSPECTIONS						
320033 <sup>S</sup>			DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR					Service	ATA:32
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 32.095	AFL	7300							
			REF: AFMS INSPECTION B12						PKG:18,91



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>320034<sup>S</sup> INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.510	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>320035<sup>S</sup> INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER Service ATA:32</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 32.520	AFL	6832						
				REF: AFMS INSPECTION C12				PKG:30,92
<b>320036<sup>S</sup> INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK Service ATA:32</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 32.530	AFL	6832						
				REF: AFMS INSPECTION C12				PKG:30,92
<b>320037<sup>S</sup> CHECK NOSE LEG ASSEMBLY TORQUE LINKS Service ATA:32</b>								
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 32.540	AFL	7300						
				REF: AFMS INSPECTION B12				PKG:18,91
<b>321001 LEFT MAIN LEG Component ATA:32</b>								
PN:140-810044-19	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	OVERHAUL
SN:SAM/DHB/8P/225	HRS	7475						
WC#: 32.020	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>321002 RIGHT MAIN LEG Component ATA:32</b>								
PN:140-810044-18	MOS	10-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	OVERHAUL
SN:SAM/DHB/8S/467	HRS	7475						
WC#: 32.020	AFL	4999	5000		9999 <sup>M</sup>		2386	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>321013 LEFT SIDESTAY</b>								
PN:140-810043-11	MOS	25-Oct-12	144		25-Oct-24 <sup>M</sup>		773 d	Component ATA:32 OVERHAUL
SN:SAM/DHB/8SSP/231	HRS							
WC#: 32.025	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>321014 RIGHT SIDESTAY</b>								
PN:140-810043-12	MOS	03-Nov-12	144		13-Sep-24 <sup>M</sup>		731 d	Component ATA:32 OVERHAUL
SN:SAM/DHB/8SSS/246	HRS	7475						
WC#: 32.030	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>321015 LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM</b>								
PN:140-810015-3	MOS	25-Oct-11						Component ATA:32 LIFE LIMIT
SN:SAM2210	HRS							
WC#: 32.025	AFL	4589	10000	TSN 4589	10000		2387	
<b>321016 RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.030	AFL	0	10000	TSN 0	10000		2387	
<b>321017 LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM</b>								
PN:140-810014-3	MOS	25-Oct-11						Component ATA:32 LIFE LIMIT
SN:SAM1603	HRS							
WC#: 32.025	AFL	4589	12000	TSN 4589	12000		4387	
<b>321018 RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.030	AFL	0	12000	TSN 0	12000		4387	
<b>321050 LEFT MAIN LANDING GEAR UPPER CASING</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0	24000	TSN 0	24000		16387	
<b>321051 RIGHT MAIN LANDING GEAR UPPER CASING</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.390	AFL	0	24000	TSN 0	24000		16387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>321065 LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN</b> Component ATA:32								
PN:25-8UM131-11A	MOS/MSC	25-Oct-11	O/C					
SN:UNKNOWN	HRS							
WC#: 32.400	AFL	3095						
<b>321066 RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN</b> Component ATA:32								
PN:25-8UM131-11A	MOS/MSC	25-Oct-11	O/C					
SN:UNKNOWN	HRS							
WC#: 32.400	AFL	3095						
<b>321067 LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN</b> Component ATA:32								
PN:25-8UM131-11A	MOS/MSC	25-Oct-11	O/C					
SN:UNKNOWN	HRS							
WC#: 32.495	AFL	3095						
<b>321068 RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN</b> Component ATA:32								
PN:25-8UM131-11A	MOS/MSC	25-Oct-11	O/C					
SN:UNKNOWN	HRS							
WC#: 32.495	AFL	3095						
<b>321071 LEFT MAIN LANDING GEAR JACK DISTANCE PIN</b> Component ATA:32								
PN:25UM423	MOS	25-Oct-11						LIFE LIMIT
SN:5151DA	HRS							
WC#: 32.045	AFL	4589	24000		28859 <sup>M</sup>		21246	
<b>321072 RIGHT MAIN LANDING GEAR JACK DISTANCE PIN</b> Component ATA:32								
PN:25UM423	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.045	AFL	0	24000	TSN 0	24000		16387	
<b>321075 LEFT MAIN LANDING GEAR PLUNGER TUBE</b> Component ATA:32								
PN:25-8UM5,-6/140-810016-1,-2	MOS	19-Jul-01						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0	17000	TSN 0	17000		9387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>321076 RIGHT MAIN LANDING GEAR PLUNGER TUBE</b>								
PN:25-8UM6/140-8100016-2	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.410	AFL	0	17000	TSN 0	17000		9387	
<b>321081 LEFT MAIN LANDING GEAR UPPER TORQUE LINK</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0	20000	TSN 0	20000		12387	
<b>321082 RIGHT MAIN LANDING GEAR UPPER TORQUE LINK</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.550	AFL	0	20000	TSN 0	20000		12387	
<b>321083 LEFT MAIN LANDING GEAR LOWER TORQUE LINK</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.555	AFL	0	20000	TSN 0	20000		12387	
<b>321084 RIGHT MAIN LANDING GEAR LOWER TORQUE LINK</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.555	AFL	0	20000	TSN 0	20000		12387	
<b>322001 NOSE LEG ASSEMBLY</b>								
PN:25-9UN1-353A	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component OVERHAUL
SN:SAM/DHB/9N/367	HRS	7475						
WC#: 32.050	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>322003 NOSE LANDING GEAR PIVOT PIN</b>								
PN:25UN645A	MOS	19-Jul-01						Component LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.055	AFL	0	16000	TSN 0	16000		8387	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>322007 NOSE LANDING GEAR DRAG STAY</b>								
PN:25-8UN3-179A	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component ATA:32 OVERHAUL
SN:SAM/DHB/8DS/323	HRS	7475						
WC#: 32.070	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>322009 NOSE LANDING GEAR JACK LOWER PIVOT PIN</b>								
PN:25UN597	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.075	AFL	0	22000	TSN 0	22000		14387	
<b>322011 NOSE LANDING GEAR DRAG STAY BRIDGE CASTING</b>								
PN:25-8UN487-1A	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.075	AFL	0	33000	TSN 0	33000		25387	
<b>322015 NOSE LANDING GEAR UPPER TORQUE LINK</b>								
PN:25-8UN267	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.080	AFL	0	32000	TSN 0	32000		24387	
<b>322016 NOSE LANDING GEAR LOWER TORQUE LINK</b>								
PN:25-8UN269-	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.080	AFL	0	32000	TSN 0	32000		24387	
<b>322017 NOSE LANDING GEAR DRAG STRUT PICK-UP</b>								
PN:25-8UN265	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.560	AFL	0	13900	TSN 0	13900		6287	
<b>322025 NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS</b>								
PN:A102-28J	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.380	AFL	0	10000	TSN 0	10000		2387	
<b>322031 NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS</b>								
PN:A102-21J	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.085	AFL	0	10000	TSN 0	10000		2387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>322045 NOSE LANDING GEAR PLUNGER TUBE</b>								
PN:25UN649	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.075	AFL	0	20000	TSN 0	20000		12387	
<b>323001 NOSE LANDING GEAR RETRACTION JACK</b>								
PN:AIR45404-1	MOS	02-Nov-12						Component ATA:32 OVERHAUL
SN:LK8903387	HRS	7474.9		TSO 0				
WC#: 32.090	AFL	4999	5000	TSO 0	9999		2386	
<b>323007 LEFT MAIN LANDING GEAR RETRACTION JACK</b>								
PN:AIR48502/7	MOS	29-May-15						Component ATA:32 OVERHAUL
SN:APB002274	HRS	9314.8		TSO 0				
WC#: 32.100	AFL	6009	5000	TSO 0	11009		3396	
<b>323008 RIGHT MAIN LANDING GEAR RETRACTION JACK</b>								
PN:AIR48503/7	MOS	29-May-15						Component ATA:32 OVERHAUL
SN:APB980752	HRS	9314.8		TSO 0				
WC#: 32.100	AFL	6009	5000	TSO 0	11009		3396	
<b>323019 LEFT MAIN LANDING GEAR DOOR JACK</b>								
PN:AIR48485-3	MOS	02-Nov-12						Component ATA:32 OVERHAUL
SN:LK9200235	HRS	7474.9		TSN 0				
WC#: 32.105	AFL	4999	5000	TSN 0	9999		2386	
<b>323020 RIGHT MAIN LANDING GEAR DOOR JACK</b>								
PN:AIR48484-3	MOS	26-Apr-16						Component ATA:32 OVERHAUL
SN:APB962407	HRS	10335.8		TSO 0				
WC#: 32.105	AFL	6609	5000	TSO 0	11609		3996	
<b>323031 LEFT SEQUENCE VALVE</b>								
PN:AIR48540-1	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component ATA:32 OVERHAUL
SN:APB070028	HRS	7475						
WC#: 32.110	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>323032 RIGHT SEQUENCE VALVE</b>								
PN:AIR48540-1	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component ATA:32 OVERHAUL
SN:APB080293	HRS	7475						
WC#: 32.110	AFL	4999	5000		9999 <sup>M</sup>		2386	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>323043 LEFT REVERSING VALVE</b>								
PN: AIR48542-1	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component ATA:32 OVERHAUL
SN: APB992720	HRS	7475						
WC#: 32.115	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>323044 RIGHT REVERSING VALVE</b>								
PN: AIR48543-1	MOS	03-Nov-12	144		30-Nov-24 <sup>M</sup>		809 d	Component ATA:32 OVERHAUL
SN: 51911X	HRS	7475						
WC#: 32.115	AFL	4999	5000		9999 <sup>M</sup>		2386	
<b>3230508<sup>U</sup> FILTER</b>								
PN: AIR48538	MOS/MSC	19-Jul-01	O/C					Component ATA:32
SN: BF00/0266	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>323079 LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE</b>								
PN: AIR48026-0	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN: APB010712	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
<b>323080 RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE</b>								
PN: AIR48026-0	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN: APB010706	HRS	0		TSN 0				
WC#: 32.120	AFL	0		TSN 0				
<b>323090 FRAME 15A NON-RETURN VALVE</b>								
PN: AIR45420-0	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN: APB003201	HRS	0		TSN 0				
WC#: 32.505	AFL	0		TSN 0				
<b>323097 FRAME 14 NON-RETURN VALVE</b>								
PN: AIR45420-0	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN: APB001078	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				
<b>323098 FRAME 14A NONRETURN VALVE</b>								
PN: AIR45420-0	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN: APB003190	HRS	0		TSN 0				
WC#: 32.130	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>323103 LANDING GEAR SELECTOR/DUMP VALVE</b> Component ATA:32								
PN: AIR45406-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN: APB010338	HRS	0		TSN 0				
WC#: 32.135	AFL	0		TSN 0				
<b>323115 LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE</b> Component ATA:32								
PN: AIR45444-0-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN: APB002857	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
<b>323116 RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE</b> Component ATA:32								
PN: AIR45444-0-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN: APB002864	HRS	0		TSN 0				
WC#: 32.140	AFL	0		TSN 0				
<b>323139 LEFT MAIN LANDING GEAR JACK PIVOT BOLT</b> Component ATA:32								
PN: 25UM153A	MOS	25-Oct-11						LIFE LIMIT
SN: 247970	HRS	0		TSN 0				
WC#: 32.150	AFL	4589	30000	TSN 0	34589		26976	
<b>323140 RIGHT MAIN LANDING GEAR JACK PIVOT BOLT</b> Component ATA:32								
PN: 25UM153A	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN: UNKNOWN	HRS	0		TSN 0				
WC#: 32.150	AFL	0	30000	TSN 0	30000		22387	
<b>323151 LEFT MAIN LANDING GEAR JACK CYLINDER HEAD</b> Component ATA:32								
PN: AIR48502/7	MOS	22-Jun-15	168	TSO 0	22-Jun-29 <sup>M</sup>		2474 d	LIFE LIMIT
SN: APB002274	HRS	9314.8		TSO 0				
WC#: 32.155	AFL	6009	12000	TSO 0	18009 <sup>M</sup>		10396	
<b>323152 RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD</b> Component ATA:32								
PN: AIR48503/7	MOS	22-Jun-15	168	TSO 1	22-Jun-29 <sup>M</sup>		2474 d	LIFE LIMIT
SN: APB980752	HRS	9314.8		TSO 0				
WC#: 32.155	AFL	6009	12000	TSO 0	18009 <sup>M</sup>		10396	
<b>323163 LEFT MAIN LANDING GEAR JACK EYE END</b> Component ATA:32								
PN: AIR158922	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN: UNKNOWN	HRS	0		TSN 0				
WC#: 32.160	AFL	0	10000	TSN 0	10000		2387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>323164 RIGHT MAIN LANDING GEAR JACK EYE END</b>								
PN:323164	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:323164	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.160	AFL	0	10000	TSN 0	10000		2387	
<b>323175 LEFT MAIN LANDING GEAR RETRACTION ARM</b>								
PN:28-8UM63-1A	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:323175	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.165	AFL	0	12000	TSN 0	12000		4387	
<b>323176 RIGHT MAIN LANDING GEAR RETRACTION ARM</b>								
PN:25-8UM63-2A	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:323176	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.165	AFL	0	12000	TSN 0	12000		4387	
<b>323181 LEFT MAIN LANDING GEAR RETRACTION ARM PIN</b>								
PN:25UM787	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:323181	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.170	AFL	0	32000	TSN 0	32000		24387	
<b>323182 RIGHT MAIN LANDING GEAR RETRACTION ARM PIN</b>								
PN:25UM787	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:323182	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.170	AFL	0	32000	TSN 0	32000		24387	
<b>323187 LANDING GEAR LEVER LOCK SOLENOID</b>								
PN:D5327	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN:C3249	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.175	AFL	0		TSN 0				
<b>324001 NOSE LANDING GEAR AXLE BARREL</b>								
PN:25-8UN257	MOS	19-Jul-01		TSN 0				Component ATA:32
SN:324001	HRS	0		TSN 0				LIFE LIMIT
WC#: 32.195	AFL	0	30000	TSN 0	30000		22387	
<b>324007 LEFT NOSE WHEEL</b>								
PN:AH52339	MOS/MSC	17-Feb-22	O/C	TSN 0				Component ATA:32
SN:JF110	HRS	11909.5		TSN 0				LIFE LIMIT
WC#: 32.200	AFL	7500		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324008 RIGHT NOSE WHEEL</b> Component ATA:32								
PN:AH52339	MOS/MSC	17-Feb-22	O/C					
SN:ME191	HRS	11909.5						
WC#: 32.205	AFL	7500						
<b>324019 LEFT NOSE TIRE</b> Component ATA:32								
PN:031-595-0	MOS/MSC	17-Feb-22	T/C	TSN 0				
SN:1025T00362	HRS	11909.5		TSN 0				
WC#: 32.200	AFL	7500		TSN 0				
<b>324020 RIGHT NOSE TIRE</b> Component ATA:32								
PN:031-595-0	MOS/MSC	17-Feb-22	T/C	TSN 0				
SN:1025T00351	HRS	11909.5		TSN 0				
WC#: 32.205	AFL	7500		TSN 0				
<b>324031 LEFT OUTBOARD MAIN WHEEL</b> Component ATA:32								
PN:AHA1814	MOS/MSC	22-Jun-22	O/C	TSO 0				
SN:5047GF	HRS	12023.9		TSO 0				
WC#: 32.210	AFL	7567		TSO 0				
<b>324032 RIGHT OUTBOARD MAIN WHEEL</b> Component ATA:32								
PN:AHA1814	MOS/MSC	29-Oct-21	O/C	TSO 0				
SN:ZJ041	HRS	11847		TSO 0				
WC#: 32.215	AFL	7469		TSO 0				
<b>324033 LEFT INBOARD MAIN WHEEL</b> Component ATA:32								
PN:AHA1814	MOS/MSC	22-Jun-22	O/C	TSO 0				
SN:YF155	HRS	12023.9		TSO 0				
WC#: 32.220	AFL	7567		TSO 0				
<b>324034 RIGHT INBOARD MAIN WHEEL</b> Component ATA:32								
PN:AHA1814	MOS/MSC	29-Oct-21	O/C	TSO 0				
SN:5130CW	HRS	11847		TSO 0				
WC#: 32.225	AFL	7469		TSO 0				
<b>324055 LEFT OUTBOARD MAIN TIRE</b> Component ATA:32								
PN:027-504-0	MOS/MSC	22-Jun-22	T/C					
SN:2096P0002	HRS	12023.9						
WC#: 32.210	AFL	7567						



## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324056 RIGHT OUTBOARD MAIN TIRE</b> Component ATA:32								
PN:027-504-0	MOS/MSC	29-Oct-21	T/C	TSN 1				
SN:1254P05003	HRS	11847		TSN 0				
WC#: 32.215	AFL	7469		TSN 0				
<b>324057 LEFT INBOARD MAIN TIRE</b> Component ATA:32								
PN:027-504-0	MOS/MSC	22-Jun-22	T/C	TSN 0				
SN:2096P00104	HRS	12023.9		TSN 0				
WC#: 32.220	AFL	7567		TSN 0				
<b>324058 RIGHT INBOARD MAIN TIRE</b> Component ATA:32								
PN:027-504-0	MOS/MSC	29-Oct-21	T/C	TSN 1				
SN:1253P05053	HRS	11847		TSN 0				
WC#: 32.225	AFL	7469		TSN 0				
<b>324065 RIGHT WHEEL WELL FILTER</b> Component ATA:32								
PN:AIR48538	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:BF00-0266	HRS	0		TSN 0				
WC#: 32.230	AFL	0		TSN 0				
<b>324066 LEFT FRAME 14A FILTER</b> Component ATA:32								
PN:AIR48538-0	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:BF01/0047	HRS	0		TSN 0				
WC#: 32.235	AFL	0		TSN 0				
<b>324067 RIGHT FRAME 14A FILTER</b> Component ATA:32								
PN:AIR48538-0	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:BF01/0050	HRS	0		TSN 0				
WC#: 32.235	AFL	0		TSN 0				
<b>324068 FRAME 15 FILTER</b> Component ATA:32								
PN:AIR48538-0	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:BF01/0056	HRS	0		TSN 0				
WC#: 32.235	AFL	0		TSN 0				
<b>324069 NOSE WHEEL STEERING FILTER</b> Component ATA:32								
PN:AIR45412-0	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:BF01/0012	HRS	0		TSN 0				
WC#: 32.240	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324077 PORT SHUTTLE VALVES</b> <span style="float:right">Component ATA:32</span>								
PN:AH081963	MOS/MSC	12-Sep-01	O/C					
SN:ZE093	HRS	6.6		TSN 6.6				
WC#: 32.407	AFL	5		TSN 5				
<b>324078 STARBOARD SHUTTLE VALVES</b> <span style="float:right">Component ATA:32</span>								
PN:AH081963	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:YY132	HRS	0		TSN 0				
WC#: 32.407	AFL	0		TSN 0				
<b>324079 PORT SHUTTLE VALVES</b> <span style="float:right">Component ATA:32</span>								
PN:AH081964	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:YR148	HRS	0		TSN 0				
WC#: 32.407	AFL	0		TSN 0				
<b>324080 STARBOARD SHUTTLE VALVES</b> <span style="float:right">Component ATA:32</span>								
PN:AH081964	MOS/MSC	12-Sep-01	O/C					
SN:ZF046	HRS	6.6		TSN 6.6				
WC#: 32.407	AFL	5		TSN 5				
<b>324115 BRAKE CONTROL VALVE</b> <span style="float:right">Component ATA:32</span>								
PN:AC67732	MOS/MSC	03-Jun-03	O/C					
SN:HF249	HRS	1644.3						
WC#: 32.245	AFL	1152						
<b>324121 BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE</b> <span style="float:right">Component ATA:32</span>								
PN:ACO34629	MOS	25-Oct-11		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 32.245	AFL	4330	4500	TSN 0	8830		1217	
<b>324122 BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE</b> <span style="float:right">Component ATA:32</span>								
PN:ACO346230	MOS	25-Oct-11		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 32.245	AFL	4330	4500	TSN 0	8830		1217	
<b>324123 BRAKE CONTROL VALVE INNER KNIFE EDGE</b> <span style="float:right">Component ATA:32</span>								
PN:AC021516/AC036122	MOS	25-Oct-11		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS							
WC#: 32.245	AFL	4330	4500	TSN 0	8830		1217	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324145 MAIN REDUCING VALVE</b> Component ATA:32								
PN:AC61518	MOS/MSC	06-Jan-03	O/C					
SN:WG044	HRS	1178.4						
WC#: 32.250	AFL	856						
<b>324151 EMERGENCY REDUCING VALVE</b> Component ATA:32								
PN:AC69784	MOS/MSC	26-Mar-10	O/C					
SN:RK002	HRS	6458						
WC#: 32.255	AFL	4330						
<b>324157 EMERGENCY REDUCING VALVE LEFT KNIFE EDGE</b> Component ATA:32								
PN:ACO25103/ACO34629	MOS	26-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	6458						
WC#: 32.255	AFL	4330	4500	TSN 0	8830		1217	
<b>324158 EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE</b> Component ATA:32								
PN:ACO25104/ACO34630	MOS	26-Mar-10		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	6458						
WC#: 32.255	AFL	4330	4500	TSN 0	8830		1217	
<b>324175 LEFT OUTBOARD BRAKE UNIT</b> Component ATA:32								
PN:AHA1897	MOS/MSC	27-Jun-22	O/C	TSO 0				
SN:026AM	HRS	12023.9		TSO 0				
WC#: 32.265	AFL	7567		TSO 0				
<b>324176 RIGHT OUTBOARD BRAKE UNIT</b> Component ATA:32								
PN:AHA1897	MOS/MSC	06-Jun-16	O/C	TSO 20				
SN:5136GE	HRS	10011		TSO 0				
WC#: 32.260	AFL	6400		TSO 0				
<b>324177 LEFT INBOARD BRAKE UNIT</b> Component ATA:32								
PN:AHA1897	MOS/MSC	29-Jan-18	O/C					
SN:5029JP	HRS	10726						
WC#: 32.265	AFL	6832						
<b>324178 RIGHT INBOARD BRAKE UNIT</b> Component ATA:32								
PN:AHA1897	MOS/MSC	06-Jun-16	O/C	TSO 5				
SN:VX088	HRS	10011		TSO 0				
WC#: 32.260	AFL	6400		TSO 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324223 LEFT OUTBOARD MAXARET</b> Component ATA:32								
PN:AC65218	MOS	06-Jun-16						OVERHAUL
SN:CA248	HRS	10144.9		TSO 0				
WC#: 32.270	AFL	6483	3000	TSO 0	9483		1870	
<b>324224 RIGHT OUTBOARD MAXARET</b> Component ATA:32								
PN:AC65216	MOS	27-Jun-22						OVERHAUL
SN:160N	HRS	12023.9		TSO 0				
WC#: 32.275	AFL	7567	3000	TSO 0	10567		2954	
<b>324225 LEFT INBOARD MAXARET</b> Component ATA:32								
PN:AC65216	MOS	22-Dec-14						OVERHAUL
SN:RJ109	HRS	9070.7		TSO 0				
WC#: 32.270	AFL	5871	3000	TSO 0	8871		1258	
<b>324226 RIGHT INBOARD MAXARET</b> Component ATA:32								
PN:AC65218	MOS	21-Jun-22						OVERHAUL
SN:6E212	HRS	12023.9		TSO 0				
WC#: 32.275	AFL	7567	3000	TSO 0	10567		2954	
<b>324260 LEFT MAIN LANDING GEAR DOOR</b> Component ATA:32								
PN:25-8UD505-235A	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:RG8547	HRS	0			TSN 0			
WC#: 32.280	AFL	0			TSN 0			
<b>324261 RIGHT MAIN LANDING GEAR DOOR</b> Component ATA:32								
PN:25-8UD505-236A	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:RG8544	HRS	0			TSN 0			
WC#: 32.280	AFL	0			TSN 0			
<b>324262 LEFT NOSE GEAR DOOR</b> Component ATA:32								
PN:25-8UD501-1A	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:RG8554	HRS	0			TSN 0			
WC#: 32.285	AFL	0			TSN 0			
<b>324263 RIGHT NOSE GEAR DOOR</b> Component ATA:32								
PN:25-8UD501-2A	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:RG8550	HRS	0			TSN 0			
WC#: 32.285	AFL	0			TSN 0			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324264 NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY Component ATA:32</b>								
PN:25-8UD503-1A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:RG8551	HRS	0		TSN 0				
WC#: 32.290	AFL	0		TSN 0				
<b>324265 LEFT MAIN LANDING GEAR FAIRING Component ATA:32</b>								
PN:25-8UD507-1A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:05290101SAL	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>324266 RIGHT MAIN LANDING GEAR FAIRING Component ATA:32</b>								
PN:25-8UD507-2A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:RG8542	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>324267 VENTRAL FAIRING ASSEMBLY Component ATA:32</b>								
PN:25-8FC307-155A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:DHB548	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>324271 LEFT BRAKE MODULATOR Component ATA:32</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.300	AFL	0		TSN 0				
<b>324272 RIGHT BRAKE MODULATOR Component ATA:32</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.300	AFL	0		TSN 0				
<b>324301 PILOT LEFT BRAKE MASTER CYLINDER Component ATA:32</b>								
PN:ACM30946	MOS/MSC	01-Apr-22	O/C	TSO 0				
SN:WH025	HRS	11959.5		TSO 0				
WC#: 32.310	AFL	7528		TSO 0				
<b>324302 PILOT RIGHT BRAKE MASTER CYLINDER Component ATA:32</b>								
PN:ACM30946	MOS/MSC	01-Apr-22	O/C	TSR 0				
SN:XD048	HRS	11959.5		TSR 0				
WC#: 32.310	AFL	7528		TSR 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>324303 COPILOT LEFT BRAKE MASTER CYLINDER</b> Component ATA:32								
PN:ACM30946	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:YM091	HRS	0		TSN 0				
WC#: 32.315	AFL	0		TSN 0				
<b>324304 COPILOT RIGHT BRAKE MASTER CYLINDER</b> Component ATA:32								
PN:ACM30946	MOS/MSC	18-Dec-15	O/C	TSO 3				
SN:2G075	HRS	9644.2		TSO 0				
WC#: 32.315	AFL	6206		TSO 0				
<b>324325 LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH</b> Component ATA:32								
PN:TP42000	MOS	06-Apr-16						OVERHAUL
SN:2654	HRS	9909	5000		14909 <sup>M</sup>		2821.8	
WC#: 32.320	AFL	6341						
<b>324326 RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH</b> Component ATA:32								
PN:TP42000	MOS	30-Apr-13						OVERHAUL
SN:2809	HRS	10537	5000		15537 <sup>M</sup>		3449.8	
WC#: 32.320	AFL	6713						
<b>324337 FORWARD HIGH PRESSURE TRANSDUCER</b> Component ATA:32								
PN:APTE-29-1000-2000SG	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:6056-7-287	HRS	0		TSN 0				
WC#: 32.325	AFL	0		TSN 0				
<b>324338 AFT HIGH PRESSURE TRANSDUCER</b> Component ATA:32								
PN:APTE-29-1000-2000SG	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:6056-7-290	HRS	0		TSN 0				
WC#: 32.325	AFL	0		TSN 0				
<b>325001 STEERING JACK</b> Component ATA:32								
PN:AIR45396-5	MOS/MSC	25-Sep-04	O/C	TSO 0				
SN:LK0410	HRS	2582.3		TSO 0				
WC#: 32.330	AFL	1805		TSO 0				
<b>325003 NOSE LANDING GEAR CONNECTING ROD</b> Component ATA:32								
PN:25-8UN433-1A	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.335	AFL	0	20000	TSN 0	20000		12387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>325007 STEERING JACK EYE END</b> <span style="float:right">Component ATA:32</span>								
PN:AIR110646	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.340	AFL	0	14400	TSN 0	14400		6787	
<b>325008 PORT WING TO FUSELAGE FAIRING</b> <span style="float:right">Component ATA:32</span>								
PN:25-6FC-601-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:DHB2029	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>325009 WING TO FUSELAGE FAIRING</b> <span style="float:right">Component ATA:32</span>								
PN:25FC5808A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:DHB2030	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>325011 NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE</b> <span style="float:right">Component ATA:32</span>								
PN:25-8UN455/*-25-8UN441/*	MOS	19-Jul-01						LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.335	AFL	0	20000	TSN 0	20000		12387	
<b>325012 FAIRING SUB ASSEMBLY</b> <span style="float:right">Component ATA:32</span>								
PN:25-8FC3603-601A	MOS/MSC	19-Jul-01	O/C					
SN:RG8545	HRS	0		TSN 0				
WC#: 32.295	AFL	0		TSN 0				
<b>325013 COVER</b> <span style="float:right">Component ATA:32</span>								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.303	AFL	0		TSN 0				
<b>325015 NOSE LANDING GEAR STEERING PIN</b> <span style="float:right">Component ATA:32</span>								
PN:25UN605	MOS	19-Jul-01		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.345	AFL	0	25000	TSN 0	25000		17387	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>325021 NOSE LANDING GEAR MAIN CASING BOLT</b>								
PN:25UN603	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.345	AFL	0	33000	TSN 0	33000		25387	
<b>325025 NOSE WHEEL STEERING ON/OFF VALVE</b>								
PN:AIR45408-0	MOS/MSC	19-Jul-01	O/C					Component ATA:32
SN:LK8509338	HRS	0		TSN 0				
WC#: 32.350	AFL	0		TSN 0				
<b>325031 NOSE WHEEL ANTI-SHIMMING VALVE</b>								
PN:AIR48284-1	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:32
SN:APB992894	HRS	0		TSN 0				
WC#: 32.355	AFL	0		TSN 0				
<b>325041 NOSE LANDING GEAR UPPER STEERING MAIN MEMBER</b>								
PN:25-UN431-1A	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.360	AFL	0	35000	TSN 0	35000		27387	
<b>325042 NOSE LANDING GEAR LOWER STEERING MAIN MEMBER</b>								
PN:25-8UN431-2A	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.360	AFL	0	35000	TSN 0	35000		27387	
<b>325051 NOSE LANDING GEAR STEERING JACK PICK-UP</b>								
PN:25-8UN263-1A	MOS	19-Jul-01		TSN 0				Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.365	AFL	0	18000	TSN 0	18000		10387	
<b>325058 NOSE LANDING GEAR STEERING SLEEVE</b>								
PN:SEE REMARKS	MOS	19-Jul-01						Component ATA:32 LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 32.365	AFL	0	20000	TSN 0	20000		12387	
<b>ATA 33 - LIGHTS</b>								
<b>330003<sup>S</sup> CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM</b>								
	MOS	03-May-21						Service ATA:33
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 33 - LIGHTS									
WC#: 33.080	AFL	7300	REF: AFMS INSPECTION B1					PKG:7,91	
<b>330007</b>	<b>MAIN CG ILLUMINATED LABEL</b>							Component	ATA:33
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.015	AFL	0		TSN 0					
<b>330008</b>	<b>FORWARD CG ILLUMINATED LABEL</b>							Component	ATA:33
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.015	AFL	0		TSN 0					
<b>3300525<sup>U</sup></b>	<b>LEFT LOGO LIGHT ASSEMBLY</b>							Component	ATA:33
PN:00033190-115	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
<b>3300526<sup>U</sup></b>	<b>RIGHT LOGO LIGHT ASSEMBLY</b>							Component	ATA:33
PN:0033190-116	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
<b>334001</b>	<b>TOP ANTI COLLISION BEACON</b>							Component	ATA:33
PN:01-0790044-55	MOS/MSC	20-Apr-22	O/C	TSN 0					
SN:11429020002	HRS	12009.9		TSN 0					
WC#: 33.020	AFL	7554		TSN 0					
<b>334002</b>	<b>BOTTOM ANTI COLLISION BEACON</b>							Component	ATA:33
PN:01-0790044-54	MOS/MSC	21-Feb-18	O/C						
SN:7116	HRS	10726							
WC#: 33.020	AFL	6832							
<b>334013</b>	<b>LEFT WING STROBE LIGHT</b>							Component	ATA:33
PN:30-0538-7	MOS/MSC	25-Oct-11	O/C						
SN:11500	HRS	6820.7							
WC#: 33.025	AFL	0							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 33 - LIGHTS</b>									
<b>334014</b>	<b>RIGHT WING STROBE LIGHT</b>							<b>Component</b>	<b>ATA:33</b>
PN:30-0538-8	MOS/MSC	25-Oct-11	O/C						
SN:10437	HRS	6820.7							
WC#: 33.025	AFL	0							
<b>334016</b>	<b>TEST LEFT WING STROBE LIGHT INTENSITY</b>							<b>Service</b>	<b>ATA:33</b>
PN:30-0538-7	MOS	29-Oct-21							
SN:11500	HRS	11847.1	400 (+50/-50)		12247.1	12297.1	159.9 (+50)		
WC#: 33.025	AFL	7469							
<b>334017</b>	<b>TEST RIGHT WING STROBE LIGHT INTENSITY</b>							<b>Service</b>	<b>ATA:33</b>
PN:30-0538-8	MOS	29-Oct-21							
SN:10437	HRS	11847.1	400 (+50/-50)		12247.1	12297.1	159.9 (+50)		
WC#: 33.025	AFL	7469							
<b>334044</b>	<b>TAIL STROBE LIGHT</b>							<b>Component</b>	<b>ATA:33</b>
PN:30-3-0531-1	MOS/MSC	25-Oct-11	O/C						
SN:9071	HRS	6820.7							
WC#: 33.040	AFL	0							
<b>334047</b>	<b>TEST TAIL STROBE LIGHT INTENSITY</b>							<b>Service</b>	<b>ATA:33</b>
PN:30-3-0531-1	MOS	29-Oct-21							
SN:9071	HRS	11847.1	400 (+50/-50)		12247.1	12297.1	159.9 (+50)		
WC#: 33.040	AFL	7469							
<b>334061</b>	<b>STROBE LIGHTS POWER SUPPLY</b>							<b>Component</b>	<b>ATA:33</b>
PN:701571	MOS/MSC	28-Sep-04	O/C						
SN:APS-9983	HRS	2582.3							
WC#: 33.045	AFL	1805							
<b>335001</b>	<b>EMERGENCY LIGHTING INERTIA SWITCH</b>							<b>Component</b>	<b>ATA:33</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.050	AFL	0		TSN 0					
<b>335025</b>	<b>NO. 1 (AA PNL) DIMMER</b>							<b>Component</b>	<b>ATA:33</b>
PN:LT52A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:15786	HRS	0		TSN 0					
WC#: 33.055	AFL	0		TSN 0					





## Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 33 - LIGHTS</b>									
335027	NO. 2 (AA PNL) DIMMER							Component	ATA:33
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.055	AFL	0		TSN 0					
335029	NO. 1 (AB PNL) DIMMER							Component	ATA:33
PN:LT52A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:15788	HRS	0		TSN 0					
WC#: 33.060	AFL	0		TSN 0					
335031	NO. 2 (AB PNL) DIMMER							Component	ATA:33
PN:LT52A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:15789	HRS	0		TSN 0					
WC#: 33.060	AFL	0		TSN 0					
335050 <sup>U</sup>	AFT EMERGENCY LIGHTS BATTERY							Component	ATA:33
PN:60-1321-1	MOS/MSC	08-Nov-13	O/C	TSO 0					
SN:19764	HRS	8133.1		TSO 0					
	AFL	5385		TSO 0					
3350501 <sup>U</sup>	FOWARD EMERGENCY LIGHTS BATTERY							Component	ATA:33
PN:60-1321-1	MOS/MSC	08-Nov-13	O/C	TSO 0					
SN:23889	HRS	8133.1		TSO 0					
	AFL	5385		TSO 0					
336027	NO. 5 POWER CONVERTER							Component	ATA:33
PN:LT52A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:15785	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
336028	NO. 6 POWER CONVERTER							Component	ATA:33
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 33.070	AFL	0		TSN 0					
336040	ESCAPE HATCH BETALIGHT "EXIT" SIGN							Component	ATA:33
PN:132848-11	MOS	11-Sep-17	72 (+24m)	TSN 0	31-Jul-23 <sup>M</sup>	31-Jul-25	321 d (+731)	REPLACE	
SN:32375	HRS	10715		TSN 0					
	AFL	6825		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340002	<b>DRAIN PITOT/STATIC DRAIN TRAPS</b>							Service	ATA:34
	MOS	25-Feb-21	24 (+2m)		25-Feb-23	25-Apr-23	165 d (+59)		
	HRS	11418.4							
WC#: 34.025	AFL	7225							
REF: AFMS OUT OF PHASE INSPECTIONS									
340003 <sup>S</sup>	<b>INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT</b>							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 34.405	AFL	6832							
REF: AFMS INSPECTION C4									
340004 <sup>S</sup>	<b>INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR</b>							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 34.410	AFL	6832							
REF: AFMS INSPECTION C7									
340005 <sup>S</sup>	<b>INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT</b>							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 34.415	AFL	6832							
REF: AFMS INSPECTION C7									
340006	<b>PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS</b>							Service	ATA:34
	MOS	25-Feb-21	24 (+2m)		25-Feb-23	25-Apr-23	165 d (+59)		
	HRS	11418.4							
WC#: 34.015	AFL	7225							
REF: AFMS OUT OF PHASE INSPECTIONS									
340007	<b>CHECK PITOT SYSTEM ISOLATION VALVES</b>							Service	ATA:34
	MOS	25-Feb-21	24 (+2m)		25-Feb-23	25-Apr-23	165 d (+59)		
	HRS	11418.4							
WC#: 34.290	AFL	7225							
REF: AFMS OUT OF PHASE INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340008 <sup>S</sup>	TEST MACH TRIM SYSTEM							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 34.270	AFL	6832							
	REF: AFMS INSPECTION D1							PKG:31,93	
340010 <sup>S</sup>	TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 34.425	AFL	6832							
	REF: AFMS INSPECTION D1							PKG:31,93	
340011 <sup>S</sup>	CHECK MACH TRIM FAIL ANNUNCIATION RELAYS							Service	ATA:34
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 34.420	AFL	6832							
	REF: AFMS INSPECTION D1							PKG:31,93	
340012	SWING CHECK NO. 1 COMPASS							Service	ATA:34
	MOS	02-Apr-22	36 (+2m)	Adj -64d	31-Jan-25	28-Mar-25	871 d (+56)		
	HRS								
WC#: 34.095	AFL								
	REF: AFMS OUT OF PHASE INSPECTIONS								
340012	SWING CHECK NO. 2 COMPASS							Service	ATA:34
	MOS	02-Apr-22	36 (+2m)	Adj -64d	31-Jan-25	28-Mar-25	871 d (+56)		
	HRS								
WC#: 34.095	AFL								
	REF: AFMS OUT OF PHASE INSPECTIONS								
340012	SWING CHECK STANDBY COMPASS							Service	ATA:34
	MOS	02-Apr-22	36 (+2m)	Adj -64d	28-Jan-25	28-Mar-25	868 d (+59)		
	HRS								
WC#: 34.095	AFL								
	REF: AFMS OUT OF PHASE INSPECTIONS								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340013	COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME							Service	ATA:34
	DAYS/MSC	26-Apr-11	A/R						
	HRS								
WC#: 34.020	AFL								
REF: AFMS OUT OF PHASE INSPECTIONS									
340013-U1 <sup>U</sup>	POST PAINT OR MAINTENANCE IN THE AREA AFFECTING AIRFLOW OVER THESTATIC PORT AND RVSM CHECK							Service	ATA:34
	MOS/MSC	26-Apr-11	-						
	HRS	0							
	AFL	0							
340022 <sup>U</sup>	AVIONICS DOOR REMOVAL							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	-	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
3400515 <sup>U</sup>	EXTERNAL CAPACITOR							Component	ATA:34
PN:071-1270-01	MOS/MSC	01-Feb-03	O/C						
SN:2404	HRS	1256.1							
	AFL	915							
3400547 <sup>U</sup>	ACCELEROMETER (GPWS)							Component	ATA:34
PN:2231230-5-A	MOS/MSC	27-Mar-08	O/C						
SN:1116	HRS	5400							
	AFL	3609							
3400547.1 <sup>U S</sup>	EGPWS TERRAIN DATABASE							Service	ATA:34
	MOS/MSC	21-Aug-15	- <sup>S</sup>						
	HRS	9440.6							
	AFL	6083							
341001	LEFT PITOT PRESSURE HEAD							Component	ATA:34
PN:5D853JF	MOS/MSC	08-Jul-21	O/C	TSN 0					
SN:15300	HRS	11762.6		TSN 0					
WC#: 34.010	AFL	7415		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
<b>341002 RIGHT PITOT PRESSURE HEAD</b> Component ATA:34								
PN:853JF1	MOS/MSC	22-Apr-14	O/C					
SN:14223	HRS	8594.3						
WC#: 34.010	AFL	5601						
<b>341073 LEFT ALTIMETER</b> Component ATA:34								
PN:4016341-905	MOS/MSC	03-May-21	O/C	TSR 0				
SN:80111776	HRS	11562.2		TSR 0				
WC#: 34.030	AFL	7300		TSR 0				
<b>341074 RIGHT ALTIMETER</b> Component ATA:34								
PN:4016341-905	MOS/MSC	19-Jul-09	O/C					
SN:01049512	HRS	6021.7						
WC#: 34.035	AFL	4065						
<b>341085 TEST LEFT ALTIMETER (FAR 91.411)</b> Service ATA:34								
PN:4016341-905	MOS	03-May-21	24		31-May-23		260 d	MANDATORY
SN:80111776	HRS							
WC#: 34.030	AFL							
REF: FAR FAR PART 91								
<b>341086 TEST RIGHT ALTIMETER (FAR 91.411)</b> Service ATA:34								
PN:4016341-905	MOS	25-Feb-21	24		28-Feb-23		168 d	MANDATORY
SN:01049512	HRS							
WC#: 34.035	AFL							
REF: FAR FAR PART 91								
<b>341097 STANDBY ALTIMETER</b> Component ATA:34								
PN:27101-01-01	MOS/MSC	25-Apr-11	O/C					
SN:M007437	HRS	0						
WC#: 34.040	AFL	0						
<b>341103 TEST STANDBY ALTIMETER (FAR 91.411)</b> Service ATA:34								
PN:27101-01-01	MOS	25-Feb-21	24		28-Feb-23		168 d	MANDATORY
SN:M007437	HRS							
WC#: 34.040	AFL							
REF: FAR FAR PART 91								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
341109	LEFT AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.050	AFL	0			TSN 0			
341110	RIGHT AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.055	AFL	0			TSN 0			
341111	NO. 1 AIRSPEED REFERENCE PANEL							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.315	AFL	0			TSN 0			
341112	NO. 2 AIRSPEED REFERENCE PANEL							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.315	AFL	0			TSN 0			
341115	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.045	AFL	0			TSN 0			
341163	LEFT SAT/TAS INDICATOR							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.320	AFL	0			TSN 0			
341164	RIGHT SAT/TAS INDICATOR							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.320	AFL	0			TSN 0			
341195	VOICE ADVISORY							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.060	AFL	0			TSN 0			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
341228	NO. 1 AIR DATA COMPUTER							Component	ATA:34
PN:7000700-668	MOS/MSC	05-Aug-22	O/C						
SN:96106908	HRS	12078.9							
WC#: 34.065	AFL	7605							
REF: GENERIC NO REF									
341229	NO. 2 AIR DATA COMPUTER							Component	ATA:34
PN:7000700-668	MOS/MSC	08-Sep-22	O/C	TSR 0					
SN:98128257	HRS	12086.8		TSR 0					
WC#: 34.066	AFL	7611		TSR 0					
REF: GENERIC NO REF									
341230	NO. 1 AIR DATA MODULE							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.325	AFL	0		TSN 0					
341231	NO. 2 AIR DATA MODULE							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.325	AFL	0		TSN 0					
341234	SIGNAL INTERFERENCE ADAPTER							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.330	AFL	0		TSN 0					
341235	(ESIS) MAGNETOMETER							Component	ATA:34
PN:19004-00-01	MOS/MSC	28-Oct-08	O/C	TSO 0					
SN:M014430	HRS	5676		TSO 0					
WC#: 34.485	AFL	3820		TSO 0					
341237	AIR DATA ESIS UNIT							Component	ATA:34
PN:27101-01-01	MOS/MSC	03-Sep-07	O/C	TSO 0					
SN:M007437	HRS	4869		TSO 0					
WC#: 34.435	AFL	3262		TSO 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
341238	TEST AIR DATA ESIS UNIT (FAA 91.411)							Service	ATA:34
PN:27101-01-01	MOS	25-Feb-21	24		28-Feb-23		168 d	MANDATORY	
SN:M007437	HRS								
WC#: 34.435	AFL								
REF: FAR FAR PART 91									
341240	TEST NO.1 AIR DATA COMPUTER (FAA 91.411)							Service	ATA:34
PN:7000700-668	MOS	05-Aug-22	24		31-Aug-24		718 d	MANDATORY	
SN:96106908	HRS								
WC#: 34.065	AFL								
REF: FAR FAR PART 91									
341241	TEST NO.2 AIR DATA COMPUTER (FAA 91.411)							Service	ATA:34
PN:7000700-668	MOS	08-Sep-22	24		30-Sep-24		748 d	MANDATORY	
SN:98128257	HRS								
WC#: 34.066	AFL								
REF: FAR FAR PART 91									
341276	RADIO ALTIMETER UNIT							Component	ATA:34
PN:7001840-912	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1039157	HRS	0		TSN 0					
WC#: 34.070	AFL	0		TSN 0					
341279	LEFT RADIO ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:20266	HRS	0		TSN 0					
WC#: 34.075	AFL	0		TSN 0					
341281	RIGHT RADIO ALTIMETER ANTENNA							Component	ATA:34
PN:S67-2002	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:15058	HRS	0		TSN 0					
WC#: 34.080	AFL	0		TSN 0					
342013	EMERGENCY GYRO HORIZON INDICATOR							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.090	AFL	0		TSN 0					





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
342014	SECONDARY FLIGHT DISPLAY							Component	ATA:34
PN:39205-00-01	MOS/MSC	04-Nov-08	O/C						
SN:M007649	HRS	5685.3			TSO 0				
WC#: 34.490	AFL	3829			TSO 0				
342061	NO. 1 HORIZONTAL SITUATIONAL INDICATION (HSI)							Component	ATA:34
PN:7003110-901	MOS/MSC	05-Jul-12	O/C						
SN:98101444	HRS	7278							
	AFL	4861							
342062	NO. 2 HORIZONTAL SITUATIONAL INDICATION (HSI)							Component	ATA:34
PN:7003110-901	MOS/MSC	09-Mar-06	O/C						
SN:97010191	HRS	3781							
	AFL	2535							
342097	STANDBY COMPASS (E2B) INDICATOR							Component	ATA:34
PN:KCA0104W	MOS/MSC	19-Jul-01	O/C		TSN 0				
SN:AN3640201	HRS	0			TSN 0				
WC#: 34.106	AFL	0			TSN 0				
342145	NO. 1 DATA LOADER							Component	ATA:34
PN:G7226-02	MOS/MSC	03-Jul-16	O/C		TSO 0				
SN:2504	HRS	10077.1			TSO 0				
WC#: 34.115	AFL	6441			TSO 0				
342220	NO. 1 FLIGHT MANAGEMENT COMPUTER							Component	ATA:34
PN:7018879-03014	MOS/MSC	02-Oct-13	O/C						
SN:01083382	HRS	8133.1							
WC#: 34.350	AFL	5385							
342221	NO. 2 FLIGHT MANAGEMENT COMPUTER							Component	ATA:34
PN:7018879-03014	MOS/MSC	29-Aug-12	O/C						
SN:2093717	HRS	7383							
WC#: 34.350	AFL	4930							
342240	REMOTE TUNING UNIT							Component	ATA:34
PN:AI-RCI-170293	MOS/MSC	19-Jul-01	O/C						
SN:030101364	HRS	0			TSN 0				
WC#: 34.340	AFL	0			TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
342253	NO. 1 COMPASS FLUX VALVE							Component	ATA:34
PN:7010133	MOS/MSC		O/C						
SN:96033084	HRS	3360							
WC#: 34.120	AFL								
342254	NO. 2 COMPASS FLUX VALVE							Component	ATA:34
PN:7010133	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1035901	HRS	0		TSN 0					
WC#: 34.120	AFL	0		TSN 0					
342265	NO. 1 AHRS COMPUTER							Component	ATA:34
PN:7003360-943	MOS/MSC	10-Mar-21	O/C						
SN:89071391	HRS	11424							
WC#: 34.125	AFL	7228							
342266	NO. 2 AHRS COMPUTER							Component	ATA:34
PN:7003360-943	MOS/MSC	15-Dec-15	O/C						
SN:97053819	HRS	9644.2							
WC#: 34.125	AFL	6206							
342289	NO. 1 AHRS CONTROLLER							Component	ATA:34
PN:7004545-901	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:112409	HRS	0		TSN 0					
WC#: 34.140	AFL	0		TSN 0					
342290	NO. 2 AHRS CONTROLLER							Component	ATA:34
PN:7004545-901	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:122425	HRS	0		TSN 0					
WC#: 34.140	AFL	0		TSN 0					
342501	NO. 1 MULTIFUNCTION DISPLAY							Component	ATA:34
PN:7003110-901	MOS/MSC	05-Jul-12	O/C						
SN:98101444	HRS	7277.9							
WC#: 34.130	AFL	4861							
342502	NO. 2 MULTIFUNCTION DISPLAY							Component	ATA:34
PN:7003110-901	MOS/MSC	09-Mar-06	O/C						
SN:97010191	HRS	3781.4		TSR 0					
WC#: 34.135	AFL	2535		TSR 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
<b>342503 NO. 1 ELECTRONIC FLIGHT INSTRUMENT SYSTEM ATTITUDE DIRECTION INDICATOR(ADI)</b> Component ATA:34								
PN:7003110-901	MOS/MSC	01-Jul-12	O/C					
SN:88052710	HRS	7273						
	AFL	4859						
<b>342504 NO. 2 ELECTRONIC FLIGHT INSTRUMENT SYSTEM ATTITUDE DIRECTION INDICATOR(ADI)</b> Component ATA:34								
PN:7003110-901	MOS/MSC	01-Oct-13	O/C					
SN:90044728	HRS	8133						
	AFL	5385						
<b>342513 NO. 1 PRIMARY FLIGHT DISPLAY</b> Component ATA:34								
PN:7003110-901	MOS/MSC	01-Jul-12	O/C					
SN:88052710	HRS	7273.4						
WC#: 34.130	AFL	4859						
<b>342514 NO. 2 PRIMARY FLIGHT DISPLAY</b> Component ATA:34								
PN:7003110-901	MOS/MSC	01-Oct-13	O/C					
SN:90044728	HRS	8133.1						
WC#: 34.135	AFL	5385						
<b>342516 NO. 1 REMOTE INSTRUMENT CONTROL</b> Component ATA:34								
PN:7011345-901	MOS/MSC	07-Mar-18	O/C					
SN:98081210	HRS	10727						
WC#: 34.145	AFL	6833						
<b>342517 NO. 2 REMOTE INSTRUMENT CONTROL</b> Component ATA:34								
PN:7011345-911	MOS/MSC	20-Jun-17	O/C		TSR 2			
SN:1031491	HRS	10697			TSR 0			
WC#: 34.145	AFL	6813			TSR 0			
<b>342525 NO. 1 EFIS DISPLAY PROCESSOR</b> Component ATA:34								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0			TSN 0			
WC#: 34.335	AFL	0			TSN 0			
<b>342526 NO. 2 EFIS DISPLAY PROCESSOR</b> Component ATA:34								
PN:7517900-55012	MOS/MSC	10-Apr-15	O/C					
SN:01064707	HRS	9204.2						
WC#: 34.335	AFL	5943						



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
<b>342527 NO. 1 EFIS SYMBOL GENERATOR</b> Component ATA:34								
PN:7011674-119	MOS/MSC	25-Jul-22	O/C		TSR 0			
SN:99011529	HRS	12037			TSR 0			
WC#: 34.150	AFL	7577			TSR 0			
<b>342528 NO. 2 EFIS SYMBOL GENERATOR</b> Component ATA:34								
PN:7011674-119	MOS/MSC	15-Dec-14	O/C					
SN:01071851	HRS	8971.9						
WC#: 34.150	AFL	5831						
<b>342530 MULTIFUNCTION SYMBOL GENERATOR</b> Component ATA:34								
PN:7011675-119	MOS/MSC	26-Jun-07	O/C		TSO 0			
SN:99120913	HRS	4733.2			TSO 0			
WC#: 34.150	AFL	3166			TSO 0			
<b>342537 NO. 1 DISPLAY CONTROL PANEL</b> Component ATA:34								
PN:7005819-707	MOS/MSC	05-May-15	O/C					
SN:1034197	HRS	9226						
WC#: 34.155	AFL	5955						
<b>342538 NO. 2 DISPLAY CONTROL PANEL</b> Component ATA:34								
PN:7005819-707	MOS/MSC	05-May-15	O/C					
SN:1044232	HRS	9226						
WC#: 34.155	AFL	5955						
<b>342539 MULTI FUNCTION EFIS CONTROL</b> Component ATA:34								
PN:7007062-921	MOS/MSC	03-May-21	O/C		TSR 0			
SN:85050121	HRS	11562.2			TSR 0			
WC#: 34.160	AFL	7300			TSR 0			
<b>342541 NO. 1 CONSOLE CONTROL DISPLAY UNIT</b> Component ATA:34								
PN:2888-01-1	MOS/MSC	05-May-15	O/C					
SN:942	HRS	9226.2						
WC#: 34.445	AFL	5955						
<b>342542 NO. 2 CONSOLE CONTROL DISPLAY UNIT</b> Component ATA:34								
PN:G7830-03	MOS/MSC	03-Dec-21	O/C		TSN 0			
SN:66474	HRS	11882.7			TSN 0			
WC#: 34.450	AFL	7485			TSN 0			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
342545	<b>NO. 1 FLUX DETECTOR</b>							Component	ATA:34
PN:7010133	MOS/MSC	29-Oct-07	O/C						
SN:96033084	HRS	5001.4		TSR 0					
WC#: 34.500	AFL	3360		TSR 0					
342547	<b>NO. 2 FLUX DETECTOR</b>							Component	ATA:34
PN:7010133	MOS/MSC	19-Jul-01	O/C						
SN:01035901	HRS	0		TSN 0					
WC#: 34.500	AFL	0		TSN 0					
342561	<b>TCAS COMPUTER</b>							Component	ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.175	AFL	0		TSN 0					
342562	<b>TCAS (TOP) ANTENNA</b>							Component	ATA:34
PN:7514081-910	MOS/MSC	22-Mar-22	O/C		TSO 0				
SN:0001C217	HRS	11959.5			TSO 0				
WC#: 34.180	AFL	7528			TSO 0				
342563	<b>TCAS (BOTTOM) ANTENNA</b>							Component	ATA:34
PN:S65-5366-11L	MOS/MSC	19-Jul-01	O/C		TSN 0				
SN:3962	HRS	0			TSN 0				
WC#: 34.180	AFL	0			TSN 0				
342601	<b>NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT</b>							Component	ATA:34
PN:7510100-731	MOS/MSC	22-Nov-21	O/C						
SN:96061924	HRS	11882.3							
WC#: 34.185	AFL	7484							
342602	<b>NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT</b>							Component	ATA:34
PN:7510100-731	MOS/MSC	19-Feb-18	O/C						
SN:90100551	HRS	10726							
WC#: 34.185	AFL	6832							
342624	<b>NO. 1 ADF ANTENNA</b>							Component	ATA:34
PN:7510300-901	MOS/MSC	06-Jul-22	O/C		TSN 0				
SN:2204S656	HRS	12037			TSN 0				
WC#: 34.190	AFL	7577			TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
342625	NO. 2 ADF ANTENNA							Component ATA:34
PN:7510300-901	MOS/MSC	08-Jul-22	O/C		TSN 0			
SN:22045655	HRS	12025.8			TSN 0			
WC#: 34.190	AFL	7570			TSN 0			
342640	EGPWS COMPUTER							Component ATA:34
PN:965-1076-001-206-206	MOS/MSC	21-Jul-10	O/C					
SN:2051	HRS	6547						
WC#: 34.455	AFL	4396						
343001	GLIDE SLOPE AERIAL							Component ATA:34
PN:17-21F6	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:7286	HRS	0			TSN 0			
WC#: 34.195	AFL	0			TSN 0			
343013	MARKER AERIAL							Component ATA:34
PN:17-5C	MOS/MSC	19-Jul-01	O/C					
SN:7173	HRS	0			TSN 0			
WC#: 34.200	AFL	0			TSN 0			
344001	NO. 1 WEATHER RADAR CONTROL PANEL							Component ATA:34
PN:7008471-407	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:1045711	HRS	0			TSN 0			
WC#: 34.205	AFL	0			TSN 0			
344002	NO. 2 WEATHER RADAR CONTROL PANEL							Component ATA:34
PN:7008471-407	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:1045719	HRS	0			TSN 0			
WC#: 34.205	AFL	0			TSN 0			
344016	RADAR CHECKLIST MODULE							Component ATA:34
PN:7008266-904	MOS/MSC	03-Jun-03	O/C					
SN:98121729	HRS	1644.3						
WC#: 34.215	AFL	1152						
344036	ISOLATION VALVE							Component ATA:34
PN:25MC2175103AA01	MOS/MSC	19-Jul-01	O/C		TSN 0			
SN:FR019BE	HRS	0			TSN 0			
WC#: 34.220	AFL	0			TSN 0			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
<b>3440503<sup>U</sup></b>		<b>TRANSCEIVER/ANTENNA</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
<b>345001</b>		<b>NO. 1 VHF NAVIGATION RECEIVER</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.300	AFL	0			TSN 0				
<b>345002</b>		<b>NO. 2 VHF NAVIGATION RECEIVER</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.300	AFL	0			TSN 0				
<b>345003</b>		<b>DATA BASE UNIT</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.503	AFL	0			TSN 0				
<b>345008</b>		<b>SENSOR UNIT DISPLAY</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.295	AFL	0			TSN 0				
<b>345009</b>		<b>SENSOR DRIVER DISPLAY</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.295	AFL	0			TSN 0				
<b>345015</b>		<b>ILS CONVERTER</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.300	AFL	0			TSN 0				
<b>345019</b>		<b>NO. 1 ADF RECEIVER</b>						<b>Component</b>	<b>ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 34.310	AFL	0			TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
<b>345020</b>	<b>NO. 2 ADF RECEIVER</b>							<b>Component ATA:34</b>
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.310	AFL	0		TSN 0				
<b>345037</b>	<b>LEFT VOR/LOC AERIAL</b>							<b>Component ATA:34</b>
PN:S65-247-12	MOS/MSC	27-Oct-05	O/C	TSN 0				
SN:5732	HRS	3470.1		TSN 0				
WC#: 34.230	AFL	2345		TSN 0				
<b>345038</b>	<b>RIGHT VOR/LOC AERIAL</b>							<b>Component ATA:34</b>
PN:S65-247-12	MOS/MSC	27-Oct-05	O/C	TSN 0				
SN:5733	HRS	3470.1		TSN 0				
WC#: 34.230	AFL	2345		TSN 0				
<b>3450522<sup>U</sup></b>	<b>ATC ANTENNA</b>							<b>Component ATA:34</b>
PN:S65-5366-8L	MOS/MSC	19-Jul-01	O/C					
SN:5276	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>345109</b>	<b>NO. 1 DME AERIAL</b>							<b>Component ATA:34</b>
PN:10A1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8207	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
<b>345110</b>	<b>NO. 2 DME AERIAL</b>							<b>Component ATA:34</b>
PN:10A1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8240	HRS	0		TSN 0				
WC#: 34.250	AFL	0		TSN 0				
<b>345133</b>	<b>NO. 1 ATC TRANSPONDER AERIAL</b>							<b>Component ATA:34</b>
PN:10A1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8231	HRS	0		TSN 0				
WC#: 34.255	AFL	0		TSN 0				
<b>345134</b>	<b>NO. 2 ATC TRANSPONDER AERIAL</b>							<b>Component ATA:34</b>
PN:10A1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:8236	HRS	0		TSN 0				
WC#: 34.255	AFL	0		TSN 0				





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 34 - NAVIGATION</b>								
345135	FORWARD TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.460	AFL	0		TSN 0				
345136	AFT TRANSPONDER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.465	AFL	0		TSN 0				
345205	NO. 1 DME TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.305	AFL	0		TSN 0				
345206	NO. 2 DME TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 34.305	AFL	0		TSN 0				
345217	NO. 1 ATC TRANSPONDER							Component ATA:34
PN:7510700-764	MOS/MSC	20-Jun-17	O/C					
SN:98113418	HRS	10697						
WC#: 34.260	AFL	6813						
345218	NO. 2 ATC TRANSPONDER							Component ATA:34
PN:7510700-764	MOS/MSC	20-Jun-17	O/C					
SN:01056410	HRS	10697						
WC#: 34.260	AFL	6813						
345229	SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413)							Service ATA:34
PN:7510700-764	MOS	25-Feb-21	24		28-Feb-23		168 d	MANDATORY
SN:98113418	HRS							
WC#: 34.260	AFL							
REF: FAR FAR PART 91								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
345230	SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413)							Service	ATA:34
PN:7510700-764	MOS	25-Feb-21	24		28-Feb-23		168 d	MANDATORY	
SN:01056410	HRS								
WC#: 34.260	AFL								
REF: FAR FAR PART 91									
345305	MACH TRIM COMPUTER							Component	ATA:34
PN:822-0872-001	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:CTDG	HRS	0		TSN 0					
WC#: 34.270	AFL	0		TSN 0					
345309	AFIS DMU							Component	ATA:34
PN:400-045500-003	MOS/MSC	19-Jul-01	O/C						
SN:2518	HRS	0		TSN 0					
WC#: 34.470	AFL	0		TSN 0					
345310	AFIS CONFIGURATION MODULE							Component	ATA:34
PN:31990-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:10138	HRS	0		TSN 0					
WC#: 34.475	AFL	0		TSN 0					
345404	NO. 1 GPS SENSOR UNIT							Component	ATA:34
PN:HG2021GD02	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:01015700	HRS	0		TSN 0					
WC#: 34.275	AFL	0		TSN 0					
345405	NO. 2 GPS SENSOR UNIT							Component	ATA:34
PN:HG2021GD06	MOS/MSC	25-Jul-21	O/C						
SN:0344	HRS	11768.3							
WC#: 34.275	AFL	7421							
345406	NO. 1 GPS ANTENNA							Component	ATA:34
PN:S67-1575-20	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:5775	HRS	0		TSN 0					
WC#: 34.280	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
345407	NO. 2 GPS ANTENNA							Component	ATA:34
PN:S67-1575-20	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:5764	HRS	0		TSN 0					
WC#: 34.280	AFL	0		TSN 0					
345413	NO. 1 CONFIGURATION STRAPPING UNIT							Component	ATA:34
PN:7014940-902	MOS/MSC	19-Jul-01	O/C						
SN:01014839	HRS	0		TSN 0					
WC#: 34.285	AFL	0		TSN 0					
345414	NO. 2 CONFIGURATION STRAPPING UNIT							Component	ATA:34
PN:7014940-902	MOS/MSC	19-Jul-01	O/C						
SN:01034979	HRS	0		TSN 0					
WC#: 34.285	AFL	0		TSN 0					
3460502 <sup>U</sup>	NO.1 COMPUTER							Component	ATA:34
PN:7000700-668	MOS/MSC	24-Sep-16	O/C	TSN 0					
SN:01079099	HRS	10258.7		TSN 0					
	AFL	6557		TSN 0					
3460503 <sup>U</sup>	NO.2 COMPUTER							Component	ATA:34
PN:700700-668	MOS/MSC	24-Sep-16	O/C						
SN:010448997	HRS	10258.7							
	AFL	6557							
349001 <sup>U</sup>	NAVIGATION DATA BASE UPDATE							Service	ATA:34
	MOS/MSC	08-Sep-22	DUE		05-Oct-22 <sup>M</sup>		22 d		
	HRS	12086.8							
	AFL	7611							
<b>ATA 35 - OXYGEN</b>									
350001 <sup>S</sup>	CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE							Service	ATA:35
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 35.110	AFL	7300							
REF: AFMS INSPECTION B4								PKG:10,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
350002 <sup>S</sup>	FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE							Service	ATA:35
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 35.035	AFL	6832							
					REF: AFMS INSPECTION D2			PKG:32,93	
350004 <sup>S</sup>	TEST/INSPECT PASSENGER OXYGEN SYSTEM							Service	ATA:35
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 35.075	AFL	7513							
					REF: AFMS INSPECTION E2			PKG:44,94	
350005 <sup>S</sup>	CHECK BAROMATIC CONTROL VALVE							Service	ATA:35
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 35.100	AFL	7513							
					REF: AFMS INSPECTION E2			PKG:44,94	
350006 <sup>S</sup>	INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES							Service	ATA:35
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 35.115	AFL	7513							
					REF: AFMS INSPECTION E4			PKG:46,94	
350007 <sup>S</sup>	INSPECT PORTABLE BREATHING EQUIPMENT							Service	ATA:35
	MOS	13-Mar-22	12 <sup>S</sup> (+1m/-1m)						
	HRS	11930.2							
WC#: 35.120	AFL	7513							
					REF: AFMS INSPECTION E4			PKG:46,94	
350008 <sup>S</sup>	INSPECT OXYGEN CYLINDERS							Service	ATA:35
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 35.105	AFL	6832							
					REF: AFMS INSPECTION C7			PKG:25,92	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
3500502 <sup>U</sup>		OXYGEN VALVE LEFT CONSOLE						Component	ATA:35
PN:WKA29720-2	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
351001		MASTER OXYGEN SUPPLY VALVE						Component	ATA:35
PN:SDV1012	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:11890	HRS	0		TSN 0					
WC#: 35.030	AFL	0		TSN 0					
351013		OXYGEN PRESSURE GAUGE						Component	ATA:35
PN:18430901-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:9464	HRS	0		TSN 0					
WC#: 35.040	AFL	0		TSN 0					
351014		ALTERNATIVE OXYGEN PRESSURE GAUGE						Component	ATA:35
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.040	AFL	0		TSN 0					
351015		OXYGEN CHARGING FILTER ASSEMBLY						Component	ATA:35
PN:WKA27942-2	MOS/MSC	14-Aug-20	O/C						
SN:2196	HRS	11060							
WC#: 35.215	AFL	7036							
351025		OXYGEN REDUCING VALVE						Component	ATA:35
PN:WKA29720-2	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 35.045	AFL	0		TSN 0					
351031		PILOT OXYGEN MASK						Component	ATA:35
PN:MF10-03-02	MOS	03-May-21	72	TSO 0	03-May-27		1693 d	OVERHAUL	
SN:1059311	HRS	11562.2		TSO 0					
WC#: 35.050	AFL	7300		TSO 0					
351032		COPILOT OXYGEN MASK						Component	ATA:35
PN:MC10-03-02	MOS	19-Feb-18	72		29-Feb-24 <sup>M</sup>		534 d	OVERHAUL	
SN:82852	HRS	7474.9		TSO 0					
WC#: 35.050	AFL	4999		TSO 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
<b>351043</b>	<b>LEFT OXYGEN OUTLET VALVE</b>							<b>Component</b>	<b>ATA:35</b>
PN:DPB181-01	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:30601	HRS	0		TSN 0					
WC#: 35.055	AFL	0		TSN 0					
<b>351044</b>	<b>RIGHT OXYGEN OUTLET VALVE</b>							<b>Component</b>	<b>ATA:35</b>
PN:DPB181-01	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:29401	HRS	0		TSN 0					
WC#: 35.055	AFL	0		TSN 0					
<b>351050<sup>U</sup></b>	<b>PASSANGER OXYGEN ON/OFF VALVE</b>							<b>Component</b>	<b>ATA:35</b>
PN:SDV1012	MOS/MSC	19-Jul-01	O/C						
SN:12053	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>351051</b>	<b>NO. 1 PASSENGER OXYGEN MASK</b>							<b>Component</b>	<b>ATA:35</b>
PN:289-601-228	MOS	20-Jan-22	72	TSN 0	20-Jan-28		1955 d	OVERHAUL	
SN:UNKNOWN	HRS	11886		TSN 0					
WC#: 35.150	AFL	7487		TSN 0					
								REF: GENERIC CMM	
<b>351052</b>	<b>NO. 2 PASSENGER OXYGEN MASK</b>							<b>Component</b>	<b>ATA:35</b>
PN:289-601-228	MOS	20-Jan-22	72	TSN 0	20-Jan-28		1955 d	OVERHAUL	
SN:UNKNOWN	HRS	11886		TSN 0					
WC#: 35.150	AFL	7487		TSN 0					
								REF: GENERIC CMM	
<b>351053</b>	<b>NO. 3 PASSENGER OXYGEN MASK</b>							<b>Component</b>	<b>ATA:35</b>
PN:289-601-228	MOS	24-Jan-22	72	TSN 0	24-Jan-28		1959 d	OVERHAUL	
SN:UNKNOWN	HRS	11886		TSN 0					
WC#: 35.155	AFL	7487		TSN 0					
								REF: GENERIC CMM	
<b>351054</b>	<b>NO. 4 PASSENGER OXYGEN MASK</b>							<b>Component</b>	<b>ATA:35</b>
PN:289-601-228	MOS	20-Jan-22	72	TSN 0	20-Jan-28		1955 d	OVERHAUL	
SN:UNKNOWN	HRS	11886		TSN 0					
WC#: 35.155	AFL	7487		TSN 0					
								REF: GENERIC CMM	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
351055	<b>NO. 5 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.160	AFL	6664		TSN 0					
REF: GENERIC CMM									
351056	<b>NO. 6 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	20-Jan-22	72	TSN 0	20-Jan-28		1955 d	OVERHAUL	
SN:UNKNOWN	HRS	11886		TSN 0					
WC#: 35.160	AFL	7487		TSN 0					
REF: GENERIC CMM									
351057	<b>NO. 7 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.170	AFL	6664		TSN 0					
REF: GENERIC CMM									
351058	<b>NO. 8 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.170	AFL	6664		TSN 0					
REF: GENERIC CMM									
351059	<b>NO. 9 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.180	AFL	6664		TSN 0					
REF: GENERIC CMM									
351060	<b>NO. 10 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.180	AFL	6664		TSN 0					
REF: GENERIC CMM									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
351061	<b>NO. 11 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.190	AFL	6664		TSN 0					
				REF: GENERIC CMM					
351062	<b>NO. 12 PASSENGER OXYGEN MASK</b>							Component	ATA:35
PN:289-601-228	MOS	08-Dec-16	72		08-Dec-22 <sup>M</sup>		86 d	OVERHAUL	
SN:UNKNOWN	HRS	10443.2		TSN 0					
WC#: 35.190	AFL	6664		TSN 0					
				REF: GENERIC CMM					
351080	<b>NO. 1 MASK DEPLOYMENT CONTAINER</b>							Component	ATA:35
PN:833-649-01	MOS/MSC	19-Jul-01	O/C						
SN:0330	HRS	0		TSN 0					
WC#: 35.195	AFL	0		TSN 0					
351081	<b>NO. 2 MASK DEPLOYMENT CONTAINER</b>							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1267	HRS	0		TSN 0					
WC#: 35.195	AFL	0		TSN 0					
351082	<b>NO. 3 MASK DEPLOYMENT CONTAINER</b>							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1272	HRS	0		TSN 0					
WC#: 35.200	AFL	0		TSN 0					
351083	<b>NO. 4 MASK DEPLOYMENT CONTAINER</b>							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1305	HRS	0		TSN 0					
WC#: 35.200	AFL	0		TSN 0					
351084	<b>NO. 5 MASK DEPLOYMENT CONTAINER</b>							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1474	HRS	0		TSN 0					
WC#: 35.205	AFL	0		TSN 0					





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
351085	NO. 6 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1478	HRS	0		TSN 0					
WC#: 35.205	AFL	0		TSN 0					
351086	NO. 7 MASK DEPLOYMENT CONTAINER							Component	ATA:35
PN:833-648-01	MOS/MSC	19-Jul-01	O/C						
SN:1489	HRS	0		TSN 0					
WC#: 35.210	AFL	0		TSN 0					
351093	OXYGEN PRESSURE SWITCH							Component	ATA:35
PN:1106P76-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:874	HRS	0		TSN 0					
WC#: 35.125	AFL	0		TSN 0					
351101	NO. 1 OXYGEN CYLINDER							Component	ATA:35
PN:WKA37447	MOS/MSC	28-Jan-19	O/C	TSO 0					
SN:788960	HRS	10750		TSO 0					
WC#: 35.010	AFL	6853		TSO 0					
351102	NO. 2 OXYGEN CYLINDER							Component	ATA:35
PN:WKA37447	MOS/MSC	28-Jan-19	O/C						
SN:181903	HRS	10750							
WC#: 35.015	AFL	6853							
351103	NO. 3 OXYGEN CYLINDER							Component	ATA:35
PN:176531-35	MOS/MSC	24-Mar-14	O/C						
SN:817570/7029	HRS								
WC#: 35.020	AFL								
351110	HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER							Service	ATA:35
PN:WKA37447	MOS	14-Aug-20	60		14-Aug-25		1066 d		
SN:788960	HRS								
WC#: 35.010	AFL								
REF: GENERIC CMM									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
351110	HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER							Service	ATA:35
PN:WKA37447	MOS	14-Aug-20	60		14-Aug-25		1066 d		
SN:181903	HRS								
WC#: 35.015	AFL								
REF: GENERIC CMM									
351110	HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER							Service	ATA:35
PN:176531-35	MOS	14-Aug-20	60		14-Aug-25		1066 d		
SN:817570/7029	HRS								
WC#: 35.020	AFL								
REF: GENERIC CMM									
352001	ON/OFF OXYGEN VALVE							Component	ATA:35
PN:SDV1012	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:12053	HRS	0		TSN 0					
WC#: 35.065	AFL	0		TSN 0					
352007	BAROMATIC VALVE							Component	ATA:35
PN:K39117/2	MOS/MSC	22-Feb-11	O/C						
SN:2296	HRS	6820.7		TSN 0					
WC#: 35.070	AFL	4589		TSN 0					
353001	PORTABLE OXYGEN BOTTLE							Component	ATA:35
PN:176960-14	MOS/MSC	03-May-21	O/C	TSO 0					
SN:015271	HRS	11562.2		TSO 0					
WC#: 35.080	AFL	7300		TSO 0					
353007	HYDROSTATIC TEST PORTABLE OXYGEN BOTTLE							Service	ATA:35
PN:176960-14	MOS	03-May-21	60		03-May-26		1328 d	MANDATORY	
SN:015271	HRS								
WC#: 35.080	AFL								
353031	(PBE) PROTECTIVE BREATHING EQUIPMENT							Component	ATA:35
PN:802300-14	MOS	27-Jun-22	120		30-Apr-32		3517 d	LIFE LIMIT	
SN:E22040546	HRS	12023.9		TSN 0					
WC#: 35.085	AFL	7567		TSN 0					
Manufacture Date:: 30-Apr-22 REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
354000	AUTOMATIC SHUT OFF VALVE							Component	ATA:35
PN:WKA35964-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1026	HRS	0		TSN 0					
WC#: 35.130	AFL	0		TSN 0					
<b>ATA 38 - WATER/WASTE</b>									
380001 <sup>S</sup>	INSPECT TOILET AND GALLEY WATER SYSTEMS							Service	ATA:38
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 38.010	AFL	7300							
								PKG:12,91	
<b>ATA 44 - CABIN SYSTEMS</b>									
4420510 <sup>U</sup>	SPEAKER (DIVAN)							Component	ATA:44
PN:AI-620	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							
4420511 <sup>U</sup>	NO.1 SPEAKER (MIDRANGE/TWEETER)							Component	ATA:44
PN:AI-620	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							
4420512 <sup>U</sup>	NO.2 SPEAKER (MIDRANGE/TWEETER)							Component	ATA:44
PN:AI-5.25CX	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							
4420513 <sup>U</sup>	NO.3 SPEAKER (MIDRANGE/TWEETER)							Component	ATA:44
PN:X4623	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							
4420514 <sup>U</sup>	NO.1 SPEAKER (WOOFER)							Component	ATA:44
PN:AI-5.25CX	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 44 - CABIN SYSTEMS</b>									
4420515 <sup>U</sup>		NO.2 SPEAKER (WOOFER)						Component	ATA:44
PN:AI-5.25CX	MOS/MSC	19-Jul-01	O/C						
SN:NSN	HRS	0							
	AFL	0							
4420516 <sup>U</sup>		NO.1 VIDEO MONITOR						Component	ATA:44
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0							
	AFL	0							
4430501 <sup>U</sup>		ARTU (FLIGHTPHONE)						Component	ATA:44
PN:400-10680-001	MOS/MSC	08-May-07	O/C						
SN:1068012926	HRS	4627.5		TSN 0					
	AFL	3095		TSN 0					
4430503 <sup>U</sup>		NO.1 HANDSET (FLIGHTPHONE)						Component	ATA:44
PN:300-09623-0501	MOS/MSC	27-Apr-06	O/C						
SN:1145	HRS	3909.9							
	AFL	2622							
4430504 <sup>U</sup>		NO.2 HANDSET (FLIGHTPHONE)						Component	ATA:44
PN:725729-807PD	MOS/MSC	17-Nov-04	O/C						
SN:MX46333	HRS	2676.6							
	AFL	1860							
4430509 <sup>U</sup>		ANTENNA (FLIGHTPHONE)						Component	ATA:44
PN:902131-1	MOS/MSC	19-Jul-01	O/C						
SN:01126	HRS	0		TSN 0					
	AFL	0		TSN 0					
<b>ATA 49 - AIRBORNE AUXILIARY POWER</b>									
490001	INSPECT PATS APU GTCP36-150W						Service	ATA:49	
	MOS	24-Jan-22	12 (+1m)		24-Jan-23	24-Feb-23	133 d (+31)		
	HRS	11886							
WC#: 49.205	AFL	7487							
	APH	10370	750		11120		562		
REF: AFMS OUT OF PHASE INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 49 - AIRBORNE AUXILIARY POWER</b>									
490003	ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION							Service	ATA:49
	MOS	24-Jan-22	12 (+1m)		31-Jan-23	24-Feb-23	140 d (+24)		
	HRS	11886	1000 (+10%)		12886	12986	798.8 (+100)		
WC#: 49.220	AFL	7487							
REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS									
490003	ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK							Service	ATA:49
	MOS/MSC	25-Jan-21	N/R						
	HRS	11368.5							
WC#: 49.221	AFL	7198							
	APH	10186							
REF: AFMS OUT OF PHASE INSPECTIONS, AFMS OUT OF PHASE INSPECTIONS									
491010	APU - TURBINE ROTOR							Component	ATA:49
PN:3615880-1	MOS	29-Jan-18		TSN 0				LIFE LIMIT	
SN:40134513114	HRS	9862	10000	TSN 0	19862		9304		
WC#: 49.010	APUS	0	10000	TSN 0	10000 <sup>M</sup>		2537		
REF: GENERIC NO REF									
491020	APU - COMPRESSOR ROTOR							Component	ATA:49
PN:3822101-1	MOS	20-Nov-01		TSN 0				LIFE LIMIT	
SN:UNKNOWN	HRS	0	100000	TSN 0	100000		89442		
WC#: 49.015	APUS	0	100000	TSN 0	100000		92537		
REF: GENERIC NO REF									
491025	APU - INSPECT COMPRESSOR ROTOR							Service	ATA:49
PN:3822101-1	MOS	21-Feb-13							
SN:UNKNOWN	HRS	7840	4500		12340		1782		
WC#: 49.020	APUS	7							
REF: MM 49-20-00									
491030	APU - INSPECT HOT SECTION							Service	ATA:49
	MOS	21-Feb-13							
	HRS	7840	4500		12340		1782		
WC#: 49.025	APUS	7							
REF: MM 49-20-00									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 49 - AIRBORNE AUXILIARY POWER</b>								
493010	APU - FUEL CONTROL							Component ATA:49
PN:3882730-9	MOS/MSC	20-Nov-04	O/C	TSN 0				
SN:27286	HRS	3161		TSN 0				
WC#: 49.030	APUS			TSN 0				
				REF: MM 49-30-52				
493020	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT							Service ATA:49
	MOS	05-Jan-17		TAC 0				
	HRS	9666	1000	TAC 0	10666		108	
WC#: 49.035	APUS	20		TAC 0				
				REF: MM 49-30-52				
493040	APU - FUEL SHUTOFF VALVE							Component ATA:49
PN:3882440-1	MOS/MSC	20-Nov-01	O/C					
SN:UNKNOWN	HRS	0						
WC#: 49.045	APUS	0						
				REF: MM 49-30-54				
493050	APU - CHECK FUEL NOZZLE FLOW RATE							Service ATA:49
	MOS	21-Feb-13						
	HRS	7840	4500		12340		1782	
WC#: 49.050	APUS	7						
				REF: MM 49-20-00				
493060	APU - CONTROLLER							Component ATA:49
PN:2118330-2	MOS/MSC	20-Nov-01	O/C	TSN 0				
SN:79-B0346	HRS	0		TSN 0				
WC#: 49.055	APUS	0		TSN 0				
				REF: MM 49-60-46				
493070	APU - LOAD CONTROL VALVE							Component ATA:49
PN:109812-9	MOS/MSC	20-Nov-01	O/C	TSN 0				
SN:3014	HRS	0		TSN 0				
WC#: 49.060	APUS	0		TSN 0				
				REF: MM 49-50-33				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 49 - AIRBORNE AUXILIARY POWER</b>									
494010	APU - IGNITION UNIT							Component	ATA:49
PN:10-516000-3	MOS/MSC	23-Aug-22	O/C	TSR 0					
SN:J17280020	HRS	10558		TSR 0					
WC#: 49.065	APUS	7463		TSR 0					
REF: MM 49-40-32									
494020	APU - IGNITER PLUG							Component	ATA:49
PN:3888002-2	MOS/MSC	29-Jan-18	O/C						
SN:UNKNOWN	HRS	9862							
WC#: 49.070	APUS								
REF: MM 49-40-33									
494030	APU - REMOVE AND INSPECT IGNITER PLUG							Service	ATA:49
PN:3888002-2	MOS	21-Jun-22							
SN:UNKNOWN	HRS	10529	750		11279		721		
WC#: 49.075	APUS	7463							
REF: MM 49-40-33									
499020	APU - INSPECT MAGNETIC DRAIN PLUG							Service	ATA:49
	MOS	24-Jan-22	12		31-Jan-23		140 d		
	HRS	10370	750		11120		562		
WC#: 49.100	APUS	7463							
REF: MM 49-90-46									
499030	APU - CHANGE OIL							Service	ATA:49
	MOS	24-Jan-22	12		31-Jan-23		140 d		
	HRS	10370	750		11120		562		
WC#: 49.105	APUS	7463							
REF: MM 49-20-00									
499040	APU - REMOVE AND REPLACE OIL FILTER ELEMENT							Service	ATA:49
	MOS	24-Jan-22	12		31-Jan-23		140 d		
	HRS	10370	750		11120		562		
WC#: 49.110	APUS	7463							
REF: MM 49-90-47									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 49 - AIRBORNE AUXILIARY POWER</b>								
499070	APU - LOW OIL PRESSURE SWITCH							Component ATA:49
PN:3876001-8	MOS/MSC	29-Jan-18	O/C					
SN:UNKNOWN	HRS							
WC#: 49.125	APUS							
REF: MM 49-60-43								
499110	APU - SOAP CHECK OIL							Service ATA:49
	MOS/MSC	25-Jan-21	O/C					
	HRS	10186						
WC#: 49.130	APUS	17						
REF: SIL SIL APU-49								
49APU1	APU							Component ATA:49
PN:3800304-1	MOS/MSC	30-Jan-05	E/C					
SN:P-545	HRS	0		TSO 6439				
WC#: 49.APU1	AFL	0		TSO 22				
<b>ATA 51 - STD PRACTICES AND STRUCT-GENRL</b>								
510001	INSPECT/NDT NOSE LANDING GEAR BAY SIDEWALLS							Service ATA:51
	MOS	02-Nov-12	144 (+3m)		30-Nov-24	02-Feb-25	809 d (+64)	
	HRS	7475						
WC#: 51.100	AFL	4999	5000 (+10%)		9999	10499	2386 (+500)	
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-111								
510002	DETAIL INSPECT FRONT PRESSURE BULKHEAD							Service ATA:51
	MOS	19-Feb-18						
	HRS	10726						
WC#: 51.010	AFL	6832	1000 (+10%)		7832	7932	219 (+100)	
REF: AFMS STRUCTURAL INSPECTIONS								
510003	INSPECT/NDT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS							Service ATA:51
	MOS	24-Jan-22	48 (+3m)	Adj -85d	31-Oct-25	31-Jan-26	1144 d (+92)	
	HRS	11886						
WC#: 51.020	AFL	7487						
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-105A								





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 51 - STD PRACTICES AND STRUCT-GENRL									
510004	DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS							Service	ATA:51
	MOS	20-Nov-01							
	HRS	0							
WC#: 51.030	AFL	0	20000 (+500)		20000	20500	12387 (+500)		
REF: AFMS STRUCTURAL INSPECTIONS									
510005	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19							Service	ATA:51
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)		
	HRS	10726							
WC#: 51.040	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-107, NTM 53-10-108, NTM 53-10-108B, NTM 53-10-109									
510006	DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14							Service	ATA:51
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)		
	HRS	10726							
WC#: 51.050	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
510007	INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17							Service	ATA:51
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)		
	HRS	10726							
WC#: 51.060	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-106A									
510008	X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16							Service	ATA:51
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)		
	HRS	10726							
WC#: 51.070	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-108A									
510009	DETAIL INSPECT ENTRY DOOR SURROUND							Service	ATA:51
	MOS	17-Jun-22	48 (+3m)	Adj -89d	31-Mar-26	20-Jun-26	1295 d (+81)		
	HRS	12023.9							
WC#: 51.080	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 51 - STD PRACTICES AND STRUCT-GENRL</b>								
510010	INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR							Service ATA:51
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)	
	HRS	10726						
WC#: 51.090	AFL	6832						
					REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-104, NTM 53-10-101, NTM 53-10-102, NTM 53-10-103A, NTM 53-10-106			
<b>ATA 52 - DOORS</b>								
520004 <sup>S</sup>	CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES							Service ATA:52
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 52.025	AFL	6832						
					REF: AFMS INSPECTION C6			
								PKG:24,92
520005 <sup>S</sup>	CHECK ESCAPE HATCH RELEASE MECHANISM							Service ATA:52
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 52.015	AFL	7300						
								PKG:12,91
520006 <sup>S</sup>	INSPECT ESCAPE HATCH SEALS							Service ATA:52
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 52.035	AFL	7300						
								PKG:12,91
520007 <sup>S</sup>	INSPECT/CHECK ENTRY DOOR							Service ATA:52
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 52.010	AFL	6832						
					REF: AFMS INSPECTION C6			
								PKG:24,92
520008	INSPECT/NDT MAIN ENTRY DOOR							Service ATA:52
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)	
	HRS	10726						
WC#: 52.010	AFL	6832						
					REF: NTM 52-80-102			



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 52 - DOORS</b>									
520009	DETAIL INSPECT ESCAPE HATCH							Service	ATA:52
	MOS	19-Feb-18	96 (+3m)		28-Feb-26	19-May-26	1264 d (+80)		
	HRS	10726							
WC#: 52.015	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
520011 <sup>S</sup>	DETAILED VISUAL INSPECTION EXTERNAL BAGGAGE UNIT (EBU) LOADING DOOR LATCH AND PINASSEMBLIES							Service	ATA:52
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 52.060	AFL	7300							
REF: AFMS INSPECTION B7									
521001	MAIN ENTRY DOOR ASSEMBLY							Component	ATA:52
PN:259W03838-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:SD/DH/426	HRS	0		TSN 0					
WC#: 52.010	AFL	0		TSN 0					
521016	LONG RANGE TANK DOOR							Component	ATA:52
PN:25-8PT111-87A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:SD/DH/368	HRS	0		TSN 0					
WC#: 52.055	AFL	0		TSN 0					
522001	ESCAPE HATCH							Component	ATA:52
PN:25-8FC3601-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:RG8547	HRS	0		TSN 0					
WC#: 52.015	AFL	0		TSN 0					
<b>ATA 53 - FUSELAGE</b>									
530001	DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19							Service	ATA:53
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)		
	HRS	12023.9							
WC#: 53.115	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 53 - FUSELAGE</b>									
530002	INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS							Service	ATA:53
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)		
	HRS	12023.9							
WC#: 53.040	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
530003	DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).							Service	ATA:53
	MOS	19-Feb-18	96 (+3m)		31-Aug-25 <sup>M</sup>	30-Nov-25	1083 d (+91)		
	HRS	10726							
WC#: 53.110	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
530004	DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)							Service	ATA:53
	MOS	19-Feb-18	96 (+3m)		19-Feb-26	19-May-26	1255 d (+89)		
	HRS	10726							
WC#: 28.015	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
530007	DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS							Service	ATA:53
	MOS	19-Feb-18	96 (+3m)		31-Aug-25 <sup>M</sup>	30-Nov-25	1083 d (+91)		
	HRS	10726							
WC#: 53.105	AFL	6832							
530009	INSPECT/NDT FUSELAGE LAP JOINTS							Service	ATA:53
	MOS	20-Nov-01							
	HRS	0							
WC#: 53.125	AFL		T:27000 (+50 0)		27000	27500	19387 (+500)		
REF: NTM 53-10-104									
530010	DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING							Service	ATA:53
	MOS/MSC	20-Nov-01	A/R						
	HRS	0							
WC#: 53.020	AFL	0							
530011	INSPECT LEFT-HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)							Service	ATA:53
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)		
	HRS	12023.9							
WC#: 53.175	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
530012	INSPECT RIGHT- HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)							Service	ATA:53
	MOS	07-Sep-21	96 (+3m)		07-Sep-29	07-Dec-29	2551 d (+91)		
	HRS	11809.3							
WC#: 53.070	AFL	7445							
REF: AFMS STRUCTURAL INSPECTIONS									
530013	INSPECT/NDT PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS							Service	ATA:53
	MOS	02-Jun-16							
	HRS	10011	10000 (+500)		20000 <sup>M</sup>	20500	7912.8 (+500)		
WC#: 53.030	AFL	6400							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110									
530014	INSPECT/NDT REAR ENGINE MOUNT FITTINGS							Service	ATA:53
	MOS	20-Nov-01							
	HRS	0	20000 (+500)		20000	20500	7912.8 (+500)		
WC#: 53.035	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-110A									
530015	INSPECT/NDT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE							Service	ATA:53
	MOS	20-Nov-01							
	HRS	0	30000 (+500)		30000	30500	17912.8 (+500)		
WC#: 53.015	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-30-104									
530016	DETAIL INSPECT ENGINE BEAM							Service	ATA:53
	MOS	06-Jun-16							
	HRS	10011	10000 (+500)		20000 <sup>M</sup>	20500	7912.8 (+500)		
WC#: 53.080	AFL	6400							
REF: AFMS STRUCTURAL INSPECTIONS									
530017	INSPECT NO. 1 ENGINE MOUNTING BRACKETS							Service	ATA:53
	MOS/MSC	11-Jan-16	E/C					PART OF MPI	
	HRS	9692.3							
WC#: 53.200	AFL	6232							
REF: AFMS STRUCTURAL INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 53 - FUSELAGE</b>									
530017	INSPECT NO. 2 ENGINE MOUNTING BRACKETS							Service	ATA:53
	MOS/MSC	11-Jan-16	E/C					PART OF MPI	
	HRS	9692.3							
WC#: 53.200	AFL	6232							
REF: AFMS STRUCTURAL INSPECTIONS									
530018	DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS							Service	ATA:53
	MOS	21-Jun-21							
	HRS	11707.4	2400 (+10%)		14107.4	14347.4	2020.2 (+240)		
WC#: 53.205	AFL	7385							
REF: AFMS STRUCTURAL INSPECTIONS									
530019	DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE							Service	ATA:53
	MOS	13-Mar-22	12 (+1m)		13-Mar-23	13-Apr-23	181 d (+31)		
	HRS	11930.2							
WC#: 53.210	AFL	7513							
REF: AFMS STRUCTURAL INSPECTIONS									
530021	DETAIL INSPECT APU SUPPORT STRUCTURE							Service	ATA:53
	MOS	25-Jan-21							
	HRS	11368.5							
WC#: 53.010	AFL	7198							
	APH	10001	3000		13001		2443		
REF: AFMS STRUCTURAL INSPECTIONS									
530022	DETAIL INSPECT APU MOUNTING HARDWARE							Service	ATA:53
	MOS	12-Dec-11							
	HRS	0							
WC#: 53.215	AFL	0							
	APH	7377	4500	Adj 284	12161		1603		
	APS	0							
REF: AFMS STRUCTURAL INSPECTIONS, AFMS STRUCTURAL INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 53 - FUSELAGE</b>									
530023	DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS							Service	ATA:53
	MOS	12-Dec-11							
	HRS	0							
WC#: 53.220	AFL	0							
	APH	7377	4500	Adj 284	12161		1603		
	APS	0							
REF: AFMS STRUCTURAL INSPECTIONS									
530024	FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE							Service	ATA:53
	MOS	20-Nov-01							
	HRS	0							
WC#: 53.225	AFL	0							
	APH	0	22500		22500		11942		
	APS	0							
REF: AFMS STRUCTURAL INSPECTIONS, AFMS STRUCTURAL INSPECTIONS									
530025	DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS							Service	ATA:53
	MOS	20-Nov-01							
	HRS	0							
WC#: 53.170	AFL	0	10000 (+500)		10000	10500	2387 (+500)		
REF: AFMS STRUCTURAL INSPECTIONS									
530027 <sup>S</sup>	VISUAL INSPECTION FUSELAGE SKIN							Service	ATA:53
	MOS	17-Jun-22	48 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 53.235	AFL	7567							
REF: AFMS INSPECTION G									
PKG:96									
531146	RADOME							Component	ATA:53
PN:25-8RF13-1A	MOS/MSC	09-Apr-12	O/C						
SN:DHB17	HRS	7104							
WC#: 53.135	AFL	4775							
531152	TAIL CONE FAIRING							Component	ATA:53
PN:25.8GF/Z27-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FL355	HRS	0		TSN 0					
WC#: 53.140	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 53 - FUSELAGE</b>								
531154	FUSELAGE							Component ATA:53
PN:25-8FA1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:258545	HRS	0		TSN 0				
WC#: 53.145	AFL	0		TSN 0				
<b>5340501<sup>U</sup> VENTRAL FAIRING</b>								
PN:259W03059-1A	MOS/MSC	19-Jul-01	O/C	TSN 0				Component ATA:53
SN:FL321	HRS	0		TSN 0				
	AFL	0		TSN 0				
<b>ATA 55 - STABILIZERS</b>								
550001	DETAIL INSPECT ELEVATORS AND TABS							Service ATA:55
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)	
	HRS	12023.9						
WC#: 27.070	AFL	7567						
REF: AFMS STRUCTURAL INSPECTIONS								
550002	LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS							Service ATA:55
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)	
	HRS	12023.9						
WC#: 55.075	AFL	7567						
REF: AFMS STRUCTURAL INSPECTIONS								
550003	XRAY ELEVATORS							Service ATA:55
	MOS	21-Jun-22	48 (+3m)		21-Jun-26	21-Sep-26	1377 d (+92)	
	HRS	12023.9						
WC#: 55.055	AFL	7567						
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-20-101, NTM 55-20-102								
550004	DETAIL INSPECT RUDDER AND TAB							Service ATA:55
	MOS	17-Jun-22	48 (+3m)	Adj -109d	28-Feb-26	31-May-26	1264 d (+92)	
	HRS	12023.9						
WC#: 27.045	AFL	7567						
REF: AFMS STRUCTURAL INSPECTIONS								





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 55 - STABILIZERS</b>									
550005	INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB							Service	ATA:55
	MOS	17-Jun-22	48 (+3m)	Adj -80d	29-Mar-26	29-Jun-26	1293 d (+92)		
	HRS	12023.9							
WC#: 55.065	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
550006	X-RAY RUDDER (IN-SITU)							Service	ATA:55
	MOS	21-Jun-22	48 (+3m)	Adj -113d	28-Feb-26	31-May-26	1264 d (+92)		
	HRS	12023.9							
WC#: 27.045	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-40-101									
550007	DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS							Service	ATA:55
	MOS	09-Feb-18	96 (+3m)		09-Feb-26	09-May-26	1245 d (+89)		
	HRS								
WC#: 27.045	AFL								
REF: AFMS STRUCTURAL INSPECTIONS									
550008 <sup>S</sup>	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING							Service	ATA:55
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 55.010	AFL	7567							
REF: AFMS INSPECTION F8									
PKG:62,95									
550009	DETAIL INSPECT HORIZONTAL STABILIZER							Service	ATA:55
	MOS	19-Feb-18	96 (+3m)		19-Feb-26	19-May-26	1255 d (+89)		
	HRS	10726							
WC#: 55.040	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
550010	INSPECT/NDT VERTICAL STABILIZER							Service	ATA:55
	MOS	07-Sep-21	T:216 (+3m)		07-Sep-39	07-Dec-39	6203 d (+91)		
	HRS	0							
WC#: 55.050	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-30-101, NTM 55-30-102, NTM 55-30-103									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 55 - STABILIZERS</b>									
550011	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS							Service	ATA:55
	MOS	07-Sep-21	T:192 (+3m)		07-Sep-37	07-Dec-37	5473 d (+91)		
	HRS	0							
WC#: 55.025	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS									
550012	INSPECT/NDT HORIZONTAL STABILIZER							Service	ATA:55
	MOS	19-Feb-18	96 (+3m)		19-Feb-26	19-May-26	1255 d (+89)		
	HRS	10726							
WC#: 55.045	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-10-104A, NTM 55-10-104B, NTM 55-10-104C									
550013	X-RAY HORIZONTAL STABILIZER							Service	ATA:55
	MOS	30-Jan-18	T:216 (+3m)		30-Jan-36	30-Apr-36	4887 d (+91)		
	HRS	0							
WC#: 55.035	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-10-101, NTM 55-10-102, NTM 55-10-103, NTM 55-10-105									
550014	DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER							Service	ATA:55
	MOS/MSC	20-Nov-01	A/R						
	HRS	0							
WC#: 55.060	AFL								
REF: AFMS STRUCTURAL INSPECTIONS									
550015	INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS							Service	ATA:55
	MOS	21-Jun-22	24 (+2m)	Adj -47d	05-May-24	05-Jul-24	600 d (+61)		
	HRS	12023.9							
WC#: 55.070	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
551004	UPPER VERTICAL STABILIZER							Component	ATA:55
PN:25-8TF513-1A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:FL/DHB/8547	HRS	0		TSN 0					
WC#: 55.015	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 55 - STABILIZERS</b>								
551006	TAILPLANE							Component ATA:55
PN:25-8TP257-601AENG	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FL/DHB/8546	HRS	0		TSN 0				
WC#: 55.020	AFL	0		TSN 0				
551010	BULLET FAIRING							Component ATA:55
PN:25-8GF501-6155A	MOS/MSC	12-Sep-01	O/C	TSN 0				
SN:RG8570	HRS	7		TSN 0				
WC#: 55.030	AFL	5		TSN 0				
553005	FIN LEADING EDGE							Component ATA:55
PN:25-8TF133-3A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:FL436	HRS	0		TSN 0				
WC#: 55.305	AFL	0		TSN 0				
<b>ATA 56 - WINDOWS</b>								
56-00-00 <sup>U</sup>	LH A SCREEN ICA REQUIREMENTS							Service ATA:56
	MOS/MSC	03-Dec-21	A/R					
	HRS	11882.7						
	AFL	7485						
560005 <sup>S</sup>	CHECK PASSENGER CABIN WINDOWS							Service ATA:56
	MOS	25-Sep-21						
	HRS	11828	800 <sup>S</sup> (+40/-10)					
WC#: 56.090	AFL	7454						
					REF: AFMS INSPECTION B3			PKG:9,91
560006 <sup>S</sup>	INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER							Service ATA:56
	MOS	03-May-21						
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 56.070	AFL	7300						
					REF: AFMS INSPECTION B4			PKG:10,91



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 56 - WINDOWS</b>									
560007 <sup>S</sup>	SCREEN HEAT CIRCUIT BREAKERS - DO A VISUAL INSPECTION FOR HEAT DISTRESS, DISCOLORATION AND DEFORMATION							Service	ATA:56
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
	AFL	7567							
REF: AFMS INSPECTION F6								PKG:60,95	
561001	LEFT (PANEL A) HEATED WINDSCREEN							Component	ATA:56
PN:1966001	MOS/MSC	21-Aug-19	O/C	TSN 0					
SN:0501	HRS	10786		TSN 0					
WC#: 56.010	AFL	6876		TSN 0					
561002	RIGHT (PANEL A) HEATED WINDSCREEN							Component	ATA:56
PN:NF24016-416	MOS/MSC	13-Mar-22	O/C	TSN 64, TSR 0					
SN:L437085	HRS	11930.2		TSN 1573.2, TSR 0					
WC#: 56.010	AFL	7513		TSN 891, TSR 0					
561003	LEFT DIRECT VIEW B WINDOW							Component	ATA:56
PN:NF24016-91	MOS/MSC	25-Jul-21	O/C	TSN 0					
SN:L539420	HRS	11768.3		TSN 0					
WC#: 56.015	AFL	7421		TSN 0					
561004	RIGHT DIRECT VIEW B WINDOW							Component	ATA:56
PN:NH24016-92	MOS/MSC	14-Aug-20	O/C	TSN 0					
SN:L524508	HRS	11060.4		TSN 0					
WC#: 56.015	AFL	7036		TSN 0					
561005	LEFT C WINDOW							Component	ATA:56
PN:25-8FN353-43A	MOS/MSC	21-Jul-06	O/C	TSR 0					
SN:L317599	HRS	4021		TSR 0					
WC#: 56.020	AFL	2691		TSR 0					
561006	RIGHT C WINDOW							Component	ATA:56
PN:25-8FN353-44A	MOS/MSC	27-Oct-05	O/C	TSN 0					
SN:L350902	HRS	3470.1		TSN 0					
WC#: 56.020	AFL	2345		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 56 - WINDOWS</b>								
<b>562001 NO. 1 LEFT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2792	HRS	5001.4		TSN 0				
WC#: 56.025	AFL	3360		TSN 0				
<b>562002 NO. 1 RIGHT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2919	HRS	5001.4		TSN 0				
WC#: 56.025	AFL	3360		TSN 0				
<b>562003 NO. 2 LEFT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2758	HRS	5001.4		TSN 0				
WC#: 56.030	AFL	3360		TSN 0				
<b>562004 NO. 2 RIGHT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2897	HRS	5001.4		TSN 0				
WC#: 56.030	AFL	3360		TSN 0				
<b>562005 NO. 3 LEFT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2863	HRS	5001.4		TSN 0				
WC#: 56.035	AFL	3360		TSN 0				
<b>562006 NO. 3 RIGHT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2713	HRS	5001.4		TSN 0				
WC#: 56.035	AFL	3360		TSN 0				
<b>562007 NO. 4 LEFT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2770	HRS	5001.4		TSN 0				
WC#: 56.040	AFL	3360		TSN 0				
<b>562008 NO. 4 RIGHT CABIN WINDOW Component ATA:56</b>								
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0				
SN:2900	HRS	5001.4		TSN 0				
WC#: 56.040	AFL	3360		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 56 - WINDOWS</b>									
562009	NO. 5 LEFT CABIN WINDOW							Component	ATA:56
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0					
SN:2901	HRS	5001.4		TSN 0					
WC#: 56.045	AFL	3360		TSN 0					
562010	NO. 5 RIGHT CABIN WINDOW							Component	ATA:56
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0					
SN:2850	HRS	5001.4		TSN 0					
WC#: 56.045	AFL	3360		TSN 0					
562011	NO. 6 LEFT CABIN WINDOW							Component	ATA:56
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0					
SN:2922	HRS	5001.4		TSN 0					
WC#: 56.050	AFL	3360		TSN 0					
562012	NO. 6 RIGHT CABIN WINDOW							Component	ATA:56
PN:LA25FC7881-53	MOS/MSC	26-Oct-07	O/C	TSN 0					
SN:2814	HRS	5001.4		TSN 0					
WC#: 56.050	AFL	3360		TSN 0					
<b>ATA 57 - WINGS</b>									
570001 <sup>S</sup>	INSPECT LEFT FLAP HINGE FITTINGS							Service	ATA:57
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 57.095	AFL	7300							
					REF: AFMS INSPECTION B9			PKG:15,91	
570002 <sup>S</sup>	INSPECT RIGHT FLAP HINGE FITTINGS							Service	ATA:57
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 57.095	AFL	7300							
					REF: AFMS INSPECTION B10			PKG:16,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
570003 <sup>S</sup>	DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service	ATA:57
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 57.090	AFL	7567							
	REF: AFMS INSPECTION F9							PKG:63,95	
570004 <sup>S</sup>	INSPECT LEFT FLAP SKIN PROTECTION PANELS (IF FITTED)							Service	ATA:57
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 57.140	AFL	7567							
	REF: AFMS INSPECTION F9							PKG:63,95	
570005 <sup>S</sup>	DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4							Service	ATA:57
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 57.090	AFL	7567							
	REF: AFMS INSPECTION F10							PKG:64,95	
570006 <sup>S</sup>	INSPECT RIGHT FLAP SKIN PROTECTION PANELS (IF FITTED)							Service	ATA:57
	MOS	17-Jun-22	24 <sup>S</sup> (+2m/-2m)						
	HRS	12023.9							
WC#: 57.140	AFL	7567							
	REF: AFMS INSPECTION F10							PKG:64,95	
570007	X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -113d	28-Feb-26	31-May-26	1264 d (+92)		
	HRS	12023.9							
WC#: 57.040	AFL	7567							
	REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-30-101								
570008	DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -122d	19-Feb-26	19-May-26	1255 d (+89)		
	HRS	12023.9							
WC#: 57.035	AFL	7567							
	REF: AFMS STRUCTURAL INSPECTIONS								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
570009	DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8							Service	ATA:57
	MOS	26-Apr-21							
	HRS	11562.2	1200 (+10%)		12762.2	12882.2	675 (+120)		
WC#: 57.070	AFL	7300							
REF: AFMS STRUCTURAL INSPECTIONS									
570010	DETAIL INSPECT WING FRONT SPAR, FORWARD FACE							Service	ATA:57
	MOS	19-Feb-18	96 (+3m)		19-Feb-26	19-May-26	1255 d (+89)		
	HRS	10726	4800 (+10%)		15526	16006	3438.8 (+480)		
WC#: 57.020	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00, MMS 57-00-00									
570011	INSPECT WING REAR SPAR, REAR FACE							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -89d	31-Mar-26	24-Jun-26	1295 d (+85)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 57.030	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
570012	DETAIL INSPECT LEFT LOWER AIRBRAKE							Service	ATA:57
	MOS	22-Jun-22	48 (+3m)	Adj -123d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 27.240	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
570012	DETAIL INSPECT LEFT UPPER AIRBRAKE							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -122d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 27.240	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
570012	DETAIL INSPECT RIGHT LOWER AIRBRAKE							Service	ATA:57
	MOS	22-Jun-22	48 (+3m)	Adj -123d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 27.245	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
570012	DETAIL INSPECT RIGHT UPPER AIRBRAKE							Service	ATA:57
	MOS	22-Jun-22	48 (+3m)	Adj -123d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 27.245	AFL	7567	REF: AFMS STRUCTURAL INSPECTIONS						
570013	DETAIL INSPECT AILERONS							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -122d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 27.020	AFL	7567	REF: AFMS STRUCTURAL INSPECTIONS						
570014	LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -122d	28-Feb-26	19-May-26	1264 d (+80)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 57.145	AFL	7567	REF: AFMS STRUCTURAL INSPECTIONS						
570015	INSPECT/X RAY AILERONS							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -109d	04-Mar-26	04-Jun-26	1268 d (+92)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 57.100	AFL	7567	REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-107						
570016	INSPECT/X RAY FLAPS AND FLAP VANES							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -142d	30-Jan-26	30-Apr-26	1235 d (+90)		
	HRS	12023.9	2400 (+10%)		14423.9	14663.9	2336.7 (+240)		
WC#: 57.130	AFL	7567	REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-105, NTM 57-50-106						
570017	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7							Service	ATA:57
	MOS	20-Nov-01							
	HRS		T:24000 (+500)		24000	24500	11912.8 (+500)		
WC#: 57.055	AFL	0	REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00						



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
570018	DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP							Service	ATA:57
	MOS	20-Nov-01							
	HRS		T:24000 (+500)		24000	24500	11912.8 (+500)		
WC#: 57.080	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00									
570019	INSPECT/NDT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0							Service	ATA:57
	MOS	20-Nov-01							
	HRS		T:24000 (+500)		24000	24500	11912.8 (+500)		
WC#: 57.060	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-30-104, MMS 57-00-00									
570020	INSPECT/NDT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)							Service	ATA:57
	MOS	20-Nov-01							
	HRS		T:24000 (+500)		24000	24500	11912.8 (+500)		
WC#: 57.075	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-00-102									
570021	DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS.							Service	ATA:57
	MOS/MSC	20-Nov-01	A/R						
	HRS	0							
WC#: 57.010	AFL	0							
REF: AFMS STRUCTURAL INSPECTIONS									
570022	DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH							Service	ATA:57
	MOS	21-Aug-15							
	HRS	9441	4800 (+10%)		14241	14721	2153.8 (+480)		
WC#: 57.050	AFL	6083							
REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00									
570023	INSPECT/NDT AILERON HORN BALANCE WEIGHT							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -113d	28-Feb-26	31-May-26	1264 d (+92)		
	HRS	12023.9							
WC#: 57.135	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS, NTM 57-50-107, MMS 57-00-00									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
570024	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH							Service	ATA:57
	MOS	21-Jun-22							
	HRS	12023.9	7200 (+500)	Adj -23.9	19200	19700	7112.8 (+500)		
WC#: 57.065	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00									
570025	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH							Service	ATA:57
	MOS	18-Aug-15							
	HRS	9441	4800 (+10%)		14241	14721	2153.8 (+480)		
WC#: 57.050	AFL	6083							
REF: AFMS STRUCTURAL INSPECTIONS, MMS 57-00-00									
570026	INSPECT WING LEADING EDGES							Service	ATA:57
	MOS	21-Jun-22	48 (+3m)	Adj -85d	28-Mar-26	28-Jun-26	1292 d (+92)		
	HRS	12023.9							
WC#: 57.025	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
570027	DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP							Service	ATA:57
	MOS	19-Feb-18	96 (+3m)		19-Feb-26	19-May-26	1255 d (+89)		
	HRS	10726	4800 (+10%)		15526	16006	3438.8 (+480)		
WC#: 57.045	AFL	6832							
REF: AFMS STRUCTURAL INSPECTIONS									
570028	INSPECT AILERON AT OUTBOARD HINGE CASTING							Service	ATA:57
	MOS	17-Jun-22	48 (+3m)	Adj -89d	31-Mar-26	20-Jun-26	1295 d (+81)		
	HRS	12023.9							
WC#: 57.125	AFL	7567							
REF: AFMS STRUCTURAL INSPECTIONS									
571010	WING							Component	ATA:57
PN:25-WS1-5A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:DHB8545	HRS	0		TSN 0					
WC#: 57.010	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 57 - WINGS</b>									
571010-U1 <sup>U</sup>	WING							Component	ATA:57
PN:25-8WS1-5A	MOS/MSC	19-Jul-01	O/C						
SN:DHB8545	HRS	0		TSN 0					
	AFL	0		TSN 0					
571109	REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS							Service	ATA:57
	MOS	19-Jul-01						LIFE LIMIT	
	HRS	0		TAC 0					
WC#: 57.150	AFL	0	14600	TAC 0	14600		6987		
571110	REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS							Service	ATA:57
	MOS	19-Jul-01						LIFE LIMIT	
	HRS	0		TAC 0					
WC#: 57.150	AFL	0	14600	TAC 0	14600		6987		
574001	LEFT LEADING EDGE ASSEMBLY							Component	ATA:57
PN:25-8WS3299-3A	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:AST01B316	HRS	0		TSN 0					
WC#: 57.085	AFL	0		TSN 0					
574002	RIGHT LEADING EDGE ASSEMBLY							Component	ATA:57
PN:25-9WS7-347A	MOS/MSC	16-Feb-18	O/C						
SN:AST96J189	HRS	10726							
WC#: 57.085	AFL	6832							
<b>ATA 71 - POWER PLANT</b>									
710049	COMPRESSOR WASH NO. 1 ENGINE							Service	ATA:71
	DAYS/MSC	21-Aug-19	O/C						
	HRS	10786							
WC#: 71.025	AFL	6876							
				REF: GENERIC CMM					
710050	COMPRESSOR WASH NO. 2 ENGINE							Service	ATA:71
	DAYS/MSC	21-Aug-19	O/C						
	HRS	10786							
WC#: 71.025	AFL	6876							
				REF: GENERIC CMM					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
710083	NO. 1 ENGINE UPPER FAN COWL DOOR							Component	ATA:71
PN:C46B11000-21	MOS/MSC	28-Jul-06	O/C						
SN:B353	HRS	4028.9							
WC#: 71.060	AFL	2698							
710084	NO. 2 ENGINE UPPER FAN COWL DOOR							Component	ATA:71
PN:C46B11000-22	MOS/MSC	28-Jul-06	O/C						
SN:B348	HRS	4028.9							
WC#: 71.060	AFL	2698							
710089	NO. 1 ENGINE LOWER FAN COWL DOOR							Component	ATA:71
PN:C45B15000-21	MOS/MSC	25-Sep-04	O/C	TSR 0					
SN:B-346	HRS	2582.3		TSR 0					
WC#: 71.070	AFL	1805		TSR 0					
710090	NO. 2 ENGINE LOWER FAN COWL DOOR							Component	ATA:71
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.070	AFL	0		TSN 0					
714010 <sup>S</sup>	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service	ATA:71
	MOS	27-Jun-22							
	HRS	11763.8	600 <sup>S</sup>						
WC#: 71.030	ENC	7629							
				REF: GENERIC NO REF				PKG:3	
714010 <sup>S</sup>	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS							Service	ATA:71
	MOS	24-May-22							
	HRS	12448.3	600 <sup>S</sup>						
WC#: 71.030	ENC	8145							
				REF: GENERIC NO REF				PKG:3	
715010 <sup>S</sup>	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service	ATA:71
	MOS	27-Jun-22							
	HRS	11763.8	600 <sup>S</sup>						
WC#: 71.040	ENC	7629							
				REF: GENERIC NO REF				PKG:3	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
715010 <sup>S</sup>	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS							Service	ATA:71
	MOS	24-May-22							
	HRS	12448.3	600 <sup>S</sup>						
WC#: 71.040	ENC	8145							
REF: GENERIC NO REF								PKG:3	
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3075160-4	MOS/MSC	23-Mar-08	E/C		TSO 51.23				
SN:P-107407	HRS	0			TSO 3097.8				
WC#: 71.EN1	AFL	0			TSO 1738				
71EN2	NO. 2 ENGINE							Component	ATA:71
PN:3075160-4	MOS/MSC	23-Mar-08	E/C		TSO 51.23				
SN:P-107404	HRS	0			TSO 3097.8				
WC#: 71.EN2	AFL	0			TSO 1738				
<b>ATA 72 - ENGINE</b>									
720002	INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service	ATA:72
	MOS	21-Jun-22						PART OF MPI	
	HRS	12023.9	2500 (+10%)		14523.9	14773.9	2436.7 (+250)		
WC#: 72.030	AFL	7567							
REF: AFMS OUT OF PHASE INSPECTIONS									
720002	INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT							Service	ATA:72
	MOS	21-Jun-22						PART OF MPI	
	HRS	12023.9	2500 (+10%)		14523.9	14773.9	2436.7 (+250)		
WC#: 72.030	AFL	7567							
REF: AFMS OUT OF PHASE INSPECTIONS									
720003	DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service	ATA:72
	MOS	21-Jun-22						PART OF MPI	
	HRS	12023.9	2500 (+10%)		14523.9	14773.9	2436.7 (+250)		
WC#: 72.040	AFL	7567							
REF: AFMS OUT OF PHASE INSPECTIONS									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
720003	DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP							Service	ATA:72
	MOS	21-Jun-22						PART OF MPI	
	HRS	12023.9	2500 (+10%)		14523.9	14773.9	2436.7 (+250)		
WC#: 72.040	AFL	7567							
REF: AFMS OUT OF PHASE INSPECTIONS									
720120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service	ATA:72
	MOS	29-Jan-16							
	HRS	9645.4	2500 (+100)		(12145.4) 12405.5	12245.4	318.3 (+100)		
WC#: 71.010	ENC	6408							
REF: LMM 72-00-00									
720120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)							Service	ATA:72
	MOS	29-Jan-16							
	HRS	10448.4	2500 (+100)		(12948.4) 12524	13048.4	436.8 (+100)		
WC#: 71.010	ENC	6997							
REF: LMM 72-00-00									
720130 <sup>S</sup>	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service	ATA:72
	MOS	27-Jun-22							
	HRS	11763.8	600 <sup>S</sup>						
WC#: 71.020	ENC	7629							
REF: LMM 72-00-00									
720130 <sup>S</sup>	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES							Service	ATA:72
	MOS	24-May-22							
	HRS	12448.3	600 <sup>S</sup>						
WC#: 71.020	ENC	8145							
REF: LMM 72-00-00									
723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service	ATA:72
	MOS	21-Feb-13							
	HRS	7551.9	5000 (+200)		(12551.9) 12812	12751.9	724.8 (+200)		
WC#: 72.010	ENC	5251							
REF: LMM 72-00-00									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)							Service	ATA:72
	MOS	21-Feb-13							
	HRS	8354.9	5000 (+200)		(13354.9) 12930.5	13554.9	843.3 (+200)		
WC#: 72.010	ENC	5840							
REF: LMM 72-00-00									
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component	ATA:72
PN:3072443-5	MOS/MSC	12-Feb-02	O/C						
SN:99P06921	HRS	1367		TSN 1366.8					
WC#: 72.020	ENC	1005		TSN 1005					
REF: GENERIC NO REF									
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE							Component	ATA:72
PN:3072443-5	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:99P05695	HRS	0		TSN 0					
WC#: 72.020	ENC	0		TSN 0					
REF: GENERIC NO REF									
724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service	ATA:72
PN:3072443-5	MOS	29-Jan-16							
SN:99P06921	HRS	9645.4	2500 (+100)		(12145.4) 12405.5	12245.4	318.3 (+100)		
WC#: 72.030	ENC	6408							
REF: LMM 72-40-04									
724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE							Service	ATA:72
PN:3072443-5	MOS	29-Jan-16							
SN:99P05695	HRS	10448.4	2500 (+100)		(12948.4) 12524	13048.4	436.8 (+100)		
WC#: 72.030	ENC	6997							
REF: LMM 72-40-04									
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075447-2	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322901195	HRS	0		TSN 0					
WC#: 72.040	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075446-2	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322901551	HRS	0		TSN 0					
WC#: 72.040	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075426-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322901138	HRS	0		TSN 0					
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075425-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322901129	HRS	0		TSN 0					
WC#: 72.050	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075574-3	MOS	15-Feb-08		TSN 0				LIFE LIMIT	
SN:322907868	HRS	5477		TSN 4110					
WC#: 72.060	ENC	3861	10000	TSN 2856	(11005) 10943		3330		
REF: GENERIC NO REF									
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC							Component	ATA:72
PN:3075436-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:971217200893	HRS	0		TSN 0					
WC#: 72.060	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC							Component	ATA:72
PN:3074786-9	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:981217200932	HRS	0		TSN 0					
WC#: 72.070	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: LMM 72-50-06									
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC							Component	ATA:72
PN:3074786-9	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:981217200951	HRS	0		TSN 0					
WC#: 72.070	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: LMM 72-50-06									
725050	NO. 1 ENGINE - FAN DISC							Component	ATA:72
PN:3074621-4	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322904892	HRS	0		TSN 0					
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									
725050	NO. 2 ENGINE - FAN DISC							Component	ATA:72
PN:3074621-4	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980322904890	HRS	0		TSN 0					
WC#: 72.080	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3070440-11	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:990316000367	HRS	0		TSN 0					
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3072395-2	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:990316000364	HRS	0		TSN 0					
WC#: 72.090	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3072416-10	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:990316000211	HRS	0		TSN 0					
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3072396-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980316005430	HRS	0		TSN 0					
WC#: 72.100	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3072417-7	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980316005534	HRS	0		TSN 0					
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3072397-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:990316000027	HRS	0		TSN 0					
WC#: 72.110	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3075351-5	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980350107171	HRS	0		TSN 0					
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 19938		12325		
REF: GENERIC NO REF									
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC							Component	ATA:72
PN:3075326-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980350104888	HRS	0		TSN 0					
WC#: 72.120	ENC	0	20000	TSN 0	(20000) 19422		11809		
REF: GENERIC NO REF									
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component	ATA:72
PN:3074744-1	MOS/MSC	12-Feb-02	O/C	TSN 0					
SN:991119500587	HRS	1367		TSN 0					
WC#: 72.130	ENC	1005		TSN 0					
REF: LMM 72-30-10									
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component	ATA:72
PN:3074744-1	MOS/MSC	09-Dec-02	O/C	TSN 0					
SN:991119500514	HRS	2037.1		TSN 0					
WC#: 72.130	ENC	1491		TSN 0					
REF: LMM 72-30-10									
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER							Component	ATA:72
PN:3073398-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:982332201993	HRS	0		TSN 0					
WC#: 72.140	ENC	0	10000	TSN 0	(10000) 9938		2325		
REF: GENERIC NO REF									
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER							Component	ATA:72
PN:3073398-3	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:98532201927	HRS	0		TSN 0					
WC#: 72.140	ENC	0	10000	TSN 0	(10000) 9422		1809		
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725130	<b>NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT</b>							Component	ATA:72
PN:3072545-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:99P03923	HRS	0		TSN 0					
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 11938		4325		
REF: GENERIC NO REF									
725130	<b>NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT</b>							Component	ATA:72
PN:3072545-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:99P03915	HRS	0		TSN 0					
WC#: 72.150	ENC	0	12000	TSN 0	(12000) 11422		3809		
REF: GENERIC NO REF									
725140	<b>NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE</b>							Component	ATA:72
PN:3075579-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980316005588	HRS	0		TSN 0					
WC#: 72.160	ENC	0	30000	TSN 0	(30000) 29938		22325		
REF: GENERIC NO REF									
725140	<b>NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE</b>							Component	ATA:72
PN:3075579-1	MOS	19-Jul-01		TSN 0				LIFE LIMIT	
SN:980316005593	HRS	0		TSN 0					
WC#: 72.160	ENC	0	30000	TSN 0	(30000) 29422		21809		
REF: GENERIC NO REF									
725150	<b>NO. 1 ENGINE - FAN DRIVE SHAFT</b>							Component	ATA:72
PN:3074641-4	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:99P06856	HRS	0		TSN 0					
WC#: 72.170	ENC	0		TSN 0					
REF: GENERIC NO REF									
725150	<b>NO. 2 ENGINE - FAN DRIVE SHAFT</b>							Component	ATA:72
PN:3074641-4	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:99P06857	HRS	0		TSN 0					
WC#: 72.170	ENC	0		TSN 0					
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component	ATA:72
PN:3077063-2	MOS/MSC	15-Feb-08	O/C						
SN:6P-25788	HRS	5477							
WC#: 72.180	ENC	3861							
					REF: LMM 72-50-05				
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component	ATA:72
PN:3075292-4	MOS/MSC	19-Feb-08	O/C						
SN:00P07187	HRS	6279							
WC#: 72.180	ENC	4450							
					REF: LMM 72-50-05				
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component	ATA:72
PN:3075406-8	MOS/MSC	13-Feb-02	O/C						
SN:01P25871	HRS	1367							
WC#: 72.190	ENC	1005							
					REF: GENERIC NO REF				
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE							Component	ATA:72
PN:3075406-8	MOS/MSC	13-Feb-02	O/C						
SN:99P02255	HRS	2037							
WC#: 72.190	ENC	1491							
					REF: GENERIC NO REF				
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component	ATA:72
PN:3073765-9	MOS/MSC	13-Feb-02	O/C						
SN:01P21080	HRS	1367							
WC#: 72.200	ENC	1005							
					REF: GENERIC NO REF				
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL							Component	ATA:72
PN:3073765-9	MOS/MSC	09-Dec-02	O/C						
SN:99P07570	HRS	2037.1			TSN 2037.1				
WC#: 72.200	ENC	1491			TSN 1491				
					REF: GENERIC NO REF				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component	ATA:72
PN:3074052-2	MOS/MSC	13-Feb-02	O/C						
SN:C1P25597	HRS	1367							
WC#: 72.210	ENC	1005							
REF: GENERIC NO REF									
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT							Component	ATA:72
PN:3074052-2	MOS/MSC	09-Dec-02	O/C						
SN:99P07581	HRS	2037.1		TSN 2037.1					
WC#: 72.210	ENC	1491		TSN 1491					
REF: GENERIC NO REF									
725230	NO. 1 ENGINE - FAN SPINNER							Component	ATA:72
PN:3074623-3	MOS/MSC	21-Oct-04	O/C						
SN:32784300338	HRS	3491.1							
WC#: 72.220	ENC	2531							
REF: GENERIC NO REF, LMM 72-70-01									
725230	NO. 2 ENGINE - FAN SPINNER							Component	ATA:72
PN:3074623-3	MOS/MSC	06-Dec-02	O/C						
SN:32428000067	HRS	2037.1							
WC#: 72.220	ENC	1491							
REF: GENERIC NO REF, LMM 72-70-01									
7253504 <sup>U</sup>	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE							Component	ATA:72
PN:3075406-8	MOS/MSC	13-Feb-02	O/C						
SN:01P25871	HRS	1366.8		TSN 0					
	ENC	1005		TSN 0					
7253504 <sup>U</sup>	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE							Component	ATA:72
PN:3075406-8	MOS/MSC	10-Oct-02	O/C						
SN:99P02255	HRS	2037.1							
	ENC	1491							
726110	NO. 1 ENGINE - ACCESSORY GEARBOX							Component	ATA:72
PN:3070003-29	MOS/MSC	12-Feb-02	O/C						
SN:S-1076	HRS	1367							
WC#: 72.230	ENC	1005							
REF: LMM 72-60-02									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
726110	NO. 2 ENGINE - ACCESSORY GEARBOX							Component	ATA:72
PN:3070003-29	MOS/MSC	09-Dec-02	O/C						
SN:S-1073	HRS	2037.1							
WC#: 72.230	ENC	1491							
								REF: LMM 72-60-02	
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX							Service	ATA:72
PN:3070003-29	MOS	01-Apr-14							
SN:S-1076	HRS	8478.9	5000 (+200)		(13478.9) 13739	13678.9	1651.8 (+200)		
WC#: 72.240	ENC	5744							
								REF: LMM 72-60-02	
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX							Service	ATA:72
PN:3070003-29	MOS	01-Apr-14							
SN:S-1073	HRS	9281.9	5000 (+200)		(14281.9) 13857.5	14481.9	1770.3 (+200)		
WC#: 72.240	ENC	6333							
								REF: LMM 72-60-02	
726130	NO. 1 ENGINE - TRANSFER GEARBOX							Component	ATA:72
PN:3070093-12	MOS/MSC	12-Feb-02	O/C						
SN:P-9251	HRS	1367							
WC#: 72.250	ENC	1005							
								REF: LMM 72-60-01	
726130	NO. 2 ENGINE - TRANSFER GEARBOX							Component	ATA:72
PN:3070093-12	MOS/MSC	09-Dec-02	O/C						
SN:P-9246	HRS	2037.1							
WC#: 72.250	ENC	1491							
								REF: LMM 72-60-01	
727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service	ATA:72
	MOS	21-Feb-13							
	HRS	7551.9	5000 (+200)		(12551.9) 12812	12751.9	724.8 (+200)		
WC#: 72.270	ENC	5251							
								REF: LMM 72-70-06	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY							Service	ATA:72
	MOS	21-Feb-13							
	HRS	8354.9	5000 (+200)		(13354.9) 12930.5	13554.9	843.3 (+200)		
WC#: 72.270	ENC	5840							
REF: LMM 72-70-06									
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
730001 <sup>S</sup>	DRAIN PT2 PIPELINES TO FUEL COMPUTERS							Service	ATA:73
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 73.050	AFL	7300							
REF: AFMS INSPECTION B7									
PKG:13,91									
730001 <sup>U S</sup>	NO. 1 ENGINE - INITIAL FUEL FILTER ELEMENT REMOVE & REPLACE							Component	ATA:73
PN:PN	MOS/MSC	22-Feb-11	- <sup>S</sup>	TSN 0					
SN:UNKNOWN	HRS	6974.9		TSN 0					
	ENC	4841		TSN 0					
730001 <sup>U S</sup>	NO. 2 ENGINE - INITIAL FUEL FILTER ELEMENT REMOVE & REPLACE							Component	ATA:73
PN:PN	MOS/MSC	22-Feb-11	- <sup>S</sup>	TSN 0					
SN:UNKNOWN	HRS	8580.1		TSN 0					
	ENC	6271		TSN 0					
731110	NO. 1 ENGINE - FUEL PUMP							Component	ATA:73
PN:3060710-16	MOS/MSC	12-Feb-02	O/C						
SN:395	HRS	1367							
WC#: 73.010	ENC	1005							
REF: LMM 73-20-01, LMM 73-21-02									
731110	NO. 2 ENGINE - FUEL PUMP							Component	ATA:73
PN:3060710-16	MOS/MSC	15-Mar-22	O/C	TSO 0					
SN:1142	HRS	12354.9		TSO 0					
WC#: 73.010	ENC	8092		TSO 0					
REF: LMM 73-20-01, LMM 73-21-02									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
731120 <sup>S</sup>			<b>NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT</b>					Service	ATA:73
	MOS	27-May-22							
	HRS	11763.8	300 <sup>S</sup> (+100)						
WC#: 73.010	ENC	7629							
					REF: LMM 73-21-02, LMM 73-21-02			PKG:2	
731120 <sup>S</sup>			<b>NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT</b>					Service	ATA:73
	MOS	30-Jun-22							
	HRS	12448.3	300 <sup>S</sup> (+100)						
WC#: 73.010	ENC	8155							
					REF: LMM 73-21-02, LMM 73-21-02			PKG:2	
731130			<b>NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE</b>					Component	ATA:73
PN:394396-2-1	MOS/MSC	12-Feb-02	O/C						
SN:9930	HRS	1367							
WC#: 73.030	ENC	1005							
					REF: GENERIC NO REF				
731130			<b>NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE</b>					Component	ATA:73
PN:394396-2-1	MOS/MSC	09-Dec-02	O/C						
SN:9904	HRS	2037.1							
WC#: 73.030	ENC	1491							
					REF: GENERIC NO REF				
731140			<b>NO. 1 ENGINE - FUEL HEATER</b>					Component	ATA:73
PN:158670-5	MOS/MSC	12-Feb-02	O/C						
SN:49-7534	HRS	1367							
WC#: 73.040	ENC	1005							
					REF: LMM 73-10-04				
731140			<b>NO. 2 ENGINE - FUEL HEATER</b>					Component	ATA:73
PN:158670-5	MOS/MSC	09-Dec-02	O/C						
SN:108-7448	HRS	2037.1							
WC#: 73.040	ENC	1491							
					REF: LMM 73-10-04				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
731150 <sup>S</sup>			<b>NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)</b>					Service	ATA:73
	MOS	27-Jun-22							
	HRS	11763.8	600 <sup>S</sup>						
WC#: 73.050	ENC	7629							
					REF: LMM 79-20-06			PKG:3	
731150 <sup>S</sup>			<b>NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)</b>					Service	ATA:73
	MOS	24-May-22							
	HRS	12448.3	600 <sup>S</sup>						
WC#: 73.050	ENC	8145							
					REF: LMM 79-20-06			PKG:3	
732025	<b>NO. 1 ENGINE LOW FUEL PRESSURE SWITCH</b>							Component	ATA:73
PN:690014-1	MOS/MSC	28-Jul-06	O/C						
SN:397	HRS	4029							
WC#: 73.020	AFL	2698							
732026	<b>NO. 2 ENGINE LOW FUEL PRESSURE SWITCH</b>							Component	ATA:73
PN:690014-1	MOS/MSC	28-Jul-06	O/C						
SN:20257	HRS	4029							
WC#: 73.020	AFL	2698							
732037	<b>NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH</b>							Component	ATA:73
PN:60010	MOS/MSC	29-Jun-16	O/C						
SN:1154TW	HRS	10069							
WC#: 73.025	AFL	6433							
732038	<b>NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH</b>							Component	ATA:73
PN:60010	MOS/MSC	29-Jun-16	O/C						
SN:1118TW	HRS	10069							
WC#: 73.025	AFL	6433							
732109	<b>ENGINE FUEL SYNCHRONIZER</b>							Component	ATA:73
PN:22118756-1	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:41-C0341	HRS	0		TSN 0					
WC#: 73.035	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
732110	NO. 1 ENGINE - FUEL CONTROL UNIT							Component	ATA:73
PN:3070800-35	MOS/MSC	12-Feb-02	O/C						
SN:15220	HRS	1367							
WC#: 73.070	ENC	1005							
REF: LMM 73-20-01									
732110	NO. 2 ENGINE - FUEL CONTROL UNIT							Component	ATA:73
PN:3070800-45	MOS/MSC	17-Feb-22	O/C						
SN:12796	HRS	12333							
WC#: 73.070	ENC	8078							
REF: LMM 73-20-01									
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE							Component	ATA:73
PN:3070685-6	MOS/MSC	12-Feb-02	O/C						
SN:14071	HRS	1367							
WC#: 73.080	ENC	1005							
REF: GENERIC NO REF									
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE							Component	ATA:73
PN:3070685-6	MOS/MSC	09-Dec-02	O/C						
SN:14072	HRS	2037.1							
WC#: 73.080	ENC	1491							
REF: GENERIC NO REF									
732160	NO. 1 ENGINE - FUEL FLOW TRANSMITTER							Component	ATA:73
PN:9-127-55	MOS/MSC	28-Jul-06	O/C						
SN:J9389	HRS								
WC#: 73.090	ENC								
REF: GENERIC NO REF									
732160	NO. 2 ENGINE - FUEL FLOW TRANSMITTER							Component	ATA:73
PN:9-127-55	MOS/MSC	28-Jul-06	O/C						
SN:J9340	HRS								
WC#: 73.090	ENC								
REF: GENERIC NO REF									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
733001	NO. 1 ENGINE FUEL FLOW TRANSMITTER							Component	ATA:73
PN:9-127-55	MOS/MSC	28-Jul-06	O/C						
SN:J9389	HRS	4028.9							
WC#: 73.040	AFL	2698							
733002	NO. 2 ENGINE FUEL FLOW TRANSMITTER							Component	ATA:73
PN:9-127-55	MOS/MSC	28-Jul-06	O/C						
SN:J9340	HRS	4028.9							
WC#: 73.040	AFL	2698							
733013	NO. 1 ENGINE FUEL FLOW INDICATOR							Component	ATA:73
PN:9-328-26	MOS/MSC	03-Nov-16	O/C	TSO 0					
SN:G3573	HRS	10332		TSO 0					
WC#: 73.045	AFL	6606		TSO 0					
733014	NO. 2 ENGINE FUEL FLOW INDICATOR							Component	ATA:73
PN:9-328-26	MOS/MSC	30-Nov-06	O/C	TSR 0					
SN:G3696	HRS	4271		TSR 0					
WC#: 73.045	AFL	2864		TSR 0					
<b>ATA 74 - IGNITION</b>									
741110	NO. 1 ENGINE - IGNITION UNIT							Component	ATA:74
PN:30739144	MOS/MSC	22-Aug-01	O/C	TSO 0					
SN:86348914	HRS	1079		TSO 0					
WC#: 74.010	ENC	783		TSO 0					
					REF: LMM 74-00-01				
741110	NO. 2 ENGINE - IGNITION UNIT							Component	ATA:74
PN:3073776-1	MOS/MSC	20-Feb-12	O/C						
SN:10218022857	HRS	7836							
WC#: 74.010	ENC	5536							
					REF: LMM 74-00-01				
741120 <sup>S</sup>	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service	ATA:74
	MOS	24-May-22							
	HRS	11763.8	1200 <sup>S</sup> (+200)						
WC#: 74.010	ENC	7629							
					REF: LMM 74-00-01				

PKG:4



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 74 - IGNITION</b>									
741120 <sup>S</sup>	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM							Service	ATA:74
	MOS	27-Jun-22							
	HRS	12448.3	1200 <sup>S</sup> (+200)						
WC#: 74.010	ENC	8145							
				REF: LMM 74-00-01				PKG:4	
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	10-May-06	O/C	TSN 0					
SN:UNKNOWN	HRS	4202		TSN 0					
WC#: 74.030	ENC	2982		TSN 0					
				REF: LMM 74-00-01					
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	19-Feb-08	O/C	TSN 0					
SN:NSN	HRS	6279		TSN 0					
WC#: 74.030	ENC	4450		TSN 0					
				REF: LMM 74-00-01					
742120 <sup>S</sup>	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	17-Jun-20							
	HRS	10842.9	1200 <sup>S</sup> (+200)						
WC#: 74.030	ENC	7132							
				REF: LMM 74-00-01				PKG:5	
742120 <sup>S</sup>	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	03-Dec-20							
	HRS	12041.2	1200 <sup>S</sup> (+200)						
WC#: 74.030	ENC	7917							
				REF: LMM 74-00-01				PKG:5	
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	10-May-06	O/C	TSN 0					
SN:UNKNOWN	HRS	4202		TSN 0					
WC#: 74.050	ENC	2982		TSN 0					
				REF: LMM 74-00-01					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 74 - IGNITION									
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG							Component	ATA:74
PN:3074541-4	MOS/MSC	19-Feb-08	O/C	TSN 0					
SN:NSN	HRS	6279	TSN 0						
WC#: 74.050	ENC	4450	TSN 0						
REF: LMM 74-00-01									
742140 <sup>S</sup>	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	17-Jun-20							
	HRS	10842.9	1200 <sup>S</sup> (+200)						
WC#: 74.050	ENC	7132							
REF: LMM 74-00-01									
PKG:5									
742140 <sup>S</sup>	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE							Service	ATA:74
	MOS	03-Dec-20							
	HRS	12041.2	1200 <sup>S</sup> (+200)						
WC#: 74.050	ENC	7917							
REF: LMM 74-00-01									
PKG:5									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 75 - AIR</b>									
750001 <sup>S</sup>	INSPECT THE BLEED AIR PORT LOW PRESSURE (LP) VENTURI GASKET FOR SIGNS OF DETERIORATION, DEEP DISCOLORATION, CRACKS OR MISSING PIECES OF GASKET AND REPLACE AS NECESSARY							Service	ATA:75
	MOS	03-May-21							
	HRS	11562	800 <sup>S</sup> (+40/-10)						
	AFL	7300							
							REF: AFMS INSPECTION B11	PKG:17,91	
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component	ATA:75
PN:3070816-12	MOS/MSC	13-Aug-08	O/C	TSN 0					
SN:81789319183	HRS	5659		TSN 0					
WC#: 75.010	ENC	4003		TSN 0					
							REF: LMM 75-40-01		
750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR							Component	ATA:75
PN:70060132-1	MOS/MSC	17-Dec-20	O/C	TSN 0					
SN:2016901766210	HRS	12061.5		TSN 0					
WC#: 75.010	ENC	7928		TSN 0					
							REF: LMM 75-40-01		
754010	NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH							Component	ATA:75
PN:12423	MOS/MSC	01-Dec-13	O/C						
SN:5693TW	HRS	8166							
WC#: 75.015	AFL	5408							
754011	NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH							Component	ATA:75
PN:12423	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:3003TW	HRS	0		TSN 0					
WC#: 75.015	AFL	0		TSN 0					
<b>ATA 76 - ENGINE CONTROLS</b>									
760001 <sup>S</sup>	CHECK THROTTLE LEVER CONTROLS							Service	ATA:76
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 76.030	AFL	7300							
							REF: AFMS INSPECTION B4	PKG:10,91	





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 76 - ENGINE CONTROLS</b>								
<b>760002<sup>S</sup> CHECK ENGINE POWER CONTROL CABLES Service ATA:76</b>								
	MOS	19-Feb-18						
	HRS	10726	1600 <sup>S</sup> (+50/-50)					
WC#: 76.010	AFL	6832						
REF: AFMS INSPECTION C5						PKG:23,92		
<b>760003<sup>S</sup> CHECK POWER CONTROL CABLES Service ATA:76</b>								
	MOS/MSC	25-Oct-11	O/C <sup>S</sup>					
	HRS	320.5						
WC#: 76.020	AFL	0						
<b>760004 LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING Service ATA:76</b>								
	MOS	30-Jun-22						
	HRS	12024.9	2400		14424.9		2337.7	
WC#: 76.040	AFL	7568						
REF: AFMS LUBRICATION								
<b>760004 LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING Service ATA:76</b>								
	MOS	30-Jun-22						
	HRS	12024.9	2400		14424.9		2337.7	
WC#: 76.040	AFL	7568						
REF: AFMS LUBRICATION								
<b>760110<sup>U</sup> NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL Component ATA:76</b>								
PN:2119010-8000	MOS/MSC	20-Mar-09	O/C	TSN 0				
SN:118BY1172	HRS	5967		TSN 0				
WC#: 76.010	ENC	4223		TSN 0				
REF: GENERIC NO REF								
<b>760110<sup>U</sup> NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL Component ATA:76</b>								
PN:2119010-8000	MOS/MSC	03-May-16	O/C					
SN:77-BY0896	HRS	10710.4						
WC#: 76.010	ENC	7130						
REF: GENERIC NO REF								



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 76 - ENGINE CONTROLS</b>									
760120 <sup>S</sup>	NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service	ATA:76
	MOS	27-May-22							
	HRS	11763.8	300 <sup>S</sup> (+100)						
WC#: 76.020	ENC	7629							
					REF: LMM 76-10-03, LMM 72-00-00			PKG:2	
760120 <sup>S</sup>	NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL							Service	ATA:76
	MOS	30-Jun-22							
	HRS	12448.3	300 <sup>S</sup> (+100)						
WC#: 76.020	ENC	8155							
					REF: LMM 76-10-03, LMM 72-00-00			PKG:2	
760130	NO. 1 ENGINE - DOWNLOAD ECTM							Service	ATA:76
	MOS	08-Sep-22							
	HRS	11826							
WC#: 76.050	ENC	7673	40 (+10)		(7713) 7651	7723	38 (+10)		
					REF: MSC CAMP EHM ADENDUM, LMM 76-10-03				
760130	NO. 2 ENGINE - DOWNLOAD ECTM							Service	ATA:76
	MOS	08-Sep-22							
	HRS	12511							
WC#: 76.050	ENC	8189	40 (+10)		(8229) 7651	8239	38 (+10)		
					REF: MSC CAMP EHM ADENDUM, LMM 76-10-03				
761310	NO. 1 ENGINE - SURGE BLEED VALVE							Component	ATA:76
PN:978812-5-1	MOS/MSC	12-Feb-02	O/C						
SN:9842	HRS	1367							
WC#: 76.030	ENC	1005							
					REF: LMM 76-10-01				
761310	NO. 2 ENGINE - SURGE BLEED VALVE							Component	ATA:76
PN:978812-5-1	MOS/MSC	19-Feb-08	O/C	TSR 0					
SN:4928	HRS	6279		TSR 0					
WC#: 76.030	ENC	4450		TSR 0					
					REF: LMM 76-10-01				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 76 - ENGINE CONTROLS</b>									
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:109696-4-1	MOS/MSC	12-Feb-02	O/C						
SN:9559	HRS	1366.8							
WC#: 76.040	ENC	1005							
REF: LMM 76-10-01									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE							Component	ATA:76
PN:109696-4-1	MOS/MSC	09-Dec-02	O/C						
SN:9407	HRS	2037.1							
WC#: 76.040	ENC	1491							
REF: LMM 76-10-01									
<b>ATA 77 - ENGINE INDICATING</b>									
771025	NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR							Component	ATA:77
PN:WL717RSA-5	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:AN065	HRS	0		TSN 0					
WC#: 77.010	AFL	0		TSN 0					
771026	NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR							Component	ATA:77
PN:WL717RSA-5	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:AN064	HRS	0		TSN 0					
WC#: 77.010	AFL	0		TSN 0					
771037	NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component	ATA:77
PN:WL656RSA7	MOS/MSC	20-Dec-15	O/C	TSO 4					
SN:AM770	HRS	9644.2		TSO 0					
WC#: 77.015	AFL	6206		TSO 0					
771038	NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR							Component	ATA:77
PN:WL656RSA7	MOS/MSC	25-Oct-10	O/C	TSO 0					
SN:AN033	HRS	6639.4		TSO 0					
WC#: 77.015	AFL	4467		TSO 0					
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER							Component	ATA:77
PN:3075388-2	MOS/MSC	13-Feb-02	O/C	TSN 0					
SN:11936025557	HRS	1367		TSN 0					
WC#: 77.010	ENC	1005		TSN 0					
REF: LMM 77-10-03									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 77 - ENGINE INDICATING</b>								
<b>771110 NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER</b>								Component ATA:77
PN:PN	MOS/MSC	13-May-99	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.010	ENC	0		TSN 0				
REF: LMM 77-10-03								
<b>771120 NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER</b>								Component ATA:77
PN:3070722-3	MOS/MSC	14-Aug-08	O/C	TSN 0				
SN:61936050729	HRS	5659		TSN 0				
WC#: 77.020	ENC	4003		TSN 0				
REF: LMM 77-10-05								
<b>771120 NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER</b>								Component ATA:77
PN:PN	MOS/MSC	13-May-99	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 77.020	ENC	0		TSN 0				
REF: LMM 77-10-05								
<b>771120<sup>U</sup> NO.1 ENGINE ITT THERMOCOUPLE HARNESS</b>								Component ATA:77
PN:3073605-1	MOS/MSC	15-Feb-08	O/C	TSN 0				
SN:082021900660	HRS	5476.8		TSN 0				
	AFL	3861		TSN 0				
<b>771121<sup>U</sup> NO.2 ENGINE ITT THERMOCOUPLE HARNESS</b>								Component ATA:77
PN:3073605-1	MOS/MSC	19-Feb-08	O/C	TSN 0				
SN:0802021900659	HRS	6279		TSN 0				
	AFL	4450		TSN 0				
<b>774013 NO. 1 ENGINE ITT INDICATOR</b>								Component ATA:77
PN:WL718RSA-5	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AN056	HRS	0		TSN 0				
WC#: 77.030	AFL	0		TSN 0				
<b>774014 NO. 2 ENGINE ITT INDICATOR</b>								Component ATA:77
PN:WL718RSA-5	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:AN054	HRS	0		TSN 0				
WC#: 77.030	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
780001 <sup>S</sup>	INSPECT THRUST REVERSER LINK ARM ASSEMBLIES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.110	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780002 <sup>S</sup>	INSPECT REVERSER DOOR SEALS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.120	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780003 <sup>S</sup>	TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES							Service	ATA:78
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 78.130	AFL	6832							
				REF: AFMS INSPECTION C4				PKG:22,92	
780004 <sup>S</sup>	INSPECT PYLON SKIN PANELS							Service	ATA:78
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 78.135	AFL	6832							
				REF: AFMS INSPECTION C11				PKG:29,92	
780005 <sup>S</sup>	DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS							Service	ATA:78
	MOS	19-Feb-18							
	HRS	10726	1600 <sup>S</sup> (+50/-50)						
WC#: 78.140	AFL	6832							
				REF: AFMS INSPECTION C11				PKG:29,92	
780006 <sup>S</sup>	CHECK THRUST REVERSER LEVER BAULK MECHANISM							Service	ATA:78
	MOS	19-Feb-18							
	HRS	10726	3200 <sup>S</sup> (+150/-50)						
WC#: 78.125	AFL	6832							
				REF: AFMS INSPECTION D4				PKG:34,93	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
780009 <sup>S</sup>	INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.155	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780010 <sup>S</sup>	INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.160	AFL	7300							
				REF: AFMS INSPECTION B7				PKG:13,91	
780011 <sup>S</sup>	DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.165	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780012 <sup>S</sup>	INSPECT THRUST REVERSER HYDRAULIC LINES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.170	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780013 <sup>S</sup>	INSPECT THRUST REVERSER WIRE HARNESES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.175	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	
780014 <sup>S</sup>	INSPECT THRUST REVERSER FAN DUCTS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.180	AFL	7300							
				REF: AFMS INSPECTION B11				PKG:17,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
780015 <sup>S</sup>	INSPECT THRUST REVERSER LATCH BOX SPRINGS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.185	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	
780016 <sup>S</sup>	OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.190	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	
780017 <sup>S</sup>	INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.195	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	
780018 <sup>S</sup>	INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.200	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	
780019 <sup>S</sup>	INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.205	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	
780020 <sup>S</sup>	INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS							Service	ATA:78
	MOS	03-May-21							
	HRS	11562.2	800 <sup>S</sup> (+40/-10)						
WC#: 78.210	AFL	7300							
					REF: AFMS INSPECTION B11			PKG:17,91	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 78 - EXHAUST</b>								
<b>780021<sup>S</sup> INSPECT THRUST REVERSER PYLON PLUGS</b>								
	MOS	03-May-21						Service ATA:78
	HRS	11562.2	800 <sup>S</sup> (+40/-10)					
WC#: 78.215	AFL	7300						
REF: AFMS INSPECTION B11								PKG:17,91
<b>781001 NO. 1 ENGINE THRUST REVERSER AFTERBODY</b>								
PN:5451101-79	MOS/MSC	28-Jul-06	O/C					Component ATA:78
SN:HX236-79	HRS	4029						
WC#: 78.015	AFL	2698						
<b>781002 NO. 2 ENGINE THRUST REVERSER AFTERBODY</b>								
PN:5451101-81	MOS/MSC	28-Jul-06	O/C					Component ATA:78
SN:HX244-81	HRS	4029						
WC#: 78.015	AFL	2698						
<b>781013 NO. 1 ENGINE THRUST REVERSER ASSEMBLY</b>								
PN:HS7830100-3	MOS/MSC	01-Feb-18	O/C					Component ATA:78
SN:DHC0049	HRS	10726						
WC#: 78.010	AFL	6832						
<b>781014 NO. 2 ENGINE THRUST REVERSER ASSEMBLY</b>								
PN:HS7830100-4	MOS/MSC	01-Feb-18	O/C					Component ATA:78
SN:DHC0049	HRS	10726						
WC#: 78.011	AFL	6832						
<b>781026 NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR</b>								
PN:PN	MOS/MSC	19-Jul-01	O/C					Component ATA:78
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.020	AFL	0		TSN 0				
<b>781027 NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR</b>								
PN:5453512-20	MOS/MSC	10-Nov-10	O/C					Component ATA:78
SN:1405	HRS	6680.3						
WC#: 78.020	AFL	4495						





# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
<b>781028</b>	<b>NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR</b>							<b>Component</b>	<b>ATA:78</b>
PN:5453512-19	MOS/MSC	18-Jan-08	O/C						
SN:1791	HRS	5223.7							
WC#: 78.025	AFL	3495							
<b>781029</b>	<b>NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR</b>							<b>Component</b>	<b>ATA:78</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.025	AFL	0		TSN 0					
<b>781053</b>	<b>NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:PN-UNKNOWN	MOS/MSC	18-Jan-08	O/C						
SN:UNKNOWN	HRS	5224							
WC#: 78.030	AFL	3495							
<b>781054</b>	<b>NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.030	AFL	0		TSN 0					
<b>781055</b>	<b>NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:5453512-19	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:1791	HRS	0		TSN 0					
WC#: 78.035	AFL	0		TSN 0					
<b>781056</b>	<b>NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:PN	MOS/MSC	19-Jul-01	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 78.035	AFL	0		TSN 0					
<b>781117</b>	<b>NO. 1 ENGINE RETARD THROTTLE ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:5453305-3	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:HX3-6-02	HRS	0		TSN 0					
WC#: 78.050	AFL	0		TSN 0					
<b>781118</b>	<b>NO. 2 ENGINE RETARD THROTTLE ASSEMBLY</b>							<b>Component</b>	<b>ATA:78</b>
PN:5453303-3	MOS/MSC	27-Jul-09	O/C	TSO 0					
SN:DHC1034	HRS	6022		TSO 0					
WC#: 78.050	AFL	4065		TSO 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 78 - EXHAUST</b>								
<b>781129 THRUST REVERSER TIME DELAY RELAY</b> Component ATA:78								
PN:5400619-1	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:HX7-110-05	HRS	0		TSN 0				
WC#: 78.055	AFL	0		TSN 0				
<b>781130 CONTROL RELAY BOX</b> Component ATA:78								
PN:AI-STR-01A	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:50100134	HRS	0		TSN 0				
WC#: 78.060	AFL	0		TSN 0				
<b>781136 AUXILIARY RELAY BOX</b> Component ATA:78								
PN:5400612-1	MOS/MSC	23-Jul-12	O/C					
SN:HX339-102	HRS	7319.1						
WC#: 78.065	AFL	4893						
<b>781142 NO. 1 ENGINE THRUST REVERSER CONTROL VALVE</b> Component ATA:78								
PN:64135141-3	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:A30040574	HRS	0		TSN 0				
WC#: 78.070	AFL	0		TSN 0				
<b>781143 NO. 2 ENGINE THRUST REVERSER CONTROL VALVE</b> Component ATA:78								
PN:64135141-3	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:A30040567	HRS	0		TSN 0				
WC#: 78.070	AFL	0		TSN 0				
<b>781155 THRUST REVERSER ACCUMULATOR</b> Component ATA:78								
PN:DS259-3	MOS/MSC	19-Jul-01	O/C	TSN 0				
SN:60209-0236	HRS	0		TSN 0				
WC#: 78.075	AFL	0		TSN 0				
<b>781156 HYDRAULIC RELIEF VALVE</b> Component ATA:78								
PN:MS28893D6	MOS/MSC	19-Jul-01	O/C					
SN:62696	HRS	0		TSN 0				
WC#: 78.080	AFL	0		TSN 0				
<b>781161 THRUST REVERSER CONTROL PANEL</b> Component ATA:78								
PN:PN	MOS/MSC	19-Jul-01	O/C					
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 78.085	AFL	0		TSN 0				



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
781167	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH							Component	ATA:78
PN:2365-15	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:2793	HRS	0		TSN 0					
WC#: 78.090	AFL	0		TSN 0					
781169	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH							Component	ATA:78
PN:2365-15	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:2804	HRS	0		TSN 0					
WC#: 78.090	AFL	0		TSN 0					
781173	THRUST REVERSER PRESSURE GAUGE							Component	ATA:78
PN:MS28041T7	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:94908	HRS	0		TSN 0					
WC#: 78.090	AFL	0		TSN 0					
783008	NO. 1 ENGINE LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-9	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:TECAV0220	HRS	0		TSN 0					
WC#: 78.095	AFL	0		TSN 0					
783009	NO. 2 ENGINE LOWER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-10	MOS/MSC	12-Dec-10	O/C	TSR 0					
SN:TECAV0152	HRS	6708.4		TSR 0					
WC#: 78.095	AFL	4517		TSR 0					
783011	NO. 2 ENGINE UPPER THRUST REVERSER DOOR							Component	ATA:78
PN:HS7832000-7	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:TECAV0454	HRS	0		TSN 0					
WC#: 78.100	AFL	0		TSN 0					
<b>ATA 79 - OIL</b>									
790001 <sup>U S</sup>	NO. 1 ENGINE - ENGINE BASELINE OIL SAMPLE							Service	ATA:79
	MOS/MSC	28-Mar-16	- <sup>S</sup>						
	HRS	9815.5							
	ENC	6494							



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
790001 <sup>U S</sup>			NO. 2 ENGINE - ENGINE BASELINE OIL SAMPLE					Service	ATA:79
	MOS/MSC	06-Feb-16							
	HRS	10468.3							
	ENC	7008							
790111 <sup>S</sup>			NO. 1 ENGINE - ANALYZE OIL AND FILTER					Service	ATA:79
	MOS	27-Jun-22							
	HRS	11763.8	150 <sup>S</sup> (+100)						
WC#: 79.010	ENC	7629							
					REF: LMM 72-00-00			PKG:1	
790111 <sup>S</sup>			NO. 2 ENGINE - ANALYZE OIL AND FILTER					Service	ATA:79
	MOS	22-Jul-22							
	HRS	12461.4	150 <sup>S</sup> (+100)						
WC#: 79.010	ENC	8155							
					REF: LMM 72-00-00			PKG:1	
790120			NO. 1 ENGINE - CHANGE OIL					Service	ATA:79
	MOS	17-Jun-20							
	HRS	10842.9	1200 (+100)		(12042.9) 12303	12142.9	215.8 (+100)		
WC#: 79.020	ENC	7132							
					REF: LMM 72-00-00				
790120			NO. 2 ENGINE - CHANGE OIL					Service	ATA:79
	MOS	17-Jun-20							
	HRS	11645.9	1200 (+100)		(12845.9) 12421.5	12945.9	334.3 (+100)		
WC#: 79.020	ENC	7721							
					REF: LMM 72-00-00				
790130 <sup>S</sup>			NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR					Service	ATA:79
	MOS	27-Jun-22							
	HRS	11763.8	150 <sup>S</sup> (+100)						
WC#: 79.030	ENC	7629							
					REF: LMM 79-20-03			PKG:1	



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
790130 <sup>S</sup>	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR							Service	ATA:79
	MOS	22-Jul-22							
	HRS	12461.4	150 <sup>S</sup> (+100)						
WC#: 79.030	ENC	8155							
				REF: LMM 79-20-03				PKG:1	
792110	NO. 1 ENGINE - OIL PUMP							Component	ATA:79
PN:3060785-2	MOS/MSC	21-Oct-04	O/C	TSN 0					
SN:41405700581	HRS	3491.1		TSN 0					
WC#: 79.040	ENC	2531		TSN 0					
				REF: LMM 79-20-03					
792110	NO. 2 ENGINE - OIL PUMP							Component	ATA:79
PN:3071949-12	MOS/MSC	25-Oct-07	O/C	TSR 0					
SN:7065	HRS	6055		TSR 0					
WC#: 79.040	ENC	4296		TSR 0					
				REF: LMM 79-20-03					
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component	ATA:79
PN:PN	MOS/MSC	20-May-99	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 79.060	ENC	0		TSN 0					
				REF: LMM 79-20-02					
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY							Component	ATA:79
PN:3075323-3	MOS/MSC	20-Jun-06	O/C	TSO 0					
SN:1-08145-01262C	HRS	5087		TSO 0					
WC#: 79.060	ENC	3602		TSO 0					
				REF: LMM 79-20-02					
792140	NO. 1 ENGINE - UPPER OIL COOLER							Component	ATA:79
PN:158600-7	MOS/MSC	12-Feb-02	O/C						
SN:19-11908	HRS	1366.8							
WC#: 79.070	ENC	1005							
				REF: LMM 79-20-09					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 79 - OIL</b>									
792140	NO. 2 ENGINE - UPPER OIL COOLER							Component	ATA:79
PN:158600-7	MOS/MSC	09-Dec-02	O/C						
SN:19-11956	HRS	2037.1							
WC#: 79.070	ENC	1491							
REF: LMM 79-20-09									
792144	NO. 1 ENGINE OIL LOW PRESSURE SWITCH							Component	ATA:79
PN:690012	MOS/MSC	28-Jul-06	O/C						
SN:20202	HRS	4029							
WC#: 79.030	AFL	2698							
792145	NO. 2 ENGINE OIL LOW PRESSURE SWITCH							Component	ATA:79
PN:690012	MOS/MSC	28-Jul-06	O/C						
SN:20231	HRS	4029							
WC#: 79.030	AFL	2698							
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER							Component	ATA:79
PN:159900-3	MOS/MSC	12-Feb-02	O/C						
SN:19-9420	HRS	1366.8							
WC#: 79.080	ENC	1005							
REF: LMM 79-20-09									
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER							Component	ATA:79
PN:159910-3	MOS/MSC	09-Dec-02	O/C						
SN:100-8223	HRS	2037.1							
WC#: 79.080	ENC	1491							
REF: LMM 79-20-09									
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER							Component	ATA:79
PN:159910-3	MOS/MSC	12-Feb-02	O/C						
SN:19-8231	HRS	1366.8							
WC#: 79.090	ENC	1005							
REF: LMM 79-20-09									
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER							Component	ATA:79
PN:159900-3	MOS/MSC	09-Dec-02	O/C						
SN:19-9403	HRS	2037.1							
WC#: 79.090	ENC	1491							
REF: LMM 79-20-09									



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 79 - OIL</b>									
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR							Component	ATA:79
PN:158610-8	MOS/MSC	12-Feb-02	O/C						
SN:19-9696	HRS	1367							
WC#: 79.100	ENC	1005							
REF: LMM 79-20-07									
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR							Component	ATA:79
PN:158610-8	MOS/MSC	09-Dec-02	O/C						
SN:19-9710	HRS	2037.1							
WC#: 79.100	ENC	1491							
REF: LMM 79-20-07									
793001	NO. 1 ENGINE OIL PRESSURE TRANSMITTER							Component	ATA:79
PN:APT-20PCRT1-1000-706	MOS/MSC	28-Jul-06	O/C						
SN:6372-7-110	HRS	4029							
WC#: 79.040	AFL	2698							
793002	NO. 2 ENGINE OIL PRESSURE TRANSMITTER							Component	ATA:79
PN:APT-20PCRT-1000-70G	MOS/MSC	10-Mar-21	O/C						
SN:8237-3-196	HRS	11424							
WC#: 79.040	AFL	7228							
793037	NO. 1 ENGINE OIL PRESSURE INDICATOR							Component	ATA:79
PN:2121-01-0014	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:82432	HRS	0		TSN 0					
WC#: 79.045	AFL	0		TSN 0					
793038	NO. 2 ENGINE OIL PRESSURE INDICATOR							Component	ATA:79
PN:2121-01-0014	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:82427	HRS	0		TSN 0					
WC#: 79.045	AFL	0		TSN 0					
793049	NO. 1 ENGINE OIL TEMPERATURE INDICATOR							Component	ATA:79
PN:2121-01-0013	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:82460	HRS	0		TSN 0					
WC#: 79.050	AFL	0		TSN 0					



# Status Report

Model: HAWKER 800XP Serial: 258545 RegNo: N312FU HRS: 12087.2 AFL: 7613 As Of: 12-Sep-2022

Report Date: 13-Sep-2022

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 79 - OIL									
793050	NO. 2 ENGINE OIL TEMPERATURE INDICATOR							Component	ATA:79
PN:2121-01-0013	MOS/MSC	19-Jul-01	O/C	TSN 0					
SN:82432	HRS	0	TSN 0						
WC#: 79.050	AFL	0	TSN 0						
793110	NO. 1 ENGINE - OIL PRESSURE TRANSMITTER							Component	ATA:79
PN:APT-20PCRRRT1-1000-706	MOS/MSC	28-Jun-06	O/C						
SN:6372-7-110	HRS	4029							
	ENC	2698							
REF: GENERIC NO REF									
793110	NO. 2 ENGINE - OIL PRESSURE TRANSMITTER							Component	ATA:79
PN:APT-20PCRT-1000-70G	MOS/MSC	10-Mar-21	O/C						
SN:8237-3-196	HRS	11424							
	ENC	7228							
REF: GENERIC NO REF									