

DueList Report

HAWKER 850XP

S/N 258792 N900WT

OWNER: HABERAIR, LLC
 ADDRESS: 1417 SADLER ROAD #358
 FERNANDINA BEACH FL 32034
 OFFICE: 904-432-7604
 FAX:

OPERATOR: SKYWAYS CHARTER LLC
 ADDRESS: 3700 AIRPORT RD
 BOCA RATON FL 33431
 OFFICE: 561-237-5607
 FAX: 561-208-5514

ANALYST: GLEN WATSON
 EMAIL: GWATSON@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
 316-462-2442 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PROJECTED: 24 MOS. to 03-OCT-2025

AIRCRAFT	SERIAL/REGNO: 258792/N900WT	MODEL: HAWKER 850XP	MANUFACTURER: TEXTRON AVIATION INC.
----------	-----------------------------	---------------------	-------------------------------------

CERTIFICATION DATE: 12-JUL-2006

LAST ACTUALS:	PROJECTED:
5510.4 A/C HRS	6510.40
2784 AFL	3284
5046 APH	5546
as of 30-SEP-2023	
as of 30-SEP-2023	
as of 30-SEP-2023	

APU	SERIAL/PART: P-917/3800304-1	MODEL: GTCP36-150(W)	MANUFACTURER: HONEYWELL
-----	------------------------------	----------------------	-------------------------

INSTALLED ON: 28-DEC-2020

4391 APU HRS	5046 APU HRS	PROJECTED: 5546
0 APUS	0 APUS	0
4735.05 A/C HRS	as of 30-SEP-2023	
	as of 30-NOV-2022	

ENGINE NO. 1	SERIAL/PART: P-129233/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
--------------	---------------------------------	----------------------	-------------------------

INSTALLED ON: 12-JUL-2006

0 ENG. HRS	5510.4 ENG. HRS	PROJECTED: 6510.40
0 ENC	2784 ENC	3284
0 A/C HRS	as of 30-SEP-2023	
	as of 30-SEP-2023	

ENGINE NO. 2	SERIAL/PART: P-129238/3075160-4	MODEL: TFE731-5BR-1H	MANUFACTURER: HONEYWELL
--------------	---------------------------------	----------------------	-------------------------

INSTALLED ON: 12-JUL-2006

0 ENG. HRS	5510.4 ENG. HRS	PROJECTED: 6510.40
0 ENC	2784 ENC	3284
0 A/C HRS	as of 30-SEP-2023	
	as of 30-SEP-2023	



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
050500		INSPECTION E1-E12 COMPLETE						Package ATA:05	
	MOS	12 (+1m/-1m)		26-Sep-22	26-Sep-23	26-Oct-23	TOL (+23 d)	03-Oct-2023(3)	
	HRS			5170.5					
	AFL			2567					
		REF:							WO#: N900WT-231003-2
530019		DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE						Service ATA:53	
	MOS	12 (+1m)		10-Oct-22	10-Oct-23	10-Nov-23	7 d (+31)	10-Oct-2023(2)	
	HRS			5170.5					
	AFL			2567					
		REF: AFMS STRUCTURAL INSPECTIONS							WO#: N900WT-231003-2
120001		LUBRICATE AREA G-200 HOURS						Service ATA:12	
	MOS			13-May-23				17-Oct-2023(5)	
	HRS	200 (+40/-10)		5330.7	5530.7	5570.7	20.3 (+40)		
	AFL			2669					
		REF: AFMS LUBRICATION							WO#: N900WT-231003-2
057140		NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION						Package ATA:05	
	MOS			28-Dec-20				21-Oct-2023(2)	
	HRS	800 (+50)		4735.1	(5535.1)5535.1	5585.1	24.7 (+50)		
	ENC			2241					
		REF: LMM 72-00-00							WO#: N900WT-231003-2
057140		NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION						Package ATA:05	
	MOS			28-Dec-20				21-Oct-2023(2)	
	HRS	800 (+50)		4735.1	(5535.1)5535.1	5585.1	24.7 (+50)		
	ENC			2241					
		REF: LMM 72-00-00							WO#: N900WT-231003-2
490001		INSPECT PATS APU GTCP36-150W						Service ATA:49	
	MOS	12 (+1m)		21-Oct-22	21-Oct-23	21-Nov-23	18 d (+31)	21-Oct-2023(2)	
	HRS			5170.5					
	AFL			2567					
	APH	750		4784	5534		488		
		REF: AFMS OUT OF PHASE INSPECTIONS							WO#: N900WT-231003-2
490003		ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK						Service ATA:49	
	MOS	12 (+1m)		21-Oct-22	21-Oct-23	21-Nov-23	18 d (+31)	21-Oct-2023(2)	
	HRS			5170.5					
	AFL			2567					
	APH	750		4784	5534		488		
		REF: AFMS OUT OF PHASE INSPECTIONS							WO#: N900WT-231003-2

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
499020		APU - INSPECT MAGNETIC DRAIN PLUG						Service ATA:49
	MOS	12 (+1m/-1m)		21-Oct-22	21-Oct-23	21-Nov-23	18 d (+31)	21-Oct-2023(2)
	HRS	750		4784	5534		488	
	APUS							
		REF: MM 49-90-46						WO#: N900WT-231003-2
499040		APU - REMOVE AND REPLACE OIL FILTER ELEMENT						Service ATA:49
	MOS	12		25-Oct-22	25-Oct-23		22 d	25-Oct-2023(2)
	HRS	750		4784	5534		488	
	APUS							
		REF: MM 49-90-47						WO#: N900WT-231003-2
34R050 ^U		UPDATE FMS DATABASE						Service ATA:34
	DAYS	DUE		29-Sep-23	01-Nov-23 (M)		29 d	01-Nov-2023
	HRS			5510.4				
	AFL			2784				
		REF:						
243155		CAPACITY CHECK NO. 2 BATTERY						Service ATA:24
PN:RG-390E	MOS	6 (+1m/-1m)		13-May-23	13-Nov-23	13-Dec-23	41 d (+30)	13-Nov-2023(4)
SN:41055757	HRS			5330.7				
	AFL			2669				
		REF: AMM 24-30-151						
570029		VISUALLY INSPECT WING OUTER, UPPER AND LOWER SKINS						Service ATA:57
	MOS			21-Mar-23				21-Nov-2023(4)
	HRS	300 (+10%)	Adj:-23.4	5301.8	5578.4	5608.4	68 (+30)	
	AFL			2653				
		REF: AFMS OUT OF PHASE INSPECTIONS						
262201		REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)						Service ATA:26
PN:A1003(1)	MOS	36		03-Dec-20	03-Dec-23		61 d	03-Dec-2023
SN:N/A	HRS							
	AFL							
Disposition: LIFE LIMIT		REF: AMM 26-20-41						
262202		REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)						Service ATA:26
PN:A1003(1)	MOS	36		03-Dec-20	03-Dec-23		61 d	03-Dec-2023
SN:N/A	HRS							
	AFL							
Disposition: LIFE LIMIT		REF: AMM 26-20-41						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
760130		NO. 1 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			19-Sep-23				09-Dec-2023(10)
	HRS			5504.2				
	ENC	50		2780	(2830)2830		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						
760130		NO. 2 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			19-Sep-23				09-Dec-2023(10)
	HRS			5504.2				
	ENC	50		2780	(2830)2830		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						
080005 ^U		WEIGH AIRCRAFT AND UPDATE FLIGHT MANUAL W&B INFO						Service ATA:08
	MOS	36		28-Dec-20	28-Dec-23		86 d	28-Dec-2023
	HRS			4735.1				
	AFL			2241				
		REF:						
240030		FUNCTION TEST CABIN INVERTER (115 VAC) SYSTEM (IF INSTALLED)						Service ATA:24
	DAYS			01-Aug-23				06-Jan-2024(5)
	HRS	200 (+10%/-10%)	Adj:-1.9	5443.6	5641.7	5661.7	131.3 (+20)	
	AFL			2739				
		REF: MMA 24-20-00, MMA 24-20-05, MMA 24-20-10, AFMS OUT OF PHASE INSPECTIONS						
057110		NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			01-Aug-23				08-Jan-2024(5)
	HRS	200 (+50)		5443.6	(5643.6)5643.6	5693.6	133.2 (+50)	
	ENC			2739				
		REF: LMM 72-00-00						
057110		NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			01-Aug-23				08-Jan-2024(5)
	HRS	200 (+50)		5443.6	(5643.6)5643.6	5693.6	133.2 (+50)	
	ENC			2739				
		REF: LMM 72-00-00						
243154		CAPACITY CHECK NO. 1 BATTERY						Service ATA:24
PN:RG-390E	MOS	6 (+30d/-30d)		01-Aug-23	01-Feb-24	02-Mar-24	121 d (+30)	01-Feb-2024(4)
SN:41193595	HRS			5443.6				
	AFL			2739				
		REF: AMM 24-30-151						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
260008		FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)						Service	ATA:26
	MOS	6 (+10%)		01-Aug-23	01-Feb-24	18-Feb-24	121 d (+17)	01-Feb-2024(4)	
	HRS			5443.6					
	AFL			2739					
REF: MMA 26-11-00, AFMS OUT OF PHASE INSPECTIONS									
313068		REPLACE FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY						Service	ATA:31
	MOS	DUE		22-Feb-18	01-Feb-24 (M)		121 d	01-Feb-2024	
	HRS			4191.3					
	AFL			1855					
REF:									
240024		INSPECT/CHECK APU STARTER/GENERATOR						Service	ATA:24
PN:23080-064	MOS			27-Oct-21				15-Feb-2024	
SN:Y30091	HRS			5011.3					
	AFL			2448					
	APH	500		4639	5139		93		
REF: AMM 24-30-21, AFMS OUT OF PHASE INSPECTIONS									
490002		REMOVE/CLEAN/INSPECT APU IGNITER PLUG						Service	ATA:49
	MOS			07-Dec-20				18-Feb-2024	
	HRS								
	AFL								
	APH	750		4391	5141		95		
REF: AFMS OUT OF PHASE INSPECTIONS									
494030		APU - REMOVE AND INSPECT IGNITER PLUG						Service	ATA:49
PN:3888002-2	MOS			07-Dec-20				18-Feb-2024	
SN:UNKNOWN	HRS	750		4391	5141		95		
	APUS								
REF: MM 49-40-33									
25R007 ^U		LIFE RAFT ELT REGISTRATION						Service	ATA:25
	MOS	24		19-Feb-22	19-Feb-24		139 d	19-Feb-2024	
	HRS			5106.9					
	AFL			2528					
REF:									
351031		PILOT OXYGEN MASK						Component	ATA:35
PN:MF10-03-02	MOS	72	TSN:0	22-Feb-18	22-Feb-24		142 d	22-Feb-2024	
SN:92777	HRS		TSN:0	4191.3					
	AFL		TSN:0	1855					
Disposition: OVERHAUL REF:									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
243002		NO. 2 ENGINE STARTER/GENERATOR							Component ATA:24
PN:23080-064	MOS		TSO:34	21-Jun-23				15-Mar-2024	
SN:96216	HRS	1000	TSO:663.7	5398.8	5735.1		224.7		
	AFL		TSO:465	2706					
Disposition: OVERHAUL		REF: AMM 24-30-21							
057170		NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS			21-Feb-17				19-Apr-2024	
	HRS	1600 (+50)		4183.7	(5783.7)5783.7	5833.7	273.3 (+50)		
	ENC			1853					
		REF: LMM 72-00-00							
057170		NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION							Package ATA:05
	MOS			21-Feb-17				19-Apr-2024	
	HRS	1600 (+50)		4183.7	(5783.7)5783.7	5833.7	273.3 (+50)		
	ENC			1853					
		REF: LMM 72-00-00							
050110		INSPECTION B1-B12 COMPLETE							Package ATA:05
	MOS			22-Oct-21				09-May-2024	
	HRS	800 (+40/-10)		5011.3	5811.3	5851.3	300.9 (+40)		
	AFL			2448					
		REF:							
050771		INSPECTION 400 HOUR DETAILED WALK-AROUND							Service ATA:05
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+40/-10)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AMM 400HR, MMA 400 HR, AFMS 400 HR DETAILED WALK-AROUND							
120003		LUBRICATE AREA F1-400 HOURS							Service ATA:12
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+40/-10)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AFMS LUBRICATION							
120004		LUBRICATE AREA T1-400 HOURS							Service ATA:12
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+40/-10)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AFMS LUBRICATION							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
120007		LUBRICATE AREA W1/W2-400 HOURS							Service ATA:12
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+40/-10)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AMM 28-10-44, AFMS LUBRICATION							
210006		INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION							Service ATA:21
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+10%)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AMM 21-10-95, AFMS OUT OF PHASE INSPECTIONS							
210007		INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS							Service ATA:21
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+10%)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AMM 21-10-95, AFMS OUT OF PHASE INSPECTIONS							
240028		VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M							Service ATA:24
	MOS			01-Aug-23				09-May-2024(2)	
	HRS	400 (+10%)	Adj:-32.3	5443.6	5811.3	5851.3	300.9 (+40)		
	AFL			2739					
		REF: AMM 24-01-00, AFMS OUT OF PHASE INSPECTIONS							
240001		INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR							Service ATA:24
PN:23080-064	MOS			05-Jul-23				16-May-2024(2)	
SN:95103	HRS	400 (+10%)		5421.3	5821.3	5861.3	310.9 (+40)		
	AFL			2723					
		REF: AMM 24-30-21, AFMS OUT OF PHASE INSPECTIONS							
050240		INSPECTION C1-C12 COMPLETE							Package ATA:05
	MOS			03-Nov-18				18-May-2024	
	HRS	1600 (+50/-50)		4223.5	5823.5	5873.5	313.1 (+50)		
	AFL			1872					
		REF:							
000100 ^U		AIRCRAFT REGISTRATION RENEWAL							Service ATA:00
	MOS	DUE		21-Jan-21	31-May-24 (M)		241 d	31-May-2024	
	HRS			4760.15					
	AFL			2254					
		REF:							



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
057120		NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION						Package	ATA:05
	MOS			01-Aug-23				02-Jun-2024(2)	
	HRS	400		5443.6	(5843.6)5843.6		333.2		
	ENC			2739					
REF: LMM 72-00-00									
057120		NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION						Package	ATA:05
	MOS			01-Aug-23				02-Jun-2024(2)	
	HRS	400		5443.6	(5843.6)5843.6		333.2		
	ENC			2739					
REF: LMM 72-00-00									
240001		INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR						Service	ATA:24
PN:23080-064	MOS			01-Aug-23				02-Jun-2024(2)	
SN:96216	HRS	400 (+10%)		5443.6	5843.6	5883.6	333.2 (+40)		
	AFL			2739					
REF: AMM 24-30-21, AFMS OUT OF PHASE INSPECTIONS									
56A002 ^U		VISUAL INSPECTION OF THE RIGHT DIRECT VIEW A WINDOW IAW LAI-ICA-118						Service	ATA:56
	MOS			01-Aug-23				02-Jun-2024(2)	
	HRS	400 (+50/-50)		5443.6	5843.6	5893.6	333.2 (+50)		
	AFL			2739					
REF:									
336040		ESCAPE HATCH BETALIGHT "EXIT" SIGN						Component	ATA:33
PN:132848-11	MOS	72 (+24m)		03-Nov-18	01-Jul-24	01-Jul-26	272 d (+730)	01-Jul-2024	
SN:36675	HRS		TSN:0	4223.5					
	AFL		TSN:0	1872					
Disposition: REPLACE		REF: AMM 33-50-05							
351050		CREW CABINET OXYGEN MASK						Component	ATA:35
PN:174290-41	MOS	72	TSN:4	03-Nov-18	03-Jul-24		274 d	03-Jul-2024	
SN:UNKNOWN	HRS		TSN:0	4223.5					
	AFL		TSN:0	1872					
Disposition: OVERHAUL		REF: GENERIC CMM							
324223		LEFT OUTBOARD MAXARET						Component	ATA:32
PN:AC65218	MOS		TSN:0	12-Jul-06				13-Aug-2024	
SN:60DT	HRS		TSN:0	0					
	AFL	3000	TSN:0	0	3000		216		
Disposition: OVERHAUL		REF: AMM 32-40-101							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
324224		RIGHT OUTBOARD MAXARET						Component	ATA:32
PN:AC65216	MOS		TSN:0	12-Jul-06				13-Aug-2024	
SN:53ED	HRS		TSN:0	0					
	AFL	3000	TSN:0	0	3000		216		
Disposition: OVERHAUL		REF: AMM 32-40-101							
324225		LEFT INBOARD MAXARET						Component	ATA:32
PN:AC65216	MOS		TSN:0	12-Jul-06				13-Aug-2024	
SN:72EE	HRS		TSN:0	0					
	AFL	3000	TSN:0	0	3000		216		
Disposition: OVERHAUL		REF: AMM 32-40-101							
324226		RIGHT INBOARD MAXARET						Component	ATA:32
PN:AC65218	MOS		TSN:0	12-Jul-06				13-Aug-2024	
SN:21DY	HRS		TSN:0	0					
	AFL	3000	TSN:0	0	3000		216		
Disposition: OVERHAUL		REF: AMM 32-40-101							
276039		LEFT AIRBRAKE JACK ASSEMBLY						Component	ATA:27
PN:AIR46520-2	MOS		TSO:0	04-Jul-13				18-Aug-2024	
SN:APB990578	HRS	3000	TSO:0	2949.57	5949.57		439.2		
	AFL		TSO:0	1320					
Disposition: OVERHAUL		REF: AMM 27-61-31							
276040		RIGHT AIRBRAKE JACK ASSEMBLY						Component	ATA:27
PN:AIR46521-2	MOS		TSO:0	04-Jul-13				18-Aug-2024	
SN:LK8603561	HRS	3000	TSO:0	2949.57	5949.57		439.2		
	AFL		TSO:0	1320					
Disposition: OVERHAUL		REF: AMM 27-61-31							
262199		REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:A1003(1)	MOS	48		01-Sep-20	01-Sep-24		334 d	01-Sep-2024	
SN:N/A	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 26-20-41							
262200		REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)						Service	ATA:26
PN:A1003(1)	MOS	48		01-Sep-20	01-Sep-24		334 d	01-Sep-2024	
SN:N/A	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 26-20-41							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
243156		ENERGY LEVEL TEST NO. 3 BATTERY							Service ATA:24
PN:100-0540-04	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:2199	HRS			5504.2					
	AFL			2780					
REF: AMM 24-30-155									
243157		ENERGY LEVEL TEST NO. 4 BATTERY							Service ATA:24
PN:100-0540-04	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:1139179	HRS			5504.2					
	AFL			2780					
REF: AMM 24-30-155									
243158		ENERGY LEVEL TEST NO. 5 BATTERY							Service ATA:24
PN:100-0540-04	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:0809404	HRS			5504.2					
	AFL			2780					
REF: AMM 24-30-155									
243159		ENERGY LEVEL TEST NO. 6 BATTERY							Service ATA:24
PN:100-0540-04	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:0811503	HRS			5504.2					
	AFL			2780					
REF: AMM 24-30-155									
243160		ENERGY LEVEL TEST NO. 7 BATTERY							Service ATA:24
PN:100-0540-04	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:1990	HRS			5504.2					
	AFL			2780					
REF:									
256005		INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT)							Service ATA:25
PN:453-5000-999	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:210-04044	HRS			5504.2					
	AFL			2780					
REF:									
256010		FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT)							Service ATA:25
PN:453-5000-999	MOS	12		19-Sep-23	19-Sep-24		352 d	19-Sep-2024(2)	
SN:210-04044	HRS			5504.2					
	AFL			2780					
REF: AMM 25-61-15, AMM 25-60-05, MMA 25-61-05, MMA 25-61-10, MMA 25-61-15									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
510005		INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19						Service ATA:51
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-107, NTM 53-10-108, NTM 53-10-108B, NTM 53-10-109						
510006		DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14						Service ATA:51
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS						
510007		INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17						Service ATA:51
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-106A						
510008		X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16						Service ATA:51
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-108A						
510010		INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR						Service ATA:51
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS, NTM 53-10-104, NTM 53-10-101, NTM 53-10-102, NTM 53-10-103A, NTM 53-10-106						
520009		DETAIL INSPECT ESCAPE HATCH						Service ATA:52
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS						
530003		DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).						Service ATA:53
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024
	HRS			8.8				
	AFL			6				
		REF: AFMS STRUCTURAL INSPECTIONS						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
530004		DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)						Service	ATA:53
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024	
	HRS			8.8					
	AFL			6					
REF: AMM 28-10-15, AFMS STRUCTURAL INSPECTIONS									
550010		INSPECT/NDT VERTICAL STABILIZER						Service	ATA:55
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024	
	HRS			8.8					
	AFL			6					
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-30-101, NTM 55-30-102, NTM 55-30-103									
550013		X-RAY HORIZONTAL STABILIZER						Service	ATA:55
	MOS	T:180 (+3m)	Adj:36	21-Sep-06	21-Sep-24	21-Dec-24	354 d (+91)	21-Sep-2024	
	HRS			8.8					
	AFL			6					
REF: AFMS STRUCTURAL INSPECTIONS, NTM 55-10-101, NTM 55-10-102, NTM 55-10-103, NTM 55-10-105									
243091		GROUND SUPPLY START (E) CONTACTOR						Component	ATA:24
PN:140-380021-0001	MOS		TSN:0	12-Jul-06				24-Sep-2024	
SN:CP-13116	HRS	6000	TSN:0	0	6000		489.6		
	AFL		TSN:0	0					
Disposition: OVERHAUL REF:									
550015		INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS						Service	ATA:55
	MOS	24 (+2m)		06-Oct-22	06-Oct-24	06-Dec-24	369 d (+61)	06-Oct-2024	
	HRS			5170.5					
	AFL			2567					
REF: AMM 27-30-91, AFMS STRUCTURAL INSPECTIONS									
237015		TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON						Service	ATA:23
	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
	HRS								
	AFL								
REF: AMM 25-60-110, AMM 23-70-36, AMM 23-70-37, MMA 23-70-35									
237016		CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON						Service	ATA:23
	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
	HRS			5170.5					
	AFL			2567					
REF: AMM 25-60-110, AMM 23-70-36, AMM 23-70-37, MMA 23-70-35									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
340002		DRAIN PITOT/STATIC DRAIN TRAPS						Service	ATA:34
	MOS	24 (+2m)		10-Oct-22	10-Oct-24	10-Dec-24	373 d (+61)	10-Oct-2024	
	HRS			5170.5					
	AFL			2567					
REF: AMM 34-11-19, AFMS OUT OF PHASE INSPECTIONS									
340006		PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS						Service	ATA:34
	MOS	24 (+2m)		10-Oct-22	10-Oct-24	10-Dec-24	373 d (+61)	10-Oct-2024	
	HRS			5170.5					
	AFL			2567					
REF: AMM 34-11-19, AFMS OUT OF PHASE INSPECTIONS									
340007		CHECK PITOT SYSTEM ISOLATION VALVES						Service	ATA:34
	MOS	24 (+2m)		10-Oct-22	10-Oct-24	10-Dec-24	373 d (+61)	10-Oct-2024	
	HRS			5170.5					
	AFL			2567					
REF: AFMS OUT OF PHASE INSPECTIONS									
341238		TEST AIR DATA ESIS UNIT (FAA 91.411)						Service	ATA:34
PN:27101-01-01	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
SN:M008514	HRS								
	AFL								
Disposition: MANDATORY			REF: FAR FAR PART 91						
341240		TEST NO.1 AIR DATA COMPUTER (FAA 91.411)						Service	ATA:34
PN:822-1109-015	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
SN:2NJ8N	HRS								
	AFL								
Disposition: MANDATORY			REF: AMM 34-10-19, FAR FAR PART 91						
341241		TEST NO.2 AIR DATA COMPUTER (FAA 91.411)						Service	ATA:34
PN:822-1109-015	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
SN:2FLCG	HRS								
	AFL								
Disposition: MANDATORY			REF: AMM 34-10-19, FAR FAR PART 91						
345229		SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413)						Service	ATA:34
PN:622-9210-501	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
SN:34HHW	HRS								
	AFL								
Disposition: MANDATORY			REF: FAR FAR PART 91						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
345230		SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413)						Service	ATA:34
PN:622-9210-501	MOS	24		10-Oct-22	10-Oct-24		373 d	10-Oct-2024	
SN:1686	HRS								
	AFL								
Disposition: MANDATORY		REF: FAR FAR PART 91							
340012		SWING CHECK NO. 1 COMPASS						Service	ATA:34
	MOS	36 (+2m)		22-Oct-21	22-Oct-24	22-Dec-24	385 d (+61)	22-Oct-2024	
	HRS			5011.3					
	AFL			2448					
		REF: AMM 34-20-05, AMM 34-09-112, AFMS OUT OF PHASE INSPECTIONS							
340012		SWING CHECK NO. 2 COMPASS						Service	ATA:34
	MOS	36 (+2m)		22-Oct-21	22-Oct-24	22-Dec-24	385 d (+61)	22-Oct-2024	
	HRS			5011.3					
	AFL			2448					
		REF: AMM 34-20-05, AMM 34-09-112, AFMS OUT OF PHASE INSPECTIONS							
340012		SWING CHECK STANDBY COMPASS						Service	ATA:34
	MOS	36 (+2m)		22-Oct-21	22-Oct-24	22-Dec-24	385 d (+61)	22-Oct-2024	
	HRS			5011.3					
	AFL			2448					
		REF: AMM 34-20-05, AMM 34-09-112, AFMS OUT OF PHASE INSPECTIONS							
050630		INSPECTION F1-F12 COMPLETE						Package	ATA:05
	MOS	24 (+2m/-2m)	Adj:34d	04-Oct-22	07-Nov-24	07-Jan-25	401 d (+61)	07-Nov-2024	
	HRS			5170.5					
	AFL			2567					
		REF:							
34R005 ^U		RVSM HEIGHT MONITORING						Service	ATA:34
	MOS			13-Dec-21				02-Dec-2024	
	HRS	1000		5095	6095		584.6		
	AFL			2522					
		REF:							
441014 ^U		DUNCAN HIGH SPEED INTERNET W/ WIRELESS LAN – VISUAL INSP COMPONENT, CABLES & ANTENNA						Service	ATA:44
	MOS	24		20-Dec-22	20-Dec-24		444 d	20-Dec-2024	
	HRS			5191.2					
	AFL			2577					
		REF:							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
FAA 1974-08-09 R03		LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION						AD ATA:25
	MOS			07-Oct-22				26-Jan-2025
	HRS	1000		5170.5	6170.5		660.1	
	AFL			2567				
Disposition: MANDATORY			REF: AD					
26R104 ^U		COCKPIT PORTABLE FIRE EXTINGUISHER MID-HYDRO MAINTENANCE						Service ATA:26
PN:C354TS	MOS	72	Adj:-14	12-Mar-20	31-Jan-25 (M)		486 d	31-Jan-2025
SN:60593127	HRS			4608.2				
	AFL			2143				
			REF:					
243115		APU STARTER/GENERATOR						Component ATA:24
PN:23080-064	MOS		TSO:23	28-Dec-20				17-Feb-2025
SN:Y30091	HRS		TSO:0	4735.1				
	AFL		TSO:0	2241				
	APH	1000	TSO:0	4391	5391		345	
Disposition: OVERHAUL			REF: AMM 24-30-21, MMA 49-16-00					
490004		REMOVE AND REPLACE APU FUEL FILTER ELEMENT						Service ATA:49
	MOS			28-Dec-20				17-Feb-2025
	HRS			4735.1				
	AFL			2241				
	APH	1000		4391	5391		345	
			REF: AFMS OUT OF PHASE INSPECTIONS					
493020		APU - REMOVE AND REPLACE FUEL FILTER ELEMENT						Service ATA:49
	MOS			28-Dec-20				17-Feb-2025
	HRS	1000		4391	5391		345	
	APUS							
			REF: MM 49-30-52					
33R800 ^U		INSPECT LOPRESTI BOOM BEAM LANDING / TAXI LIGHTS (IN ACCORDANCE WITH INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT ICA LSM-500-042)						Service ATA:33
	MOS	24 (+2m)		24-Feb-23	24-Feb-25	24-Apr-25	510 d (+59)	24-Feb-2025
	HRS	1800 (+50)		5241.7	7041.7	7091.7	1531.3 (+50)	
	AFL			2614				
			REF:					
334013		LEFT WING STROBE LIGHT						Component ATA:33
PN:01-0770935-02	MOS		TSN:0	03-Nov-18				06-Mar-2025
SN:UNKNOWN	HRS	1500	TSN:0	4223.5	6223.5 (M)		713.1	
	AFL		TSN:0	1872				
Disposition: REPLACE			REF: AMM 33-40-12					

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
334014		RIGHT WING STROBE LIGHT						Component	ATA:33
PN:01-0770935-02	MOS		TSN:0	03-Nov-18				06-Mar-2025	
SN:UNKNOWN	HRS	1500	TSN:0	4223.5	6223.5 (M)		713.1		
	AFL		TSN:0	1872					
Disposition: REPLACE		REF: AMM 33-40-12							
262139		HYDROSTATIC TEST APU FIRE EXTINGUISHER						Service	ATA:26
PN:4190-1	MOS	60		10-Mar-20	10-Mar-25		524 d	10-Mar-2025	
SN:789	HRS								
	AFL								
		REF:							
720002		INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT						Service	ATA:72
	MOS			09-Dec-16				11-Mar-2025	
	HRS	2100 (+10%)	Adj:-53.37	4183.7	6230.33	6440.33	719.9 (+210)		
	AFL								
Disposition: PART OF MPI		REF: AFMS OUT OF PHASE INSPECTIONS							
720002		INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT						Service	ATA:72
	MOS			21-Feb-17				11-Mar-2025	
	HRS	2100 (+10%)	Adj:-53.37	4183.7	6230.33	6440.33	719.9 (+210)		
	AFL			1853					
Disposition: PART OF MPI		REF: AFMS OUT OF PHASE INSPECTIONS							
720003		DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP						Service	ATA:72
	MOS			09-Dec-16				11-Mar-2025	
	HRS	2100 (+10%)	Adj:-53.37	4183.7	6230.33	6440.33	719.9 (+210)		
	AFL								
Disposition: PART OF MPI		REF: AFMS OUT OF PHASE INSPECTIONS							
720003		DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP						Service	ATA:72
	MOS			21-Feb-17				11-Mar-2025	
	HRS	2100 (+10%)	Adj:-53.37	4183.7	6230.33	6440.33	719.9 (+210)		
	AFL			1853					
Disposition: PART OF MPI		REF: AFMS OUT OF PHASE INSPECTIONS							
720120		NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)						Service	ATA:72
	MOS			21-Feb-17				11-Mar-2025	
	HRS	2100 (+100)	Adj:-53.37	4183.7	(6230.33)6230.33	6330.33	719.9 (+100)		
	ENC			1853					
		REF: LMM 72-00-00							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
720120		NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)						Service ATA:72
	MOS			21-Feb-17				11-Mar-2025
	HRS	2100 (+100)	Adj:-53.37	4183.7	(6230.33)6230.33	6330.33	719.9 (+100)	
	ENC			1853				
REF: LMM 72-00-00								
SB TFE731-72-3806 R01		NO. 1 ENGINE - REDUCTION GEAR AND SHAFT SECTION - INSTALL REWORKED QUILL SHAFT ASSEMBLY, PN 3075535-3, WITH IMPROVED STRAIGHT PIN INSTALLATION ON TFE731-5B ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:MPI		EFF				11-Mar-2025
	HRS				(6230.33)6230.33 *		719.9	
	ENC				(M)			
Disposition: CATEGORY 2 REF: BULLETINS								
SB TFE731-72-3806 R01		NO. 2 ENGINE - REDUCTION GEAR AND SHAFT SECTION - INSTALL REWORKED QUILL SHAFT ASSEMBLY, PN 3075535-3, WITH IMPROVED STRAIGHT PIN INSTALLATION ON TFE731-5B ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:MPI		EFF				11-Mar-2025
	HRS				(6230.33)6230.33 *		719.9	
	ENC				(M)			
Disposition: CATEGORY 2 REF: BULLETINS								
SB TFE731-73-3157 R01		NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:73
	MOS	T:DUE		EFF				11-Mar-2025
	HRS				(6230.33)6230.33 *		719.9	
	ENC				(M)			
Disposition: CATEGORY 2 REF: BULLETINS								
SB TFE731-73-3157 R01		NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, OR -74, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-2, -3, -4, AND -5 ENGINE MODELS, SERVICE BULLETIN						Bulletin ATA:73
	MOS	T:DUE		EFF				11-Mar-2025
	HRS				(6230.33)6230.33 *		719.9	
	ENC				(M)			
Disposition: CATEGORY 2 REF: BULLETINS								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
SB TFE731-79-3070 R02		NO. 1 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-3, -4, -5 MODEL ENGINES, SERVICE BULLETIN						
	MOS	T:DUE		EFF				Bulletin ATA:79
	HRS				(6230.33)6230.33 *		719.9	11-Mar-2025
	ENC				(M)			
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-79-3070 R02		NO. 2 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-3, -4, -5 MODEL ENGINES, SERVICE BULLETIN						
	MOS	T:DUE		EFF				Bulletin ATA:79
	HRS				(6230.33)6230.33 *		719.9	11-Mar-2025
	ENC				(M)			
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-79-3077		NO. 1 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-2, -3, AND -5 MODEL ENGINES, SERVICE BULLETIN						
	MOS	T:DUE		EFF				Bulletin ATA:79
	HRS				(6230.33)6230.33 *		719.9	11-Mar-2025
	ENC				(M)			
Disposition: CATEGORY 2		REF: BULLETINS						
SB TFE731-79-3077		NO. 2 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-2, -3, AND -5 MODEL ENGINES, SERVICE BULLETIN						
	MOS	T:DUE		EFF				Bulletin ATA:79
	HRS				(6230.33)6230.33 *		719.9	11-Mar-2025
	ENC				(M)			
Disposition: CATEGORY 2		REF: BULLETINS						
724120		NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE						
PN:3075749-5	MOS			21-Feb-17				Service ATA:72
SN:06P08741	HRS	2100 (+500)		4183.7	(6283.7)6283.7	6783.7	773.3 (+500)	19-Apr-2025
	ENC			1853				
		REF: LMM 72-40-04						
724120		NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE						
PN:3075749-5	MOS			21-Feb-17				Service ATA:72
SN:04P18334	HRS	2100 (+500)		4183.7	(6283.7)6283.7	6783.7	773.3 (+500)	19-Apr-2025
	ENC			1853				
		REF: LMM 72-40-04						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: HAWKER 850XP Serial: 258792 RegNo: N900WT HRS: 5510.4 AFL: 2784
As Of: 30-Sep-2023 Operator: SKYWAYS CHARTER LLC

Report Date: 03-Oct-2023

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
760004		LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service ATA:76
	MOS			20-Feb-17				19-Apr-2025	
	HRS	2100		4183.7	6283.7		773.3		
	AFL			1853					
REF: AFMS LUBRICATION									
760004		LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING							Service ATA:76
	MOS			20-Feb-17				19-Apr-2025	
	HRS	2100		4183.7	6283.7		773.3		
	AFL			1853					
REF: AFMS LUBRICATION									
353031		(PBE) PROTECTIVE BREATHING EQUIPMENT							Component ATA:35
PN:802300-14	MOS	120		30-Jun-16	30-Apr-25		575 d	30-Apr-2025	
SN:E15040228	HRS			4065.53					
	AFL			1795					
Disposition: LIFE LIMIT		REF: GENERIC NO REF							
243001		NO. 1 ENGINE STARTER/GENERATOR							Component ATA:24
PN:23080-064	MOS		TSO:0	05-Jul-23				28-Jul-2025	
SN:95103	HRS	1000	TSO:0	5421.3	6421.3		910.9		
	AFL		TSO:0	2723					
Disposition: OVERHAUL		REF: AMM 24-30-21							
334044		TAIL STROBE LIGHT							Component ATA:33
PN:31-1840-1	MOS		TSN:0	17-Sep-21				18-Sep-2025	
SN:N/A	HRS	1500	TSN:0	4991.4	6491.4		981		
	AFL		TSN:0	2431					
Disposition: REPLACE		REF: AMM 33-40-12							